


|   |                       |   |   |
|---|-----------------------|---|---|
|  <p><b>TITANIUM ENVIRONMENTAL SERVICES, LLC</b><br/>         PO Box 4029 Longview, Texas 75606<br/>         Phone (903) 234-8443 Fax (903) 234-1641<br/>         www.titaniumenvironmental.com</p> | CLIENT                | PROJECT DESCRIPTION   | FIGURE 1  |
|   | Burk Royalty Co., Ltd | Release Report<br>Cruces No. 6<br>API 025-02462<br>Lea County, New Mexico | <b>Site Location</b><br><small>Date created: 03.26.2014<br/>Revised by: J. Van Dyke</small> |

JUN 10 2014



**Notes**  
"Waste Composite" is a 5-part composite collected within the given boundary.  
"Surface Composite A" is a 5-part composite collected within the "Release Perimeter", excluding the "Waste Composite Perimeter".



HOBBS OCD

MAR 27 2014

RECEIVED

**Approximate Scale**  
1" = 25'

|  | CLIENT                | PROJECT DESCRIPTION   | FIGURE 2   |
|--|-----------------------|---|--|
|  <p><b>TITANIUM ENVIRONMENTAL SERVICES, LLC</b><br/>PO Box 4029 Longview, Texas 75606<br/>Phone (903) 234-8443 Fax (903) 234-1641<br/>www.titaniumenvironmental.com</p> | Burk Royalty Co., Ltd | Release Report<br>Cruces No. 6<br>API 025-02462<br>Lea County, New Mexico | <b>Sampling Locations</b><br><small>Date created: 03.26.2014<br/>Revised by: J. Van Dyke</small> |

BURK ROYALTY CO., LTD  
CRUCES #6- API 025-02462  
SITE PHOTOS  
February 18, 2014

HOBBS OCD

MAR 27 2014

RECEIVED




Photo 1.: View of the Cruces # 6 pump-jack taken from release location, approximately 80-feet south of the pump-jack.





Photo 2.: View of release location displaying the excavated soil in the background and the excavated area in the foreground.

BURK ROYALTY CO., LTD  
CRUCES #6- API 025-02462  
SITE PHOTOS  
February 18, 2014



HOBBS OCD

MAR 27 2014

RECEIVED

Photo 3.: View facing southwest, showing the main extent of the release.




Photo 4.: View facing south, photo showing one of the two surface stains remaining at the time of sampling at the eastern boundary of the release.

BURK ROYALTY CO., LTD  
CRUCES #6- API 025-02462  
SITE PHOTOS  
February 18, 2014

HOBBS OCD

MAR 27 2014

RECEIVED



Photo 5.: View of the main footprint of the release from the western side of the release area facing east. Darker soil in the far right and middle of the photo displays the other surface stain at the sample location "Cruces 1".



Photo 6.: View facing east at the most western extent of the excavation and the release.