R. T. HICKS CONSULTANTS, LTD.

901 Rio Grande Blvd NW ▲ Suite F-142 ▲ Albuquerque, NM 87104 ▲ 505.266.5004 ▲ Fax: 505.266-0745

June 2, 2014

Mr. Mike Bratcher NMOCD District 2 811 S. First Street Artesia, New Mexico 88210 Via Email and US Mail

DENIEC

NM OIL CONSERVATION ARTESIA DISTRICT JUN 0 6 2014

RECEIVED


RE: Murchison - Hackberry State #1 Release C-141 form

Dear Mr. Bratcher:

On behalf of Murchison Oil and Gas, R.T Hicks Consultants submits the attached initial C-141 form for the above-referenced release. Between 3:00 pm on May 19 and 4:00 pm on May 20, the nipple on a fiberglass, open-topped tank failed, releasing approximately 155 barrels of produced water onto the location. The photograph below was taken at the time of discovery on May 20, facing west toward the tank. On May 21 during a meeting in the field with you, Chace Walls of Murchison notified you of this release.

The nipple on the tank was replaced. The stained surface was scraped and blended on site with dry material from the facility pad and spread on the location to dry the impacted material and reduce the potential of downward moisture migration and surface migration off site.

As shown on Figure 1, data from the Office of the State Engineer demonstrate that depth to groundwater exceeds 100 feet and the distance to mapped surface water bodies is nearly ½ mile. The nearest known water well is more than 1 mile distant. Our understanding of how regulated constituents migrate from the source



through the environment allow us to conclude that the residual salt on the location pose no threat to fresh water, public health, or the environment. However, a high salt concentration fixed in the underlying soil can create a problem for re-vegetation of the site after plugging and abandonment. Therefore, characterization and remediation of affected subsoils will be

conducted upon closure of the facility in accordance with applicable NMOCD Rules and, if required, Murchison will take measures to ensure that the abandoned site's surface will be reclaimed in a manner fully consistent with applicable Rules.

Please contact me with any questions regarding this submission. Thank you.

Sincerely,


R.T. Hicks Consultants

Knistin Tope

Kristin Pope

Copy: Murchison Oil & Gas, State Land Office

Enclosures as stated



* /

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Erg naia D

Popul

Form C-141 Revised August 8, 2011

.

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

District IV 1220 S. St. France	cis Dr., Santa	Fe, NM 87505				Fe, NM 875							
		•••	Dale	ase Notific				otion					
			Refe	ease nounca	1110			cuor			<u> </u>		
										al Report		nal Report	
Name of CompanyMurchison Oil & Gas, Inc.Address1100 Mira Vista Blvd, Plano, TX 75093						ContactGreg BoansTelephone No.(575) 628-3932							
Facility Name Hackberry State #1						Facility Type Production Battery							
Surface Owner State of New Mexico Mineral Owner													
Surface Ow	ner	API No. 30-015-34803											
						N OF RE							
Unit Letter	Section	Township	Range	Feet from the	North	h/South Line	Feet from the	East/V	West Line	County	County		
0	17	18S	23E	660		South	1980		East		Eddy		
Latitude 32° 44' 32.2" N Longitude 104° 42' 39.8" W													
NATURE OF RELEASE Type of Release Produced Water Volume of Release 155 bbls Volume Recovered 0 bbls													
Type of Release Produced Water Source of Release							rr Volume of Release 155 bbls Volume Recovered 0 bbls Date and Hour of Occurrence Date and Hour of Discovery						
Open-top fiberglass tank													
Was Immedia	ate Notice C		v	No 🗌 Not Red		If YES, To Whom?							
	100-	-											
By Whom? Chace Walls Was a Watercourse Reached?							s Date and Hour 5/21/2014 4:15 pm If YES, Volume Impacting the Watercourse.						
Yes X No													
If a Watercourse was Impacted, Describe Fully.*						ARTESIA DISTRICT							
n/a JUN 0 6 2014													
n/a										JUNU	b 2014		
Describe Cau	ise of Probl	em and Reme	dial Actio	n Taken.*						DEOF			
RECEIVED													
Fluid was lost due to a failure of the nipple on the backside of a 200-bbl open-top fiberglass tank. A vacuum truck was dispatched to the location but no standing fluid remained at the time of its arrival. The nipple on the tank was replaced.													
		0				ine mppre o		opiaco					
Describe Are	a Affected	and Cleanup A	Action Tal	ken.*									
Produced w	ater leaked	d out of the t	ank and c	onto the location,	affe	cting approxi	mately 4.000 so	uare fe	et. all of w	hich was c	ontained	on the	
				the impacted cal									
				public health, or t									
of affected subsoils will be conducted upon closure of the facility in accordance with applicable NMOCD Rules and, if required, the abandoned site's surface will be reclaimed in a manner fully consistent with applicable Rules.													
abandoneu	sile s suita	ice will be le	cianneu	in a manner funy	COIR	sistem with a	pplicable Rules.						
				is true and comple									
				nd/or file certain re									
				ce of a C-141 repor investigate and re									
or the enviror	nment. In a	ddition, NMC	CD accep	otance of a C-141 r									
federal, state,	or local lay	ws and/or regu	lations.					arns.		DIVICI			
							OIL CONSERVATION DIVISION						
Signature:	15	Y 12			<u>-</u>								
Printed Name: Greg Boans						Approved by Environmental Specialist:							
Title:			Proc	luction Superintend	lent	Approval Date: Expiration			Date:				
E-mail Addre	ess:			gboans@jdmii.c	om	Conditions o	f Approval:		Attached				
Date: 6/2/20	14	Pho	ne: (575) 628-3932							_		
Attach Addi				<u>,</u>	1					I			