HOBBS OCD State of New Mexico

Energy Minerals and Natural Resources

TIL 30 2014 Conservation Division 1220 South St. Francis Dr.

Revised August 8, 2011 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

20 S. St. Francis Dr., Santa Fe, NM 87505 RECEIVED: Santa	Fe, NM 87505	·····
Release Notificati	on and Corrective Action	on
	OPERATOR	🛛 Initial Report 🗌 Final Repo
lame of Company: ConocoPhillips	Contact: Spencer Cluff	
Address: 29 Vacuum Complex Lane	Telephone No. 575-391-3143	
Cacility Name: MCA Battery 4	Facility Type: Battery	
urface Owner: BLM Mineral Owner	r NMOCD	API No. 3002512709
LOCATI	ON OF RELEASE	
Init Letter Section Township Range Feet from the No		st/West Line County
A 26 17S 32E 660 No	th 660 Eas	st LEA
Latitude 32.8076533080148 Longitude - 103.426925251861		
	E OF RELEASE	
ype of Release: Spill	Volume of Release: 17.5 BBLS	Volume Recovered: 8 BBLS
ource of Release: water Line	Date and Hour of Occurrence 7/30/2014 4:00 a.m.	Date and Hour of Discovery 7/30/2014 4:00 a.m.
Vas Immediate Notice Given?	If YES, To Whom?	
🛛 Yes 🔲 No 🗍 Not Requir		Hughes
y Whom? Spencer Cluff	Date and Hour: 07/30/2014 10:30 a.m.	
Vas a Watercourse Reached?	If YES, Volume Impacting the W	Vatercourse.
🗌 Yes 🛛 No		
a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* On elease of 17.5 bbls occurred. A water hauler called MSC The heater treater water line on production heater had pro- and blocked in the line to stop the leak. MSO had shut in to of water pumps being down over night. Spill length is 6	and notified him of a leak that ssured up and started to leak. all the wells earlier in that night	was happening at MCA Battery 4. MSO went down to MCA battery 4 to prevent tank from overflowing due
elease of 17.5 bbls occurred. A water hauler called MSC the heater treater water line on production heater had pro- nd blocked in the line to stop the leak. MSO had shut in o of water pumps being down over night. Spill length is 6 eleased and 8 bbls recovered. A work order has been su IMOCD and COPC guidelines. escribe Area Affected and Cleanup Action Taken.* MSO had shut in all the wells earlier in that night to preve- ight. A work order has been submitted to repair the line. uidelines. hereby certify that the information given above is true and complete egulations all operators are required to report and/or file certain release ublic health or the environment. The acceptance of a C-141 report by hould their operations have failed to adequately investigate and remean r the environment. In addition, NMOCD acceptance of a C-141 report	and notified him of a leak that essured up and started to leak. all the wells earlier in that night 3 ft. X 150 ft. X about 2 inches ibmitted to repair the line. The nt tank from overflowing due to The area will be remediated ac o the best of my knowledge and under e notifications and perform corrective the NMOCD marked as "Final Repor iate contamination that pose a threat to	was happening at MCA Battery 4. MSO went down to MCA battery 4 to prevent tank from overflowing due deep. The spill resulted in 17.5 bbls area will be remediated according to of water pumps being down over ccording to NMOCD and COPC stand that pursuant to NMOCD rules and actions for releases which may endanger t" does not relieve the operator of liability o ground water, surface water, human health
elease of 17.5 bbls occurred. A water hauler called MSC The heater treater water line on production heater had pro	and notified him of a leak that essured up and started to leak. all the wells earlier in that night 3 ft. X 150 ft. X about 2 inches ibmitted to repair the line. The nt tank from overflowing due to The area will be remediated ac o the best of my knowledge and under e notifications and perform corrective the NMOCD marked as "Final Repor iate contamination that pose a threat to t does not relieve the operator of respon	was happening at MCA Battery 4. MSO went down to MCA battery 4 to prevent tank from overflowing due deep. The spill resulted in 17.5 bbls area will be remediated according to of water pumps being down over ccording to NMOCD and COPC stand that pursuant to NMOCD rules and actions for releases which may endanger t" does not relieve the operator of liability o ground water, surface water, human health onsibility for compliance with any other
elease of 17.5 bbls occurred. A water hauler called MSC The heater treater water line on production heater had pro- ind blocked in the line to stop the leak. MSO had shut in o of water pumps being down over night. Spill length is 6 eleased and 8 bbls recovered. A work order has been su IMOCD and COPC guidelines. Describe Area Affected and Cleanup Action Taken.* MSO had shut in all the wells earlier in that night to preve- ight. A work order has been submitted to repair the line. uidelines. hereby certify that the information given above is true and complete egulations all operators are required to report and/or file certain releas ublic health or the environment. The acceptance of a C-141 report by hould their operations have failed to adequately investigate and remeer r the environment. In addition, NMOCD acceptance of a C-141 report ederal, state, or local laws and/or regulations.	and notified him of a leak that essured up and started to leak. all the wells earlier in that night 3 ft. X 150 ft. X about 2 inches ibmitted to repair the line. The nt tank from overflowing due to The area will be remediated ac o the best of my knowledge and under e notifications and perform corrective the NMOCD marked as "Final Repor iate contamination that pose a threat to t does not relieve the operator of respon	was happening at MCA Battery 4. MSO went down to MCA battery 4 to prevent tank from overflowing due deep. The spill resulted in 17.5 bbls area will be remediated according to of water pumps being down over ccording to NMOCD and COPC stand that pursuant to NMOCD rules and actions for releases which may endanger t" does not relieve the operator of liability o ground water, surface water, human health
elease of 17.5 bbls occurred. A water hauler called MSC The heater treater water line on production heater had pro- and blocked in the line to stop the leak. MSO had shut in o of water pumps being down over night. Spill length is 6 eleased and 8 bbls recovered. A work order has been su IMOCD and COPC guidelines. Tescribe Area Affected and Cleanup Action Taken.* MSO had shut in all the wells earlier in that night to preve- ight. A work order has been submitted to repair the line. uidelines. hereby certify that the information given above is true and complete egulations all operators are required to report and/or file certain release ublic health or the environment. The acceptance of a C-141 report by hould their operations have failed to adequately investigate and remean r the environment. In addition, NMOCD acceptance of a C-141 report	and notified him of a leak that essured up and started to leak. all the wells earlier in that night 3 ft. X 150 ft. X about 2 inches ibmitted to repair the line. The nt tank from overflowing due to The area will be remediated ac o the best of my knowledge and under e notifications and perform corrective the NMOCD marked as "Final Repor iate contamination that pose a threat to t does not relieve the operator of respon	was happening at MCA Battery 4. MSO went down to MCA battery 4 to prevent tank from overflowing due deep. The spill resulted in 17.5 bbls area will be remediated according to of water pumps being down over ccording to NMOCD and COPC stand that pursuant to NMOCD rules and actions for releases which may endanger t" does not relieve the operator of liability o ground water, surface water, human health onsibility for compliance with any other RVATION DIVISION
elease of 17.5 bbls occurred. A water hauler called MSC The heater treater water line on production heater had pro- ind blocked in the line to stop the leak. MSO had shut in o of water pumps being down over night. Spill length is 6 eleased and 8 bbls recovered. A work order has been su IMOCD and COPC guidelines. Describe Area Affected and Cleanup Action Taken.* MSO had shut in all the wells earlier in that night to preve- ight. A work order has been submitted to repair the line. uidelines. hereby certify that the information given above is true and complete egulations all operators are required to report and/or file certain releas ublic health or the environment. The acceptance of a C-141 report by hould their operations have failed to adequately investigate and remeer r the environment. In addition, NMOCD acceptance of a C-141 report ederal, state, or local laws and/or regulations.	and notified him of a leak that essured up and started to leak. all the wells earlier in that night 3 ft. X 150 ft. X about 2 inches ibmitted to repair the line. The nt tank from overflowing due to The area will be remediated ac o the best of my knowledge and under e notifications and perform corrective the NMOCD marked as "Final Repor iate contamination that pose a threat to t does not relieve the operator of respon	was happening at MCA Battery 4. MSO went down to MCA battery 4 to prevent tank from overflowing due deep. The spill resulted in 17.5 bbls area will be remediated according to of water pumps being down over ccording to NMOCD and COPC stand that pursuant to NMOCD rules and actions for releases which may endanger t" does not relieve the operator of liability o ground water, surface water, human health onsibility for compliance with any other RVATION DIVISION
elease of 17.5 bbls occurred. A water hauler called MSC the heater treater water line on production heater had pro- ind blocked in the line to stop the leak. MSO had shut in o of water pumps being down over night. Spill length is 6 eleased and 8 bbls recovered. A work order has been su IMOCD and COPC guidelines. Describe Area Affected and Cleanup Action Taken.* MSO had shut in all the wells earlier in that night to prever ight. A work order has been submitted to repair the line. uidelines. hereby certify that the information given above is true and complete egulations all operators are required to report and/or file certain releas ublic health or the environment. The acceptance of a C-141 report by hould their operations have failed to adequately investigate and remed r the environment. In addition, NMOCD acceptance of a C-141 report bederal, state, or local laws and/or regulations.	and notified him of a leak that essured up and started to leak. all the wells earlier in that night 3 ft. X 150 ft. X about 2 inches ibmitted to repair the line. The nt tank from overflowing due to The area will be remediated ac o the best of my knowledge and under e notifications and perform corrective the NMOCD marked as "Final Repor iate contamination that pose a threat to t does not relieve the operator of respon	was happening at MCA Battery 4. MSO went down to MCA battery 4 to prevent tank from overflowing due deep. The spill resulted in 17.5 bbls area will be remediated according to of water pumps being down over ccording to NMOCD and COPC stand that pursuant to NMOCD rules and actions for releases which may endanger t" does not relieve the operator of liability o ground water, surface water, human health onsibility for compliance with any other EVATION DIVISION alist:
elease of 17.5 bbls occurred. A water hauler called MSC The heater treater water line on production heater had pro- ind blocked in the line to stop the leak. MSO had shut in o of water pumps being down over night. Spill length is 6 eleased and 8 bbls recovered. A work order has been su IMOCD and COPC guidelines. Describe Area Affected and Cleanup Action Taken.* MSO had shut in all the wells earlier in that night to preve- ight. A work order has been submitted to repair the line. uidelines. hereby certify that the information given above is true and complete egulations all operators are required to report and/or file certain release ubic health or the environment. The acceptance of a C-141 report by hould their operations have failed to adequately investigate and remed r the environment. In addition, NMOCD acceptance of a C-141 report ederal, state, or local laws and/or regulations.	and notified him of a leak that essured up and started to leak. all the wells earlier in that night 3 ft. X 150 ft. X about 2 inches ibmitted to repair the line. The nt tank from overflowing due to The area will be remediated ac o the best of my knowledge and under e notifications and perform corrective the NMOCD marked as "Final Repor iate contamination that pose a threat to t does not relieve the operator of respondent Approved by Environmental Special Approval Date: 7-30-19 Conditions of Approval:	was happening at MCA Battery 4. MSO went down to MCA battery 4 to prevent tank from overflowing due deep. The spill resulted in 17.5 bbls area will be remediated according to of water pumps being down over ccording to NMOCD and COPC stand that pursuant to NMOCD rules and actions for releases which may endanger t" does not relieve the operator of liability o ground water, surface water, human health onsibility for compliance with any other EVATION DIVISION alist: Expiration Date: 10-3-19
elease of 17.5 bbls occurred. A water hauler called MSC The heater treater water line on production heater had pro- ind blocked in the line to stop the leak. MSO had shut in o of water pumps being down over night. Spill length is 6 eleased and 8 bbls recovered. A work order has been su IMOCD and COPC guidelines. Describe Area Affected and Cleanup Action Taken.* MSO had shut in all the wells earlier in that night to preve- ight. A work order has been submitted to repair the line. uidelines. hereby certify that the information given above is true and complete egulations all operators are required to report and/or file certain release ublic health or the environment. The acceptance of a C-141 report by hould their operations have failed to adequately investigate and remed r the environment. In addition, NMOCD acceptance of a C-141 report ederal, state, or local laws and/or regulations.	and notified him of a leak that essured up and started to leak. all the wells earlier in that night 3 ft. X 150 ft. X about 2 inches ibmitted to repair the line. The nt tank from overflowing due to The area will be remediated ac o the best of my knowledge and under e notifications and perform corrective the NMOCD marked as "Final Repor iate contamination that pose a threat to t does not relieve the operator of respon- Approved by Environmental Special Approval Date: 7-30-19	was happening at MCA Battery 4. MSO went down to MCA battery 4 to prevent tank from overflowing due deep. The spill resulted in 17.5 bbls area will be remediated according to of water pumps being down over ccording to NMOCD and COPC stand that pursuant to NMOCD rules and actions for releases which may endanger t" does not relieve the operator of liability o ground water, surface water, human health onsibility for compliance with any other EVATION DIVISION alist: Expiration Date: /0-3-/4