

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

State of New Mexico  
Energy Minerals and Natural Resources  
AUG 20 2014  
Oil Conservation Division  
1220 South St. Francis Dr.  
RECEIVED Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	CHEVRON U.S.A Inc.	Contact	David Pagano
Address	56 Texas Camp Road, Lovington, NM 88260	Telephone No.	Office: 575-396-4414 ext 275 Cellular: 505-787-9816
Facility Name	Vacuum Glorietta West Unit #40	Facility Type	Injection Well
Surface Owner	State of New Mexico	Mineral Owner	State of New Mexico
		API No.	3002531701

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	25	17.0S	34.0E					Lea

Latitude 32.80314785 Longitude -103.5148256

### NATURE OF RELEASE

Type of Release	Produced Water Spill	Volume of Release	7.8bbl of Produced Water	Volume Recovered	0 bbls
Source of Release	Water Injection Station Pump	Date and Hour of Occurrence	03/25/12 07:00	Date and Hour of Discovery	03/25/12 07:30
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mr. Leking via voicemail		
By Whom?	David Pagano	Date and Hour	03/26/12 09:36		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Corrosion on Steel water injection line caused a Produced Water spill of 7.8 bbls. The leak was at a carbon steel fitting. Well was shut in and injection line will be repaired.

Describe Area Affected and Cleanup Action Taken.\*

On discovery vacuum truck contacted and vacuumed up the standing fluids which were sent to disposal. Next steps are for the visually contaminated soil to be excavated up to 2 feet and sent off for disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: David Pagano	Approved by Environmental Specialist: 	
Title: Health & Environmental Specialist	Approval Date: 8-20-14	Expiration Date: 10-22-14
E-mail Address: david.pagano@chevron.com	Conditions of Approval: Side Sample required Submit Lab C-141 by 10-22-14	Attached <input type="checkbox"/> IRP-3259 08-21-14 9323
Date: 03/26/12 Phone: 505-787-9816		

\* Attach Additional Sheets If Necessary

AUG 21 2014 1701423253315  
P701423253431