NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

SEP 2 2 2014

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in **RECEIMED** tance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

			Rele	ease Notific	cation	and Co	rrective A	ction					
NAB14	41021	945				OPERA:	TOR		🛚 Initi	al Report		Final Rep	
Name of Co	mpany: BO	OPCO, L.P.		240737		Contact: To	ny Savoie						
				bad, N.M. 8822			No. 575-887-732						
Facility Na	ne: Poker I	Lake Unit 2	74 Tank	Battery		Facility Typ	e: Exploration a	and Proc	duction			******	
Surface Ow	ner: Federa	al	Mineral (Owner: F	Federal			API No	. 30-015-3	35138			
				LOCA	ATION	OF REI	LEASE						
Unit Letter	Section	Township	1 0 1			South Line	Feet from the		East/West Line County				
О	12	24S	29E	360	Sout	outh 2310			East Eddy				
			•	Latitude N 32	.225443	Longitude	e_W 103.93691	7					
						OF RELI							
Type of Rele	ase: Crude o	sil .		INA I	UKE		Release: 7 bbls.		Volume l	Recovered:	None		
Source of Re							lour of Occurrence	e:	Date and Hour of Discovery: 9/3/14 at				
		•				9/3/14 time	unknown			ately 9:40 a			
Was Immedi	ate Notice G		l Vac - E] No ⊠ Not R	aguirad	If YES, To	Whom?						
By Whom?		<u> </u>	les [] NO [NOUN	equired	Date and H	lour						
Was a Water	course Reac	hed?				Date and Hour If YES, Volume Impacting the Watercourse.							
] Yes 🛭	₫ No									
If a Waterco	urse was Imr	pacted, Descr	ribe Fully.	*		l							
			•										
Describe Cau	ise of Proble	em and Reme	dial Actio	n Taken.*									
The float ins	ide the free v	water knock	out failed	to shut of the fluid	d level ca	using oil to p	pressure up and go	o out the	flare line.	The float s	ystem w	vas repaired.	
Describe Are	a Affected a	and Cleanup.	Action Ta	ken.*						_			
The release i	mpacted app	proximately 1	9,600 sq.1	ft of tank battery a									
				west of the tank l									
				ining on the vege OCD and BLM re				d been sc	raped up a	and stockpil	ed on-s	ite.	
The imarien	iculation wi	ii compiy wii	iii iiic ivivi	OCD and BEW N	cinculatio	m guidennes.	•						
				e is true and comp									
				nd/or file certain i ce of a C-141 rep									
				y investigate and									
				ptance of a C-141									
federal, state	, or local lav	vs and/or reg	ulations.							•			
							OIL CON	SERV.	<u>ATIOŅ</u>	DIVISI			
Signature:	Tan 6	Janes.							1/				
Signature.		June				Approved by	Environmental S	nacialist	. H				
Printed Nam	e: Tony Save	oie					Environmental S	peciansi	1/6	1	حب	_	
Title: Waste	Managemen	t and Remed	iation Spe	cialist		Approval Dat	te: 9/23/14		Expiration	Date:	VA		
							1						
E-mail Addre	ess: tasavoie	wbasspet.co	m			Condition Se	Approval: Rule:	s & Gu	idelines	Attached	d 🔲		
Date: 9/	22/10	+	Phone	: 432-556-8730	, -	HEMFE	NATION PRO	POSAL	. NO				
Attach Addi					12 C	HAN:_	10/23/14	<u>+</u>				10- 44	

FIELD SPILL REPORT

Distribution List: CJ Barry, TA Savoie, RL Gawlik, JR Smitherman, SF Johnson, FD Schoch, G Fletcher, J Fuqua, A Ruth, A Thompson, S Walters, B Blevins

DATE: September 3, 2014

LOCATION OF SPILL SITE: PLU 274 API 30-015-35138 UL O, Sec 12, Twns. 25S, R 29E

GPS COORDINATES (Lat & Long): N 32. 225443° W 103.936917°

ESTIMATED VOLUMES (Oil & Water Separately):

*If BBLs Recovered are not available at time of Initial Report: Send in Followup report when numbers are known

			*BBIs	Net			*BBIs	
Volume spilled:		BBIs Spilled	Recovered	Spilled		BBIs Spilled	Recovered	Net Spilled
On ground /or earth berm -	Oil:	7	0	7	Water:			0
Contained in impervious liner -	Oil:			0	Water:			0
Total:	Oil:	7	0	7	Water:	0	0	0


DESCRIPTION (What happened?): Discovery 0940 9/3/14


FWKO float failed sending fluid out the flare line, wind was blowing from SE to NW


SPILL RESPONSE (How was the spill cleaned up?):


EH&S was called to site to review, repairs underway

PICTURE ATTACHMENT:









Spill Calculations Worksheet					All light blue areas are Required Information			Incident Date			9/3/2014		
Only Change Values i	n Columns E	3, C & D I			<u> </u>	les aide at Time			Start Time End		Time		
				hange Formulas!! Conversion			Table	Incident Time			-		
		sions in fe				1966	CONTRACTOR	Location			PL	U 274	
	Length	Width	Depth	Total Volume of Fluid in Bbls		Conversions	Feet						
Average total depth				0.00	Fluid total	1≀inch	÷0.0833	Area	Standin g Liquid	In Soil	size	Oil Volume	Water Volume
Use oil depth or skim thickness				0.00	Oil volume	2 inches	0.1667	1. Very Light Mist		1/16in	328x150	2.28	
	2 (13)	1,84, page 141 gr 1,44		0.00		3 inches	0.2500	2. Spray, Pad		1/16in	175x112	0.91	
						4 inches	0:3333	3. Near Flare		2in	74x35	3.84	
-	Circula	r Spill				5 inches	0.4167	4					
	All dimensions in feet !					6 inches	0.5000	5					
	Diameter	Donth		Total Volume of Fluid		7 inches	0.5833						
Average total depth	Diameter	Depth	:	in Bbls. 0.00	Fluid total	8 inches	0.5833				Total Fluid	7.03	0
Use oil depth or skim				0.00	i idia totai	o inches	70.0007		sajed, kija		* Total Flaid	7.00	igarei
thickness			r	0.00	• • . • . • . •	9 inches	0.7500					100	
				0.00	Water Volume	10 inches	0.8333		Tuid Re	covered	Oil Volume	Water	Volum
				1		Timicies	0.9107	ANG TENNESS TO THE	Tula 110	- COVERCE			
	Fluid in	Soil Re	ectangular S	Spill *		1/256 inch	×0.000326			0 0			
		sions in fe			·	1/128 inch	£0.000651%	Weather Conditions				•	
	Length	Width	Depth-Soil Penetration	Total Volume of Fluid in Soil Pore Space (5%) in Bbls		1/64 inch	0.0013	Incident Detailed Discription	FWKO float failed sending fluid out the flar line, wind was blowing from SE to NW				
Average total depth	74	35	0:1667	3.84	Fluid total	1/32 inch 1/16 inch	0.0026s 0.0052	Immediate Actions Taken	EHS w underv		to site to rev	view, rep	airs
	Eluid in	Soil Ci	roular Spill	*			0.0104	Equiptment Component	FWKO	1			
	Fluid in Soil Circular Spill * All dimensions in feet!					1/8 inch 1/4 inch	0.0208	Cause	Float F	ailed and	l sent fluid to	flare	
		Depth-Soil Penetration		Total Volume of Fluid in Soil Pore Space (5%) in Bbls		3/8.inch	0.0313	Failure Discription					
Average total depth	76:54 7m	4. W. W. W. W. C. C. C. C.	9,1	0.00	Fluid total	1/2 inch	0.0417			******* * * * * * * * * * * * * * * *	viel de		- P. M.
* Based on 5% in soil pore space. Adjust up or down based upon site-specific conditions (sand vs. clay, soil dry or wet prior to event, etc.), local knowledge						5/8 inch 3/4 inch	0.0521		Name			100	
conditions (sand vs. (ay, son ary	or wet pric	or to event, etc.),	local knowledge			2 2U:U020	Person Making Report				•	
and judgment.						- 7/8 inch	0.0729		Phone			;	