

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Electra Federal #006	Facility Type	Flow line

Surface Owner	Federal	Mineral Owner		API No.	30-015-34708
---------------	---------	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	15	17S	30E					Eddy

Latitude N 32.83785° Longitude W 103.96420°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	2 bbl of oil, 10 bbls of produced water	Volume Recovered	1 bbl of oil, 8 bbls of produced water
Source of Release	Steel flow line	Date and Hour of Occurrence	10/17/2013	Date and Hour of Discovery	10/17/2013 @ 8:00 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Michelle Mullins	Date and Hour	10/28/2013 @ 7:42 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

NM OIL CONSERVATION  
ARTESIA DISTRICT

JUN 06 2014

Describe Cause of Problem and Remedial Action Taken.\*

A hole developed in the steel line due to corrosion. Shut in well and replaced the joint of steel pipe.


RECEIVED

Describe Area Affected and Cleanup Action Taken.\*

Initially an estimated 2 bbls of oil and 10 bbls of produced water were released from a corroded 3" steel line. We were able to recover 1 bbl of oil and 8 bbls of produced water with a vacuum truck. The spill area is located in the pasture. BBC completed remediation in accordance with the remediation plan approved by Mike Bratcher of NMOC in a meeting on 04/01/2014 and approved by Mike Burton of the BLM via email on 04/08/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:   
Printed Name: Robert Grubbs  
Title: Senior Environmental Coordinator  
E-mail Address: rgrubbs@concho.com  
Date: 6-4-14 Phone: (432) 661-6601

Approved by Environmental Specialist:

Approval Date: 6/6/14

Expiration Date: NA

Conditions of Approval:

Attached ☐

\* Attach Additional Sheets If Necessary

2RP-2039