

RECEIVED
JUL 30 2013

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division **NMOCD ARTESIA** to appropriate District Office in accordance with 19.15.29 NMAC
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company: LINN Energy	Contact: Joe Hernandez
Address: 2130 W Bender Blvd. - Hobbs, NM	Telephone No.: 575-942-8675
Facility Name: Turner B South Well 111 Flowline	Facility Type: Producing Oil Well

Surface Owner: BLM	Mineral Owner: BLM	Lease No.: LC-029395-B
--------------------	--------------------	------------------------

LOCATION OF RELEASE

30-015-29530

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	30	17S	31E	330	S	1825	E	Eddy

Latitude: 32 48' 8.322" Longitude: 103 54' 35.936"

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 25bbls	Volume Recovered: 0
Source of Release: Flowline	Date and Hour of Occurrence: 09/28/2011 - 0700	Date and Hour of Discovery: 09/28/2011 - 0800
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? T. Gregston, BLM, M. Bratcher, OCD	
By Whom? Fred Holmes	Date and Hour: 09/29/2011 - 0730	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Coupling thread integrity failed, back pressure caused line to break. Well was shut in, and repairs were made to the line.

Describe Area Affected and Cleanup Action Taken.* : Area is "tear-drop shaped" which includes road and portions of the pasture. Pasture area impact is approx. 560' long, the wider portion of the spill area is approx. 50' in diameter and as it goes northward, it is reduced to 10-15' wide. Impacted soils above regulatory threshold levels were manually and mechanically excavated from the spill area. During the course of the excavation soil samples were screened on site to determine the progress of the remediation. Impacted soils were transported off-site for disposal at Lea Land Landfill. Once the impacted soils were removed to acceptable levels, the pasture areas and road areas were backfilled with like materials and smoothed to grade. The pasture area was seeded with a BLM mix #2 and #4. Water bars were installed to prevent wind and water erosion.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jose Hernandez</i>	OIL CONSERVATION DIVISION		
Printed Name: Jose Hernandez	Approved by District Supervisor: <i>[Signature]</i>		
Title: Foreman	Approval Date: <i>10/6/12</i>	Expiration Date: <i>NA</i>	
E-mail Address: jhernandez@linneenrgy.com	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>	
Date: 10/15/2012	Phone: 575-738-1739		

* Attach Additional Sheets If Necessary

22P-932