

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Sterling Silver 3 Federal #6 Battery	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		Lease No.	NM-55142

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	3	24S	31E	1980	North	2310	West	Eddy

Latitude N 32.24812° Longitude W 103.76672°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	200 bbls water, 1 bbl oil	Volume Recovered	180 bbls
Source of Release	Rubber brushing failure between pump and motor caused tank to spill over	Date and Hour of Occurrence	1/23/13	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- OCD; James Amos- BLM		
By Whom?	Chancey Summers	Date and Hour	1/24/13 @ 1:54 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Rubber brushing failure between a pump and motor caused a tank to spill over releasing 200 bbls of produced water and 1 bbl of oil onto the ground. 180 bbls were recovered via vacuum truck and the brushing was repaired.

Describe Area Affected and Cleanup Action Taken.*

Rubber brushing failure between a pump and motor caused a tank to spill over releasing 200 bbls of produced water and 1 bbl of oil onto the ground. 180 bbls were recovered via vacuum truck and the brushing was repaired. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 04/05/2013 and approved by Jennifer Van Curen via email on 04/10/2013.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Chancey Summers

Title: HES Specialist

E-mail Address: Chancey.Summers@oxy.com

Date: 8-6-13

Phone: (575) 397-8216

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Approval Date:

4/22/15

Expiration Date:

MA

Conditions of Approval:

Final

Attached ☐

* Attach Additional Sheets If Necessary

2RP-1546