

District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1519648727		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P.		Contact: Bradley Blevins			
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329			
Facility Name: PLU 330H		Facility Type: Exploration and Production			
Surface Owner: Federal		Mineral Owner:		API No. 3001539253	

LOCATION OF RELEASE

Unit Letter D	Section 13	Township 24S	Range 30E	Feet from the 130	North/South Line	Feet from the 710	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	----------------------	------------------	----------------------	----------------	----------------

Latitude: 32.197383 Longitude: 103.827265

NATURE OF RELEASE

Type of Release: Crude oil, Produced water	Volume of Release: 1 barrel oil, 23 barrels produced water	Volume Recovered: No fluids were recovered
Source of Release: Flowline failed due to corrosion	Date and Hour of Occurrence: July 4 2015 @ 7:00am	Date and Hour of Discovery: July 4 2015 @ 8:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike/ Heather via e-mail	
By Whom? Amy Ruth	Date and Hour: July 4 2015 @ 4:49pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

NM OIL CONSERVATION  
ARTESIA DISTRICT

Describe Cause of Problem and Remedial Action Taken.\*

A flowline failed due to corrosion of the steel line, the well was shut in until repairs could be made.

JUL 10 2015

Describe Area Affected and Cleanup Action Taken.\*

A section of the flowline was repaired and the well was put back on production. No fluids were recovered.

RECEIVED

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>		OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins		Signed By: <u>Mike Blevins</u>	
Title: Assistant Remediation Foreman		Approved by Environmental Specialist:	
E-mail Address: bblevins@basspet.com		Approval Date: <u>7/14/15</u>	Expiration Date: <u>N/A</u>
Date: <u>7-10-15</u> Phone: 432-214-3704		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>8/10/15</u>	

\* Attach Additional Sheets If Necessary

2RD. 308

**Bratcher, Mike, EMNRD**

---

**From:** Blevins, Bradley <BBlevins@BassPet.Com>  
**Sent:** Friday, July 10, 2015 12:50 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** Blevins, Bradley  
**Subject:** Initial C-141 PLU 330H  
**Attachments:** doc04421520150710112228.pdf

Mike/ Heather,

Please find the initial C-141 for the PLU 330H, If you have any questions please let me know. Thank you

Brad Blevins  
Assistant Remediation Foreman  
BOPCO, LP  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office-575-887-7329  
Cell-1-432-214-3704  
[bblevins@basspet.com](mailto:bblevins@basspet.com)

## Patterson, Heather, EMNRD

---

**From:** Ruth, Amy C. <ACRuth@BassPet.Com>  
**Sent:** Saturday, July 04, 2015 4:49 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** jamos@blm.gov  
**Subject:** BOPCO PLU 330H flow line leak 7-4-15  
**Attachments:** IMG\_0707.JPG; IMG\_0711.JPG; IMG\_0723.JPG; Image with leak areaw.jpg  
  
**Categories:** printed

Leak was discovered this morning at 3 am. GPS is displayed on photos. Mostly produced water with some oil. The rupture due to corrosion in our steel line was clamped. The well was shut in until section can be replaced. No fluids were recovered. A C-141 will be submitted. Leak may exceed 25 bbls though not by much. The leak affected 1170 square feet of pasture west of the road and 915 square feet of lease road. Thanks!



*Amy C. Ruth*  
BOPCO, L.P.  
EH&S Remediation Specialist  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office: (575)887-7329  
Fax: (575)887-7473  
Cell: (432)661-0571