District I 1625 N. French District II	h Dr., Hobbs, N	NM 88240				New Mex	ico I Resources			Ĩ		Form C-14 August 8, 201
	, Artesia, NM I	88210				vation Div		Sub	mit 1 Com			- ·
1000 Rio Brazo District IV	os Road, Aztec					St. Franc		200	a	y to appropri ccordance w	ith 19.1	5.29 NMA
1220 S. St. Francis Dr. Conta Fr. NM 97505			anta Fe	a Fe, NM 87505				_				
	• • •		Relea	ase Notifi	cation	and Co	orrective A	ctior	1			
	521549			hna97-		<b>OPERA</b>			🛛 Initi	ial Report		Final Rep
	company: BC			<i>IV 13 1</i> Id, N.M. 8822			adley Blevins No. 575-887-73	29			t	
	ame: BEU D						e: Exploration		oduction			
Surface Ov	wner: Federa	al		Mineral	Owner:				API No	o. 3001541	798	
				LOC	ATION	N OF REI	LEASE				i	
Unit Letter D	Section	Township 21S	1	Feet from the 700	North/	South Line	Feet from the 969	East/	West Line	County Eddy		
<u> </u>		215	1296		2 401200	) Longitud	<b>e</b> : 104.008657			Luuy		
						0						
Type of Rela	ease: Lubrica	tor fitting fai	iled resulting	NA' g in fire, no cru		OF REL	EASE Release: None		Volume	Recovered: 1	NA	
gas loss.	elease: Hydra						lour of Occurren			Hour of Dis	i	
						7-30-15 @	8:45pm		7-30-15	@ 8:59pm		
Was Immed	liate Notice G					If YES, To	Whom? Mike B	ratcher,	Jim Amos	via email	1	
		$\bowtie$	Yes 📋	No 🗌 Not F	Required							
	Bradley Blev	vins	Yes 📋	No 🛄 Not F	Required		lour: 7-30-15 @		1	NM OIL	COM	e
Was a Wate	Bradley Blev proourse Reac	vins ched?	]Yes 🛛		Required		lour: 7-30-15 @ olume Impacting		n ercourse.		<del>6 3</del>	2015
Was a Water If a Waterco Describe Ca Lubricator f	purse was Imp ause of Proble fitting failed of	vins whed? pacted, Descr em and Reme causing hydra	] Yes 🛛 ribe Fully.* edial Action	No Taken.*		lf YES, Vo		the Wat		AU RE	G 3 CEIV	2015 ED
Was a Water If a Waterco Describe Ca Lubricator f eliminated t Describe Ar The fire was	burse was Imp ause of Proble fitting failed of the fire burned rea Affected a s contained to	vins whed? pacted, Descr em and Reme causing hydra d itself out. and Cleanup o an area betw	Yes ribe Fully.* edial Action aulic fluid to Action Take ween the eng	No Taken.* drip on the eng n.* jine mufflers or	gine exha	If YES, Vo ust, igniting a . No fluid or	olume Impacting	e compre	essor skid. ubricator li	AU RE Once the fue	G 3 CEIV	2015 ED e was
Was a Water If a Waterco Describe Ca Lubricator f eliminated t Describe Ar The fire was by compress I hereby cer regulations public healt should their or the enviro	ause of Proble fitting failed of the fire burned rea Affected a s contained to sor mechanic	vins whed? pacted, Descr pacted, Descr causing hydra d itself out. and Cleanup o an area betw information g are required ronment. The nave failed to ddition, NMG	Yes ribe Fully.* edial Action aulic fluid to Action Take ween the eng ng morning. given above i to report ance adequately i OCD accepta	No Taken.* drip on the eng n.* jine mufflers on The skid was p is true and com l/or file certain of a C-141 rep nvestigate and	gine exha n the skid power was plete to the release no port by the remediate	If YES, Vo ust, igniting a . No fluid or shed and com ne best of my otifications a e NMOCD m e contaminati	a small fire on the	e compro- ed; the l in servi understa ctive act Report" o reat to g	essor skid. ubricator li ice. Ind that pur tions for re does not re round wate sibility for o	AU RE Once the fue one was repla suant to NM leases which lieve the ope er, surface w compliance v	CEIV CEIV el source aced and coCD ru may er rator of ater, hur with any	2015 ED e was l inspected lability man health
Was a Water If a Waterco Describe Ca Lubricator f eliminated t Describe Ar The fire was by compress I hereby cer regulations i public healt should their or the enviro federal, state	ause of Proble fitting failed of the fire burned rea Affected a s contained to sor mechanic tify that the i all operators th or the envir operations h onment. In a e, or local lay	vins whed? pacted, Descr pacted, Descr em and Reme causing hydra d itself out. and Cleanup o an area betw information g are required to ddition, NMG ws and/or reg	Yes ribe Fully.* edial Action aulic fluid to Action Take ween the eng ng morning. given above i to report ance adequately i OCD accepta.	No Taken.* drip on the eng n.* jine mufflers on The skid was p is true and com l/or file certain of a C-141 rep nvestigate and	gine exha n the skid power was power was release n port by the remediate 1 report d	If YES, Vo ust, igniting a . No fluid or shed and com the best of my otifications a e NMOCD m e contaminations of the state of the state of the state of the state of the state of the stat	a small fire on the gas loss was not pressor put back knowledge and und perform corre arked as "Final F ion that pose a the re the operator of	e compro- ed; the l in servi understa ctive act Report" of reat to g respons	essor skid. ubricator li ice. ind that pur tions for re does not re round wate sibility for o	AU RE Once the fue one was repla suant to NM leases which lieve the ope er, surface w compliance v	CEIV CEIV el source aced and coCD ru may er rator of ater, hur with any	2015 ED e was l inspected lability man health
Was a Water If a Waterco Describe Ca Lubricator f eliminated t Describe Ar The fire was by compress I hereby cer regulations a public healt should their or the enviro federal, state Signature: Printed Nam	ause of Proble fitting failed of the fire burned rea Affected a s contained to sor mechanic trify that the i all operators h or the envir operations h onment. In a e, or local law	vins whed? pacted, Descr pacted, Descr em and Reme causing hydra d itself out. and Cleanup o an area betw information g are required to ddition, NMG ws and/or reg Blevins	Yes ribe Fully.* edial Action aulic fluid to Action Take ween the eng ng morning. given above i to report and e acceptance adequately i OCD accepta	No Taken.* drip on the eng n.* jine mufflers on The skid was p is true and com l/or file certain of a C-141 rep nvestigate and	gine exha n the skid power was plete to the release n- port by the remediate 1 report de	If YES, Vo ust, igniting a . No fluid or shed and com otifications a e NMOCD m e contaminations oes not reliev Approved by	a small fire on the gas loss was not pressor put back knowledge and on pressor put back knowledge and on perform corre arked as "Final Fion that pose a the the operator of <u>OIL CON</u> Environmental S	e compre ed; the l in servi understa ctive act Report" of respons Specialis	essor skid. ubricator li ice. Ind that pur tions for re does not re round wate sibility for o <u>ATION</u> st:	AU RE Once the fue one was repla suant to NM leases which lieve the ope er, surface w compliance v	CEIV el source aced and coCD ru may er rator of ater, hui with any	2015 ED e was l inspected lability man health
Was a Water If a Waterco Describe Ca Lubricator f eliminated t Describe Ar The fire was by compress I hereby cer regulations i public healt should their or the enviro federal, state Signature: Printed Nam	ause of Proble fitting failed of the fire burner rea Affected a s contained to sor mechanic tify that the i all operators th or the envir operations h onment. In a e, or local lay	vins whed? pacted, Descr pacted, Descr em and Reme causing hydra d itself out. and Cleanup o an area betw information g are required to ddition, NMG ws and/or reg May and the second state of the second st	Yes ribe Fully.* edial Action aulic fluid to Action Take ween the eng ng morning. given above i to report and e acceptance adequately i OCD accepta ulations.	No Taken.* drip on the eng n.* jine mufflers on The skid was p is true and com l/or file certain of a C-141 rep nvestigate and	gine exha n the skid power was plete to the release n- port by the remediate 1 report de	If YES, Vo ust, igniting a . No fluid or shed and com otifications a e NMOCD m e contaminations oes not reliev Approved by	a small fire on the gas loss was not pressor put back knowledge and on pressor put back knowledge and on perform corre arked as "Final Fion that pose a the the operator of <u>OIL CON</u> Environmental S	e compre ed; the l in servi understa ctive act Report" of respons Specialis	essor skid. ubricator li ice. Ind that pur tions for re does not re round wate sibility for o <u>ATION</u> st:	AU RE Once the fue once the fue ine was replation suant to NM leases which lieve the ope er, surface w compliance v LDIVISIO	CEIV el source aced and coco ru may er rator of ater, hu with any CA	2015 ED e was l inspected lability man health
Was a Water If a Waterco Describe Ca Lubricator f eliminated the Describe Ar The fire was by compress I hereby cer regulations f public healt should their or the enviro federal, state Signature: Printed Narr Title: Assist E-mail Addu	recourse Reac purse was Imp ause of Proble fitting failed of the fire burned rea Affected a s contained to sor mechanic tify that the i all operators h or the envir operations h onment. In a e, or local law	vins ched? pacted, Descri- pacted, Descri- em and Reme causing hydra d itself out. and Cleanup o an area betw information g are required to information, NMC ws and/or reg <u>Slevins</u> tion Foremar s@basspet.cc	Yes ribe Fully.* edial Action aulic fluid to Action Take ween the eng ng morning. given above i to report ance adequately i OCD acceptance adequately i OCD acceptance adequately i OCD acceptance adequately i occ acceptance adoquately i occ acceptance ad	No Taken.* drip on the eng n.* jine mufflers on The skid was p is true and com l/or file certain of a C-141 rep nvestigate and	gine exha n the skid power was plete to the release n- port by the remediate 1 report de	If YES, Vo ust, igniting a . No fluid or shed and com otifications a e NMOCD m e contaminations oes not reliev Approved by	a small fire on the gas loss was not pressor put back knowledge and on pressor put back knowledge and on perform corre arked as "Final Fion that pose a the the operator of <u>OIL CON</u> Environmental S	e compre ed; the l in servi understa ctive act Report" of respons Specialis	essor skid. ubricator li ice. Ind that pur tions for re does not re round wate sibility for o <u>ATION</u> st:	AU RE Once the fue once the fue ine was replated suant to NM leases which lieve the ope er, surface w compliance w compliance w DIVISIO	CEIV el source aced and coco ru may er rator of ater, hu with any CA	2015 ED e was l inspected lability man health
Was a Water If a Waterco Describe Ca Lubricator f eliminated the Describe Ar The fire was by compress I hereby cer regulations f public healt should their or the enviro federal, state Signature: Printed Narr Title: Assist E-mail Addu	ause of Proble fitting failed of the fire burned rea Affected a s contained to sor mechanic tify that the i all operators h or the envir operations h onment. In a e, or local law	vins ched? pacted, Descri- pacted, Descri- em and Reme causing hydra d itself out. and Cleanup o an area betw information g are required to information, NMC ws and/or reg <u>Slevins</u> tion Foremar s@basspet.cc	Yes ribe Fully.* edial Action aulic fluid to Action Take ween the eng ng morning. given above i to report ance adequately i OCD acceptance adequately i OCD acceptance adequately i OCD acceptance adequately i occ acceptance adoquately i occ acceptance ad	No Taken.* drip on the eng in.* ine mufflers or The skid was p is true and com l/or file certain o fa C-141 rep investigate and ance of a C-141	gine exha n the skid power was plete to the release n- port by the remediate 1 report de	If YES, Vo ust, igniting a . No fluid or shed and com otifications a e NMOCD m e contaminations oes not reliev Approved by	a small fire on the gas loss was not- pressor put back knowledge and on pressor put back knowledge and on pressor put back knowledge and on the perform corre arked as "Final Fion that pose a the the operator of <u>OIL CON</u> Environmental S	e compre ed; the l in servi understa ctive act Report" of respons Specialis	essor skid. ubricator li ice. Ind that pur tions for re does not re round wate sibility for o <u>ATION</u> st:	AU RE Once the fue once the fue ine was replation leases which lieve the ope or, surface w compliance w LDIVISIC Date: N Attachec	CEIV el source aced and locD ru may er rrator of ater, hui with any	2015 ED e was inspected danger liability man health other
Was a Water If a Waterco Describe Ca Lubricator f eliminated the Describe Ar The fire was by compress I hereby cer regulations f public healt should their or the enviro federal, state Signature: Printed Narr Title: Assist E-mail Addu	recourse Reac purse was Imp ause of Proble fitting failed of the fire burned rea Affected a s contained to sor mechanic tify that the i all operators h or the envir operations h onment. In a e, or local law	vins ched? pacted, Descri- pacted, Descri- em and Reme causing hydra d itself out. and Cleanup o an area betw information g are required to information, NMC ws and/or reg <u>Slevins</u> tion Foremar s@basspet.cc	Yes ribe Fully.* edial Action aulic fluid to Action Take ween the eng ng morning. given above i to report ance adequately i OCD acceptance adequately i OCD acceptance adequately i OCD acceptance adequately i occ acceptance adoquately i occ acceptance ad	No Taken.* drip on the eng in.* ine mufflers or The skid was p is true and com l/or file certain o fa C-141 rep investigate and ance of a C-141	gine exha n the skid power was plete to the release n- port by the remediate 1 report de	If YES, Vo ust, igniting a . No fluid or shed and com otifications a e NMOCD m e contaminations oes not reliev Approved by	a small fire on the gas loss was not pressor put back knowledge and on pressor put back knowledge and on perform corre arked as "Final Fion that pose a the the operator of <u>OIL CON</u> Environmental S	e compre ed; the l in servi understa ctive act Report" of respons Specialis	essor skid. ubricator li ice. Ind that pur tions for re does not re round wate sibility for o <u>ATION</u> st:	AU RE Once the fue once the fue ine was replation leases which lieve the ope or, surface w compliance w LDIVISIC Date: N Attachec	CEIV el source aced and locD ru may er rrator of ater, hui with any	2015 ED e was l inspected lability man health

## Patterson, Heather, EMNRD

From:	Blevins, Bradley <bblevins@basspet.com></bblevins@basspet.com>
Sent:	Monday, August 03, 2015 9:46 AM
То:	Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James
Cc:	Blevins, Bradley; Savoie, Tony A.; Ruth, Amy C.
Subject:	Initial/ Final C-141 DI28 Compressor Fire
Attachments:	doc04475420150803082119.pdf

All,

Please find the attached C-141 for the compressor fire that occurred at the DI28/Golden 8 Battery. If you have any questions please let me know.

Thank you

Brad Blevins Assistant Remediation Foreman BOPCO, LP 522 W. Mermod, Suite 704 Carlsbad, NM 88220 Office-575-887-7329 Cell-1-432-214-3704 bblevins@basspet.com

## Patterson, Heather, EMNRD

From:	Blevins, Bradley <bblevins@basspet.com></bblevins@basspet.com>
Sent:	Thursday, July 30, 2015 10:04 PM
То:	Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos
Cc:	Blevins, Bradley
Subject:	BEU DI 28 Compressor

All,

This email is to inform you that BOPCO had a minor fire on a compressor at the DI 28 location. The hydraulic lubricator line failed causing the hydraulic line and plug wire to catch fire. All damage is reported to be minor and no fluid loss was noted, the site has been secured for the night and will be accessed first thing tomorrow morning. I will keep you posted if site conditions change. Thanks

Sent from my iPhone

## Patterson, Heather, EMNRD

From:	Blevins, Bradley <bblevins@basspet.com></bblevins@basspet.com>
Sent:	Friday, July 31, 2015 10:16 AM
То:	Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James
Cc:	Blevins, Bradley
Subject:	FW: BEU DI 28 Compressor
Attachments:	photo 1.jpg

Update:

After the review this am, the fire was small and contained between the mufflers. A very small amount of fluid remained inside the compressor skid, no fluid was released to the ground surface. The skid will be cleaned and compressor mechanics are currently replacing two 1/4 inch nipples and stainless tubing. If you need further information please let me know.

Thank you,

-----Original Message-----From: Blevins, Bradley Sent: Thursday, July 30, 2015 10:04 PM To: Mike Bratcher; heather.patterson@state.nm.us; Jim Amos Cc: Blevins, Bradley Subject: BEU DI 28 Compressor

All,

This email is to inform you that BOPCO had a minor fire on a compressor at the DI 28 location. The hydraulic lubricator line failed causing the hydraulic line and plug wire to catch fire. All damage is reported to be minor and no fluid loss was noted, the site has been secured for the night and will be accessed first thing tomorrow morning. I will keep you posted if site conditions change. Thanks

Sent from my iPhone