

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

SEP 15 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1526426751 **4323** **OPERATOR** ☐ Initial Report ☒ Final Report

Name of Company - Chevron USA Inc.	Contact - Stephen Gwin
Address - 1616 W Bender Blvd, Hobbs NM	Telephone No. 575-263-0427
Facility Name - Federal BN #1	Facility Type - Gas Well Compressor



Surface Owner - Federal	Mineral Owner - Federal	API No. 30-015-23498
-------------------------	-------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	1592 Feet from the	North/South Line	444 Feet from the	East/West Line	County
H	17	22S	26E		North Line		East Line	Eddy

Latitude 32.395141 Longitude -104.307896

NATURE OF RELEASE

Type of Release - Vent	Volume of Release - 110 mcf	Volume Recovered - 0
Source of Release - Suction nipple on compressor	Date and Hour of Occurrence 9/12/2015 ~ 1:00 PM to 9/14/2015 ~ 8:00 AM	Date and Hour of Discovery 9/14/2015 8:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? - Stephen Gwin	Date and Hour 9/15/2015 12:25 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Crack was discovered on nipple on the suction side of compressor.		
Describe Area Affected and Cleanup Action Taken.* Nipple on suction side of compressor was replaced.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Stephen Gwin	Approved by Environmental Specialist: 	
Title: HES Specialist	Approval Date: <u>9/21/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: Stephen.gwin@chevron.com	Conditions of Approval: <u>FINAL</u>	Attached <input type="checkbox"/>
Date: 9/15/2015 Phone: 575-263-0427		

* Attach Additional Sheets If Necessary

2RP-32141

Bratcher, Mike, EMNRD

From: Gwin, Stephen <Stephen.Gwin@chevron.com>
Sent: Tuesday, September 15, 2015 12:44 PM
To: Bratcher, Mike, EMNRD
Subject: Chevron - Fed BN #1 - C141
Attachments: Fed BN #1 C-141.pdf

Mike,

Chevron had a venting event at a compressor on the Fed BN #1. A nipple on the suction side of the compressor had a crack in it and we lost 110 mcf. If you have any questions please let me know.

Thanks,

Stephen Gwin ●●

Health and Environment Specialist

Stephen.Gwin@chevron.com

Mid-Continent Business Unit

Hobbs, Euncie and Carlsbad

1616 W. Bender Blvd.

Hobbs, NM 88240

Tel 575-263-0427

Mobile 575-408-0073