

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 17 2015

Form C-141
Revised August 8, 2011

Submitted to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

nAB1526458218

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Dirty Dozen Federal Com #4H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-015-38150
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 36	Township 19S	Range 31E	Feet from the 1650'	North/South Line South	Feet from the 660'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.614254 Longitude -103.8162079

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 12 bbls PW	Volume Recovered: 10 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 8/31/2015 7:00 am	Date and Hour of Discovery: 8/31/2015 7:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by corroded flowline in the battery piping. A vacuum truck was dispatched to recover all standing fluid and repairs were made.

Describe Area Affected and Cleanup Action Taken.*

This release was contained within a lined facility. The facility was cleaned, repaired and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By  Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 9/22/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: September 14, 2015 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2RP-3277

Bratcher, Mike, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Thursday, September 17, 2015 2:18 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; James_Amos@blm.gov; Shelly Tucker
Subject: (Notification/C-141 Initial-Final) Dirty Dozen Federal Com #4H (30-015-38150)
Attachments: 8-31-2015 Dirty Dozen Fed Com #4H (TB) Initial-Final.pdf

Mr. Bratcher,

COG Operating LLC is reporting a release on the Dirty Dozen Federal Com #4H (30-015-38150)
Unit P Section 36 Township 19S Range 31E
The release occurred at 7:00 am 8/31/2015
Released: 12 bbls PW
Recovered: 10 bbls PW

This release was caused by corroded flowline in the battery piping. A vacuum truck was dispatched to recover all standing fluid and repairs were made. This release remained within the lined berm. Attached is a C-141 Initial-Final for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.