

Occidental Permian Limited Partnership

April 14, 2005

New Mexico Oil Conservation Division District I 1625 N. French Drive Hobbs, New Mexico 88240

Attn: Environmental Engineering

RE: Remediation Plan

South Hobbs Unit 8" Injection Trunkline from Central T/B to Injection Building #1

UL'K', Sec. 4, T-19-S, R-38-E

Leak occurred on 04/13/2005, at approximately 09:00 PM. An 8" cement lined steel trunkline used to transfer injection water from South Hobbs Unit Central T/B to South Hobbs Unit Injection Building #1 split causing spill. Valves on both ends of the trunkline were shut to isolate leak. The line operates at approximately 1100 pounds and has a rate of approximately 16,000 barrels per day. The exact throughput of the line is unknow since there are 2 trunklines that transfer injection water to this injection building. The area affected by this spill is an area measuring approximately 150° X 543°, in the pasture north and west of the spill site, and an area approximately 100° X 360° in the pasture to the south and east of the leak site where water ran. An estimated 400 barrels of injection water was spilled, no oil was spilled. All fluid was lost, none was recovered. The State of New Mexico is the surface owner. Depth to ground water according to State Engineers Office is an average of 48°, for all wells in the area, giving this spill site a ranking of 20. Remediation of the spill site will be as follows:

- 1. Piping will be repaired.
- 2. Soil samples will be gathered from ditchline and affected area.
- 3. NMOCD guidelines will be used to insure entire site is in compliance with guidelines.
- 4. Soils removed will be replaced with clean fresh soils, where needed.
- 5. Soil analysis data will be submitted with final closure letter.
- 6. Affected area will be monitored for vegetation impact, expect minimal impact due to water.

aculty-157984 Jaculty-FPAC0603830930 Incident-nPAC0603831111

Catter - PPA COCO3831464 Stanolind Rd, Hobbs, New Mexico 88240

April 14, 2005 Page 2

If you have any questions, or if I can be of further assistance, please contact me at (505) 397-8251.

Steven M. Bishop

HES Technician/Hobbs RMT Steven_Bishop@oxy.com

(505) 397-8251

Attachments: Initial C-141

Hand drawn map of spill site

STEION M BISLEY

Analytical data of South Hobbs Unit Injection Water dated 4/5/2005



District I 1625 N. French Dr., Hobbs, NM 88240 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate

District Office in accordance with Rule 116 on back side of form

Form C-141

Revised October 10, 2003

Release Notification and Corrective Action OPERATOR ☐ Initial Report Final Report Name of Company Occidental Permian Limited Partnership Contact Steven M. Bishop Telephone No. (505) 397-8251 Address 1017 West Stanolind Road, Hobbs, N.M. 88240 Facility Name South Hobbs Unit Injection System Facility Type Production Lease No. Mineral Owner Surface Owner State of New Mexico Occidental Permian Limited Partnership LOCATION OF RELEASE Unit Letter Feet from the North/South Line East/West Line Section Township Range Feet from the County ίΚ, 19-S 38-E LEA Latitude North 32°41'12.80" LongitudeWest 103°09'18.10" NATURE OF RELEASE Volume of Release Volume Recovered Type of Release 400 Bbls Injection Water 0 Bbls Date and Hour of Occurrence Source of Release Date and Hour of Discovery 8" cemetn lined steel injection trunkline 04/13/2005 09:00 PM 04/13/2005 09:00 PM Was Immediate Notice Given? If YES, To Whom? Gary Wink By Whom? Robert N. Gilbert Date and Hour 04/13/2005 09:30 PM Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. N/A ☐ Yes 🛛 No If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* An 8" cement lined steel injection trunkline from South Hobbs Unit Central T/B to South Hobbs Unit Injection Building #1 split causing spill. Isolated the trunk line by shutting valves at both ends. Describe Area Affected and Cleanup Action Taken.* Area affected is approximately 150' X 543' of pasture to the northeast of leak site and an area to the southwest of the leaksite approximately 100' X 360' where water ran. No fluid was recovered. Piping will be repaired, and samples will be taken in affected area to insure area is in compliance with NMOCD guidelines for spills. Vegetation will be monitored for impact where water ran from leaksite, minimal impact is expected. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Expiration Date:

Attached

Approved by District Supervisor:

Approval Date:

Phone: (505) 397-8251

Conditions of Approval:

E-mail Address: Steven_Bishop@oxy.com

Printed Name: Steven M. Bishop

Title: HES Technician

Date: 04/14/2005

Signature:

^{*} Attach Additional Sheets If Necessary

4L'K', Sec. 4, T-19-5, R-38-E

SPILL MAP


N 32°41'12.80" W 103°09' 18,10" (NAD83) PLEASE DRAW SKETCH OF SPILL AND INDICATE WHERE SPILL ORIGINATED.

South HOBBS Unit INSECTION SYSTEM

8"Coment I. ARC Steel to Building #1

4 113105 9:00 pm 1100# - 16,000 bbls/day

estimate OBOX 400 BW & recovered





MITCHELL ANALYTICAL LABORATORY

2638 Faudree Odessa, Texas 79765-8538 561-5579

Company: Nalco Energy Services										
Well Number: Lease: Location: Date Run: Lab Ref #:	SHU Pump Dis #2 OXY 4/5/2005 05-apr-n24611						Date Sam Sampled Employee	mple Temp: 70 te Sampled: 4/4/2005 mpled by: Mike Athey nployee #: 27-008 alyzed by: DOM		
Hydrogen Sulf Carbon Dioxid		(H2S) (CO2)			olved (Mg/L 406.00		E q. Wt. 16.00	MEq/L 25.38
Dissolved Oxy		(02)			ANAL					
Cations										
Calcium Magnesium Sodium		(Ca++ (Mg++ (Na+)					241.20 478.24 2,702.79		20.10 12.20 23.00	12.00 39.20 117.51
Barium		(Ba++)							
Manganese		(Mn+)		NOT	ANAL	YZED	.04		27.50	.00
				A	Anions					
Hydroxyl Carbonate BiCarbonate Sulfate Chloride		(OH-) (CO3= (HCO3- (SO4= (Cl-)	-)	-			.00 .00 1,490.84 850.00 4,504.95		17.00 30.00 61.10 48.80 35.50	.00 .00 24.40 17.42 126.90
Total Iron (Fe) Total Dissolved Solids Total Hardness as CaCO3 Conductivity MICROMHOS/CM						1	0.07 10,674.14 2,563.78 18,000	}	18.60	.00
pH 6.720 Specific Gravity (60/60	F	1.007
CaSO4 Solubility @ 80 F. 17.39 MEq/L, CaSO4 scale is unlikely										ely /
CaCO3 Scale Ind 70.0 80.0 90.0	: (211 091 129	100.0 110.0 120.0		.129 .389 .389	130. 140. 150.	0	.689 .689 .969		