

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NMLB1028134966

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ALAMO PERMIAN RESOURCES, LLC	Contact	CARIE STOKER
Address	415 W. WALL ST. SUITE 500	Telephone No.	432 664 7659
Facility Name:	WEST ARTESIA GRAYBURG UNIT	Facility Type:	WATER INJECTION WELL

Surface Owner	STATE	Mineral Owner		API No.	30-15-02648
---------------	-------	---------------	--	---------	-------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	8	18S	28E	2310	N	990	W	EDDY

NATURE OF RELEASE


Type of Release:	PRODUCED WATER	Volume of Release:	UNKNOWN	Volume Recovered:	8 BBLs
Source of Release:	Injection truck line	Date and Hour of Occurrence:	09/02/2010	Date and Hour of Discovery	09/02/2010 @ 5:00 PM MST
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Al Perry	Date and Hour	09/02/2010 @ 5: PM MST		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The injection trunk line on the West Artesia Grayburg Unit experienced a leak in the pasture South of the West Artesia Grayburg Unit #4, not the individual line. The West Artesia Grayburg Unit #4, an injection well, is being flowed back to a frac tank in preparation for a repair of the well. The leak was repaired, and a vacuum truck picked up 8 bbls of water.

Describe Area Affected and Cleanup Action Taken.* The injection trunk line on the West Artesia Grayburg unit experienced a leak in the pasture South of the West Artesia Grayburg Unit #4; not the individual line. The West Artesia Grayburg Unit #4, an injection well, is being flowed back to a frac tank in preparation for a repair of the well. The leak was repaired, and a vacuum truck picked up 8 bbls of water. All areas with elevated chlorides have been excavated per OCD requirements. Closure plan approved and on file with NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Carrie Stoker</u>		OIL CONSERVATION DIVISION	
		Approved by Environmental Specialist:	
Printed Name: CARIE STOKER		 Approval Date: <u>11/25/15</u> Expiration Date: <u>N/A</u>	
Title: REGULATORY AFFAIRS COORDINATOR			
E-mail Address: carie@stokeroilfield.com		Conditions of Approval: <u>FINAL</u>	Attached <input checked="" type="checkbox"/>
Date: <u>11/25/2015</u>	Phone: 432 664 7659		

* Attach Additional Sheets If Necessary

RELEASE #3 OF 3
NMLB 1028134966

2RP-D/H/H