
# Merit Energy Turner B North Battery Closure Report Unit L, Section 20, Township 17S, Range 31E Eddy County, New Mexico

**September 15, 2004** 



RECEIVED

SEP 3 0 2004

GOB ARTESIA

Prepared for:

Merit Energy P.O. Box 69 Loco Hills, New Mexico

By:

Safety & Environmental Solutions, Inc. 703 E. Clinton Suite 102 Hobbs, New Mexico 88240 (505) 397-0510

# **TABLE OF CONTENTS**

I.	Company Contacts
II.	Background
Ш.	Contaminant and Size of Area
IV.	Surface and Ground Water
V.	Soils
VI.	Work Performed
VII.	Figures & Appendices

### I. Company Contacts

Brandon Ripley Merit Energy 505-420-5502 bripley@pvtnetworks.net 505-397-0510 ballen@sesi-nm.com

#### II. Background

Safety & Environmental Solutions, Inc. (SESI) was contracted by Merit Energy to perform assessment and cleanup services on an area identified as the Turner B North Battery. The site is located in Section 20, Township 17S, Range 31E, Eddy County, New Mexico The subject site is a tank battery area, which is used for the storage of fluids produced from the wells associated with this lease. On January 15, 2004, the produced water tank leaked produced fluids onto the ground inside the bermed area of the battery. Approximately 510 barrels of fluid was released and approximately 500 barrels was recovered.

#### III. Contaminant and Size of Area

The suspected contaminant is produced water associated with the tank battery at the site. The release was contained inside the bermed area of the battery. The affected area was not grossly stained with hydrocarbons. (Site Plan)

Crude oil and produced water are considered exempt oilfield waste. No evidence of other contaminants was observed.

#### IV. Surface and Ground Water

There is no groundwater of record in the area according to information received from the New Mexico State Engineer.

#### V. Soils

The soils in the area are predominantly sand and sandy loam.

#### VI. Work Performed

The cleanup level reached by the application of the "Guidelines for Remediation of Leaks, Spill and Releases" *New Mexico Oil Conservation Division* – August 13, 1993 to this site is 5000 ppm TPH.

The contaminated area at the SW corner of the tank battery was excavated manually utilizing shovels and wheelbarrows. Approximately 12-inches of oil saturated soils were removed from a 15-ft X 20-ft area. The contaminated soil was stockpiled west of the tanks. The excavated area was sprayed with ammonium-nitrate solution to facilitate bio-remediation; the excavated area was filled with clay up to the bottoms of the adjacent tanks, and then contoured with rakes. One area of the firewall that had washed out was replaced. Wire fencing that had been removed was replaced.

## VII. Figures & Appendices

Figure 1 - Vicinity Map Figure 2 - Site Plan Appendix A - C-141 Appendix B - Site Photos Figure 1
Vicinity Map






Figure 2 Site Plan





Not to Scale

rth Battery
Safety & Environmenta

**Merit Energy** 

Turner B North Battery Sec. 20, 17S, R31E Eddy County, New Mexico

Safety & Environmental Solutions, Inc.

Appendix A C-141 District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

\* Attach Additional Sheets If Necessary


# State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003 Jubinit 2 Copies to appropriate


Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action			
	OPERATOR	Initial Report  Final Report	
Name of Company Merit Energy	Contact Namy While		
Address 1.0. Box 69 LxoHille, Will	Telephone No. 5,05-478-	5516	
Facility Name Turger & North Battery Facility Type Battery			
Surface Owner Fedoral Mineral Owner	r Fed	Lease No. 029 395 B	
LOCATION OF RELEASE			
Unit Letter Section Township Range Feet from the No.	rth/South Line   Feet from the   Eas	t/West Line   County   Edd 4	
LatitudeLongitude			
$\eta$ NATURE OF RELEASE			
Type of Release WTR Froduced	Volume of Release 5)0	Volume Recovered 500 BBLS	
Source of Release KAN TANKS OVER	Date and Hour of Occurrence	Date and Hour of Discovery	
Was Immediate Notice Given?  Yes No Not Required  If YES, To Whom?			
By Whom? Dane with Date and Hour 1.15-04 3:00 PM			
Was a Watercourse Reached?  Yes D No  If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*			
Describe Cause of Problem and Remedial Action Taken.* Electrical fairly of fransfer pump caused water fant  to run over. Vaccuumed spill			
Describe Area Affected and Cleanup Action Taken.* Firewall full of flw Acked up fluid with			
Valluum Fruck			
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.			
1 11 4	OIL CONSER	VATION DIVISION	
Signature: Approved by District Supervisor:			
Printed Name: Jany Wh. Te	Approval Date:	Expiration Date:	
Title: Llase optravol	rippioval Date.	DAPHORIUM DAIG.	
E-mail Address:	Conditions of Approval:	Attached	
Date: 1-12-03 Phone: 505-420-5516			


Appendix B Site Photos




Backfilling excavated area, looking from Southeast




Washed out firewall section before repair, looking from the East.



Inside of containment area finished, from SE



Firewall section replaced, from the East



Firewall section replaced, from West