

March 3, 2014

Subject:

AMARILLO 921 North Bivins Amarillo, Texas 79107 Phone 806.467.0607 Fax 806.467.0622 Mr. Mike Bratcher **NMOCD District 2** 811 S. 1st Street Artesia, NM 88210

ARTESIA

408 West Texas Ave. Artesia, New Mexico 88210 Phone 575.746.8768 Fax 575.748.8905 Remediation and Closure Report

Devon Energy Corp.

Black Jack 1 Federal No. 4H API # 30-015-37065 2RP-1978

HOBBS

318 East Taylor Street Hobbs, New Mexico 88241 Phone 505.393.4261 Fax 505.393.4658 Dear Mr. Bratcher,

Devon Energy has contracted Talon/LPE (Talon) to perform soil assessment and remediation services at the above referenced Black Jack 1 Federal No. 4H release. The results of our soil assessment, completed remediation activities and closure request are submitted herein.

MIDLAND

2901 State Highway 349 Midland, Texas 79706 Phone 432.522.2133 Fax 432.522.2180

Incident Date

October 3, 2013

OKLAHOMA CITY
7700 North Hudson Ave
Suite 10
Oklahoma City, Oklahoma 73116
Phone 405.486.7030
Fax 806.467.0622

Background Information

SAN ANTONIO 13111 Lookout Way San Antonio, TX 78233 Phone 210.265.8025 Fax 210.568.2191 The Black Jack 1 Federal No. 4H is located approximately thirty-seven (37) miles southeast of Carlsbad, New Mexico. The legal location for the site is Section 1, Township 24 South and Range 30 East in Eddy County, New Mexico. More Specifically the latitude and longitude for the release are 32.2407998 North and -103.835714 West.

According to the soil survey provided by the United States Department of Agriculture National Resources Conservation Services, the soil in this area is made up of Tonuco loamy fine sand with 0 to 3 percent slopes. Per the New Mexico Bureau of Geology and Mineral Resources, the local surface and shallow geology, Paleozoic Age sedimentary deposits, is comprised of the Salado formations which include loamy alluvium and eolian sands under lain by petrocalcic soils and hard caliche. The New Mexico State Engineer web site indicates the nearest ground water data to be in S34-T23S-R30E. The ground water in Section 34 is reported to be a depth of 440' below ground surface (bgs). The referenced groundwater data is presented in Appendix I.

ENVIRONMENTAL CONSULTING
ENGINEERING
DRILLING
CONSTRUCTION
SPILL MANAGEMENT

The ranking for this site is 0 based on the as following:

Depth to ground water >100'
Wellhead Protection Area >1000'
Distance to surface water body >1000'

Toll Free: 866.742.0742 www.talonlpe.com

GENERAL CONTRACTING

Incident Description

On October 3, 2013 a flow line was found to be leaking. The leak occurred on a steep incline in the middle of the pasture, releasing 2 barrels of produced water and 8 barrels of oil. The line was shut in and a vacuum truck was immediately called to the location. The poly line was subsequently replaced. The vacuum truck recovered 0.5 barrels of produced water and 0.5 barrels of oil.

Remedial Actions Taken

On February 22, 2014 Talon personnel mobilized to the site to begin excavation of the impacted area in accordance with the New Mexico Oil Conservation Division (NMOCD) approved work plan. The impacted area of the release was excavated to a depth of 3-feet below land surface. The impacted soil was transported to Lea Land, LLC. The bottom and sidewalls of the excavation were tested for chlorides using the field titration method to guide the excavation process. The excavated area was backfilled back to grade using new material transported from a local borrow pit and was contoured to match the surrounding location. The area was seeded on February 21, 2014 using BLM seed mix #2. The seeding label is attached.

Closure

On behalf of Devon Energy Corporation, we respectfully request that no further actions be required and that closure with respect to this release be granted.

If we can provide additional information or be of further assistance please contact our office at 575.746.8768.

Respectfully submitted,

TALON/LPE


Kimberly M. Wilson

Project Manager

David J. Adkins

District Manager

SITE MAP



APPENDIX I GROUNDWATER DATA



New Mexico Office of the State Engineer Water Column/Average Depth to Water

(A CLW###### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.) (R=POD has been replaced, O=orphaned,

C=the file is closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

(In feet)

	POD			n nga garangga bilan			provide nden Braza, a sammos ⁱ nin e Sautemp				
	Sub-	QQ	Q						Depth	Depth	Water
POD Number	Code basin Count	y 64 16	4 Sec	Tws	Rng	X_	Y	Distance	Well	Water	Column
C 02095	ED	2	3 34	238	30E	606337	3569759* 🥵	3623	554	440	114
C 02780	ED	2 3	2 23	248	30E	608535	3563857* 🚱	3907	505		

Average Depth to Water:

440 feet

Minimum Depth: 440 feet

Maximum Depth: 440 feet

Record Count: 2

UTMNAD83 Radius Search (in meters):

Easting (X): 609310

Northing (Y): 3567687

Radius: 4000

SEEDING LABEL

Curtis & Curtis, Inc. 4500 North Prince Clovis, NM 88130 Phone: (575) 762-4759 2/27/4

Taton / LPEALTD

1 Acre BLM # 2! Broadcast Rate

1 - 1 Acre Bag @ 30.47 Bulk Pounds Each
Job: Devon * Black Jack 1 Fed #4H

30-015-37065

N-1-24-30

700 79 40 76.01

!			-					. •
ŀ	· · ·					_	•	\sim
i	Lnt# M-11999					Germ &	Test t	Total PLS
	Yearra	Origin	ı Pu <u>ritý</u>	Germ	Dormant	Dormant	<u>Date</u>	<u>Paunds</u>
٠.	<u>Item</u> Sand Dropseed	Colora		22.00%	74.00%	96.00%	12/13	4.00
ì	VNS Little Bluestem	Nebras		87.00%	9.00%	96.00%	11/13	6.00 '
À	Camper Coreopsis	Orego	n 15.82%	83.00%	0.00%	83.00%	11/13	4.00
	Plains Sidepats Grama	Texa	s 21.63% r	13.00%	78.00%	91.00%	09/13	, 6.00 *
1	 Vaughn Indian Ricegrass 	Colors	do _14.12%	3.00%	90.00%	93.00%	12/13	4.00
	Paloma					-		
•	Other Crop:	··0.00%	There Are 1 Ba	gFor This	Mix *	'Total B	ls: 30 🕳	
•	Weed Seed:	0.04%	This Bag Weigh	ıs 3 0.47 B	uk Pounds	***		
•	Inert Matter	14.21%	Use This Bag F	or 1 Acres	•		•	
			terate to the	· • • • • • • • • • • • • • • • • • • •	ا با			•

٠

(

•

.

.

•

 \mathcal{L}

FINAL C-141