NM OIL CONSERVATION

ARTESIA DISTRICT

District J
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
700 Rio Brazos Road, Aztec, NM 87410
rict IV
10 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources MAY 1 7 2016

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Spinite Roperto appropriate District Office in Secondance with 19.15.29 NMAC.

Name of Company: COG Operating LLC 200/3 Contact: Robert McNeill
Name of Company: COG Operating LLC Address: 600 West Illinois Avenue, Midland TX 79701 Telephone No. 432-683-7443 Facility Name: NERVOUS HORZ COM #002H Facility Type: Tank Battery Surface Owner: State Mineral Owner: API No. 30-015-37143 LOCATION OF RELEASE Unit Letter Section Township Range 188 31E S12
Address: 600 West Illinois Avenue, Midland TX 79701 Telephone No. 432-683-7443 Facility Name: NERVOUS HORZ COM #002H Facility Type: Tank Battery Surface Owner: State Mineral Owner: API No. 30-015-37143 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the A 26 188 31E 330 North/South Line Feet from the 530 East East Latitude 32.7104416 Longitude 103.8161163 NATURE OF RELEASE Type of Release: Yolume of Release: 22bbts of produced water 12bbts of produced water Source of Release: Date and Hour of Occurrence: 05-09-2016 11:30am 05-09-2016 11:30am Was Immediate Notice Given? Yes No Not Required By Whom? Date and Hour: Was a Watercourse Reached? Yes No Not Required Describe Cause of Problem and Remedial Action Taken.* A 3" steel pipeline failed due to corrosion. Replaced the bad section of pipe with a new joint of 3" steel line. Describe Area Affected and Cleanup Action Taken.* The release covered a 50' X 20' area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
Surface Owner: State Mineral Owner: API No. 30-015-37143 LOCATION OF RELEASE Unit Letter Section Township Range 18S 31E Feet from the 2330 North/South Line 530 East East Latitude 32.7104416 Longitude 103.8161163 NATURE OF RELEASE Type of Release: Volume of Release: 22bbls of produced water Source of Release: 22bbls of produced water 95-09-2016 11:30am 05-09-2016 11:3
Unit Letter Section Township 18S 31E Set from the North/South Line Feet from the East/West Line County East Latitude 32.7104416 Longitude 103.8161163
Unit Letter A Section 18S Range 31E Sect from the 330 North South Line 530 East County East Latitude 32.7104416 Longitude 103.8161163 NATURE OF RELEASE Type of Release:
Unit Letter A Section 18S Range 31E Section the 330 North South Line 530 East County East Latitude 32.7104416 Longitude 103.8161163 NATURE OF RELEASE Type of Release: Volume of Release: 22bbls of produced water 12bbls of produced Water 22bbls of produced Water Source of Release: 3" steel pipeline Pes No No Not Required Pes Not Not Not Pes Not Not Pes Not Not Pes Not Not Pes Not Not Not Pes Not Not Not Pes Not
Latitude 32.7104416 Longitude 103.8161163 NATURE OF RELEASE Type of Release: Volume of Release: 22bbls of produced water 12bbls of produced Source of Release: 22bbls of produced water 12bbls of produced 11:30am 12bbls of produced 1
Type of Release: Produced Water Source of Release: 3' steel pipeline Was Immediate Notice Given? Was a Watercourse Reached? Tyes No Not Required By Whom? Date and Hour: Was a Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Action Taken. A 3" steel pipeline failed due to corrosion. Replaced the bad section of pipe with a new joint of 3" steel line. Describe Area Affected and Cleanup Action Taken. The release covered a 50' X 20' area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
Type of Release: Produced Water Source of Release: 3" steel pipeline Was Immediate Notice Given? Was a Watercourse Reached? Was a Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Action Taken. A 3" steel pipeline failed due to corrosion. Replaced the bad section of pipe with a new joint of 3" steel line. Volume Recovered: 12bbls of produced water 12bbls of produced 12bbls of produced water 12bbls of produced water 12bbls of produced 12bbls of produced water 12bbls of produced 11:30am 14 YES, To Whom? Date and Hour: 14 YES, Volume Impacting the Watercourse. 15 YES, Volume Impacting the Watercourse. Describe Cause of Problem and Remedial Action Taken. A 3" steel pipeline failed due to corrosion. Replaced the bad section of pipe with a new joint of 3" steel line. Describe Area Affected and Cleanup Action Taken. The release covered a 50' X 20' area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
Produced Water Source of Release: 3" steel pipeline Was Immediate Notice Given? Yes No Not Required By Whom? Yes No Not Required By Whom? Yes No Not Required By Watercourse Reached? Yes No Not Required TYPES, Volume Impacting the Watercourse. If YES, Volume Impacting the Watercourse. Produced water 12bbls of produced water 12bbls of produced water 05-09-2016 11:30am 05-09-2016 1
Source of Release: 3" steel pipeline Date and Hour of Occurrence: 05-09-2016 11:30am 05-
3" steel pipeline Was Immediate Notice Given? Yes No Not Required By Whom? Date and Hour: Was a Watercourse Reached? Yes No Not Required If YES, To Whom? If YES, Volume Impacting the Watercourse. Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Action Taken. A 3" steel pipeline failed due to corrosion. Replaced the bad section of pipe with a new joint of 3" steel line. Describe Area Affected and Cleanup Action Taken. The release covered a 50' X 20' area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
Was Immediate Notice Given? Yes No Not Required By Whom? Date and Hour: Was a Watercourse Reached? Yes No No Not Required If YES, To Whom? If YES, Volume Impacting the Watercourse. Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Action Taken. A 3" steel pipeline failed due to corrosion. Replaced the bad section of pipe with a new joint of 3" steel line. Describe Area Affected and Cleanup Action Taken. The release covered a 50' X 20' area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
By Whom? Was a Watercourse Reached? Yes No Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Action Taken. A 3" steel pipeline failed due to corrosion. Replaced the bad section of pipe with a new joint of 3" steel line. Describe Area Affected and Cleanup Action Taken. The release covered a 50' X 20' area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
Was a Watercourse Reached? Yes No No Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Action Taken. A 3" steel pipeline failed due to corrosion. Replaced the bad section of pipe with a new joint of 3" steel line. Describe Area Affected and Cleanup Action Taken. The release covered a 50' X 20' area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
☐ Yes ☒ No ☐ Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* A 3" steel pipeline failed due to corrosion. Replaced the bad section of pipe with a new joint of 3" steel line. Describe Area Affected and Cleanup Action Taken.* The release covered a 50' X 20' area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
Describe Cause of Problem and Remedial Action Taken.* A 3" steel pipeline failed due to corrosion. Replaced the bad section of pipe with a new joint of 3" steel line. Describe Area Affected and Cleanup Action Taken.* The release covered a 50' X 20' area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
Describe Cause of Problem and Remedial Action Taken. A 3" steel pipeline failed due to corrosion. Replaced the bad section of pipe with a new joint of 3" steel line. Describe Area Affected and Cleanup Action Taken. The release covered a 50' X 20' area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
A 3" steel pipeline failed due to corrosion. Replaced the bad section of pipe with a new joint of 3" steel line. Describe Area Affected and Cleanup Action Taken.* The release covered a 50' X 20' area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
A 3" steel pipeline failed due to corrosion. Replaced the bad section of pipe with a new joint of 3" steel line. Describe Area Affected and Cleanup Action Taken.* The release covered a 50' X 20' area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
Describe Area Affected and Cleanup Action Taken.* The release covered a 50' X 20' area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
The release covered a 50° X 20° area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
The release covered a 50° X 20° area inside the tank battery. All free fluids were recovered; an initial cleanup was performed and the facility was put
into service. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work to the NMOCD for approval prior to any significant remediation work.
To the state producting inglitted the content of th
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules an
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endange
public health or the environment. The acceptance of a C-14t report by the NMOCD marked as "Final Report" does not relieve the operator of liabili should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human he
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other
federal, state, or local laws and/or regulations.
OIL CONSERVATION DIVISION
Signature: Valet Amen
Printed Name: Robert Grubbs Jr. Approved by Environmental Specialist:
land the second of the second
Title: Senior Environmental Coordinator Approval Date: 5 8 6 Expiration Date: NA
F-mail Address: rapuble@conche.com Conditions of Approval:
E-mail Address: rgrubbs@concho.com Conditions of Approval:
F. mail Address: rapuble@conche.com Conditions of Approval:

Bratcher, Mike, EMNRD

From:

Robert Grubbs < RGrubbs@concho.com>

Sent:

Tuesday, May 17, 2016 12:25 PM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; 'agroves@slo.state.nm.us';

'dvstrang@slo.state.nm.us'; Martin, Ed; Naranjo, Mark M.

Subject:

(C-141 Initial) Nervous Horz Com #002H (30-015-37143)

Attachments:

05-09-2016 Nervous Horz Com #002H (TB).pdf


MR. BRATCHER / MS. GROVES,

ATTACHED IS A C-141 INITIAL FOR YOUR CONSIDERATION. IF YOU HAVE ANY ADDITIONAL QUESTIONS PLEASE FEEL FREE TO CONTACT ME.

THANK YOU,

ROBERT GRUBBS JR.
SR. ENVIRONMENTAL COORDINATOR
432.683.7443 (MAIN)
432.818.2369 (DIRECT)
432.661.6601 (CELL)
432.221.0892 (FAX)
RGRUBBS@CONCHO.COM
MAILING ADDRESS:
ONE CONCHO CENTER
600 W. ILLINOIS AVENUE
MIDLAND, TEXAS 79701

CONFIDENTIALITY NOTICE: THE INFORMATION IN THIS EMAIL MAY BE CONFIDENTIAL AND/OR PRIVILEGED. IF YOU ARE NOT THE INTENDED RECIPIENT OR AN AUTHORIZED REPRESENTATIVE OF THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY REVIEW, DISSEMINATION OR COPYING OF THIS EMAIL AND ITS ATTACHMENTS, IF ANY, OR THE INFORMATION HEREIN, IS PROHIBITED. IF YOU RECEIVED THIS EMAIL IN ERROR, PLEASE IMMEDIATELY NOTIFY THE SENDER BY RETURN EMAIL AND DELETE THIS EMAIL FROM YOUR SYSTEM. THANK YOU.



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.