	District 1 1625 N. French Dr., Hobbs, NM 88240 State	of New Mexico	Form C-141
<b>E</b>	District II Energy Minera 1301 W. Grand Avenue, Artesia, NM 88210	ls and Natural Resources	Revised October 10, 2003
87 N	District III 1000 Rio Brazos Road, Aztec, NM 87410	ervation Division	Submit 2 Copies to appropriate District Office in accordance
GD	1220 C. C. C	uth St. Francis Dr. Fe, NM 87505	with Rule 116 on back side of form
	Release Notification and Corrective Action		
يوني ا	<b>OPERATOR</b> Initial Report S Final Report		
	Name of Company COG Operating LLC	Contact Pat Ellis	
	Address 550 W. Texas, Suite 100, Midland, TX 79701 Facility Name Big George State Tank Battery	Telephone No.432-230-0077Facility TypeTank Battery	
ß	Surface Owner State Mineral Owne		Lease No. (API#) 30-015-26340
	LOCATION OF RELEASE 30 -015 - 28759		
24.0			West Line County
	J 12 17S 28E		Eddy County, NM
	Latitude N 32 50.85	2 Longitude <u>W 104 07.600</u>	Eddy County, NW
群 5-	NATURE OF RELEASE		
(F.	Type of Release Produced water	Volume of Release 8 bbis	Volume Recovered 7 bbls
	Source of Release 4" nipple on discharge side of water pump	Date and Hour of Occurrence 03/12/2012	Date and Hour of Discovery 03/12/2012@ 6:30 a.m.
	Was Immediate Notice Given?	If YES, To Whom?	05/12/2012(# 6:50 8.10.
	Yes X No X Not Require		
	By Whom? Was a Watercourse Reached?	Date and Hour If YES, Volume Impacting the Wat	orcourse
120	Yas a Watercourse reaction	n i co, volune impacting ne wat	
	If a Watercourse was Impacted, Describe Fully.*	1	
3			
D			
	Describe Cause of Problem and Remedial Action Taken.*		
<b>C</b> . <b>3</b>	The 1/2" nipple on the discharge side of the water pump failed due to vibration and corrosion. The 1/2" nipple has been replaced.		
	Describe Area Affected and Cleanup Action Taken.*		
1.12 	Initially 8 bbls of produced water were released from the water pump and	I we were able to recover. 7 bbls with a v	vacuum truck. The spill area measured
	roughly 10° x 60' inside the tank battery with an area of overspray measu were picked up and the overspray area was scraped with a backhoe. The	ring roughly 30' x 50' on location outsi	ide of the tank battery. All free liquids
Ψ.	allow the approved remediation plan for the spill of 07/27/2011 to handle this spill as well. The impacted soil was removed, a clay liner installed, and the		
	site backfilled.		
	I hereby certify that the information given above is true and complete to t regulations all operators are required to report and/or file certain release n	he best of my knowledge and understan otifications and perform corrective action	d that pursuant to NMOCD rules and ons for releases which may endanger
53	public health or the environment. The acceptance of a C-141 report by th should their operations have failed to adequately investigate and remediat	e NMOCD marked as "Final Report" du	pes not relieve the operator of liability
	or the environment. In addition, NMOCD acceptance of a C-141 report d	oes not relieve the operator of responsit	bility for compliance with any other
	federal, state, or local laws and/or regulations.	OIL CONSERV	ATION DIVISION
	Signature:		
		Approved by District Supervisor: 74	ceptar For Hecond
8	Printed Name: Joshf Russo		()),,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
()	Title: HSE Coordinator	Approval Date: E	xpiration Date:
_	E-mail Address: jrusso@conchoresources.com	Conditions of Approval:	Attached
		ome Contamination	eft in plane due
¥ ال	Attach Additional Sheets If Necessary by equipment. Defen find clean p		
<b>0</b> 33121	unit site abandonment DDD 1000		
đ			akr-10/7