

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 23 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1017549348

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company 14744	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Bebop 36 W/LMD State #2H	Facility Type: Producing Oil Well
Surface Owner: State	Mineral Owner:
API No. 30-015-43320	

LOCATION OF RELEASE

Unit Letter M	Section 36	Township 25S	Range 31E	Feet from the 185'	North/South Line South	Feet from the 450'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.07988951 Longitude -103.73832293

NATURE OF RELEASE

Type of Release: Oil/produced water	Volume of Release: approximately 10-15 bbls.	Volume Recovered: 10 bbls
Source of Release: Water tank	Date and Hour of Occurrence 6-18-16	Date and Hour of Discovery 6-18-16 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson	
By Whom? Zack Thomas	Date and Hour 6-18-16 12:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Choke washed out on well head sending sand to separator causing dump to hang open. FWKO over pressured and in turn sent gas to production tanks causing damage to a water tank. A hole in the flowline also developed due to sand.

Describe Area Affected and Cleanup Action Taken.*

Affected area- Well pad surface around well head. Pasture west of location was hit with light spray. Vacuum trucks were used to recover 5 bbls of produced water and 5 bbls oil. Final remediation will be conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Z. Thomas</i>	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Rep.	Approval Date: 7/23/16	Expiration Date: N/A
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:	
Date: 6-20-16	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 7/27/16	

Attached ☐
2RP 3754

Patterson, Heather, EMNRD

From: Zack Thomas <zthomas@mewbourne.com>
Sent: Thursday, June 23, 2016 7:46 AM
To: Patterson, Heather, EMNRD; agroves@slo.state.nm.us; Bratcher, Mike, EMNRD
Subject: Bebop 36 W1MD State #2H
Attachments: C141- Bebop 36 W1MD State #2H (6-18-16) MOC signed initial.pdf; IMG_0373.JPG; IMG_0374.JPG

Heather, Mike, Amber

Attached is the C141 for the release I called and left a message about on Saturday June 18th. We have already Micro Blazed the pasture area. A vacuum truck was close by when this happened and got the standing fluid on the pad recovered very quickly. I don't believe there is any kind of depth to the contamination due to the compactness of the caliche on the pad, and the recovery time of the vac truck. The backhoe was having trouble digging on the pad because it was so hard. According the Chevron Texaco Eddy Co. Depth to Ground Water Map, ground water is 300 plus feet below surface. Due to these facts I don't believe any samples are necessary. I've also attached a picture of the pad after we scraped up a load from it. If there are any questions or concerns please let me know.



Zack Thomas
Environmental Rep.
Mewbourne Oil Company
PO Box 5270
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252
(575) 602-2188
Email: zthomas@mewbourne.com



MEWBOURNE
OIL COMPANY