## NM OIL CONSERVATION

ARTESIA DISTRICT

District 1
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

JUL 07 2016

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in RECEIVED lance with 19.15.29 NMAC.

Release Notification and Corrective Action

Name of Company: BOPCO, L.P.   AUDITS 7   Contact: Bradley Blevins	NAB1619044684	OPERATOR		
Source of Release: Heater Treater Gasket		Contact: Bradley Blevins		
Surface Owner; Federal   Mineral Owner; Federal   API No. 30-015-39810				
Unit Letter   Section   Township   Range   Feet from the   2590   North/South Line   Feet from the   1670   East/West Line   Eddy   Eddy      Latitude: 32.242954   Longitude: 103.885796	Facility Name: PLU 320 Battery	Facility Type: Exploration and Production		
Unit Letter   Section   Township   Range   24S   30E   2590   North/South Line   1670   East/West Line   1670   East/West Line   East/West Line   East/West Line   East/West Line   East/West Line   Eddy   East/West Line   East/West Line   East/West Line   East/West Line   East/West Line   East/West Line   Eddy   East/West Line   East/West Line   East/West Line   East/West Line   East/West Line   Eddy   East/West Line   East/West Line   Eddy   Eddy	Surface Owner: Federal Mineral Owner: Federal API No. 30-015-39810			
Latitude: 32.242954 Longitude: 103.885796  NATURE OF RELEASE  Type of Release: Crude Oil/ Produced Water  Type of Release: Crude Oil/ Produced Water  Type of Release: Crude Oil/ Produced Water  Type of Release: Heater Treater Gasket  Source of Release: Heater Treater Gasket  Date and Hour of Occurrence: Date and Hour of Discovery 7-6-16 @ 8.00am  Was Immediate Notice Given?  Wes No Not Required  Types Source Reacher Oct. Heather Patterson OCD, Shelly Tucker BLM  By Whom? Bradley Blevins  Date and Hour: 7-6-16 @ 11:13am email  If YES, Volume Impacting the Watercourse.  If a Watercourse was Impacted, Describe Fully.*  Describe Cause of Problem and Remedial Action Taken.*  BOPCO E11S was notified of a release that occurred when the gasket failed on the production heater treater. Majority of the fluid was contained within an earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.  Describe Area Affected and Clearup Action Taken.*  Majority of the affected area was within the earth herm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.	LOCATION OF RELEASE			
Type of Release: Crude Oil/ Produced Water    Volume of Release:   111 barrels oil and 35 barrels   80 Barrels Oil and 15 Barrels Produced Water   20 Barrels Oil and 15 Barrels Produced   20 Barrels Oil and 15 Barrels Oil and 15 Barrels Produced   20 Barrels Oil and 15 Barrels Produced   20 Barrels Oil and 15 Barrels Produced   20 Barrels Oil and 15 Barrels Oi	, , , , , , , , , , , , , , , , , , , ,			
Type of Release: Crude Oil/ Produced Water    Volume of Release:   Volume Recovered: 80 Barrels Oil and 15 Barrels Produced Water   Water	Latitude: 32.242954 Longitude: 103.885796			
Source of Release: Heater Treater Gasket  Source of Release: Heater Treater Gasket  Date and Hour of Occurrence: 7-6-16 @ 8:00am  Pyes No Not Required  By Whom? Bradley Blevins  Date and Hour: 7-6-16 @ 11:13am email  By Whom? Bradley Blevins  Date and Hour: 7-6-16 @ 11:13am email  If YES, To Whom?  Was a Watercourse Reached?  If a Watercourse was Impacted, Describe Fully.*  Describe Cause of Problem and Remedial Action Taken.*  BOPCO EHS was notified of a release that occurred when the gasket failed on the production heater treater. Majority of the fluid was contained within an earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger				
Source of Release: Heater Treater Gasket  Source of Release: Heater Treater Gasket  Date and Hour of Occurrence: 7-6-16 @ 8:00am 7-6-16 @ 8:45am  Treater Governor Paralley Blevins  Was a Watercourse Reached?  The was a Watercourse Reached?  The was a Watercourse Reached?  The was a Watercourse was Impacted, Describe Fully.*  Describe Cause of Problem and Remedial Action Taken.*  BOPCO EHS was notified of a release that occurred when the gasket failed on the production heater treater. Majority of the fluid was contained within an earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.  Describe Area Affected and Cleanup Action Taken.*  Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	Type of Release: Crude Oil/ Produced Water			
Source of Release: Heater Treater Gasket  Was Immediate Notice Given?  Was a Watercourse Reached?  Was a Watercourse Reached?  Was a Watercourse Reached?  Was a Watercourse was Impacted, Describe Fully.  Describe Cause of Problem and Remedial Action Taken.  Describe Cause of Problem and Remedial Action Taken.  BOPCO EHS was notified of a release that occurred when the gasket failed on the production heater treater. Majority of the fluid was contained within an earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.  Describe Area Affected and Cleanup Action Taken.  Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger			' ' ' ' ' ' '   ' ' '   ' ' ' '   ' ' '   ' '   ' ' ' '   ' ' ' '   ' ' ' '   ' ' ' '   ' ' ' '   ' ' ' ' '   ' ' ' ' '   ' ' ' ' ' ' '   ' ' ' ' ' '   '	
Was Immediate Notice Given?    Yes   No   Not Required   If YES, To Whom?   Mike Bratcher OCD, Heather Patterson OCD, Shelly Tucker BLM	Source of Release: Heater Treater Gasket	Date and Hour of Occurrence:		
By Whom? Bradley Blevins  Date and Hour: 7-6-16 @ 11:13am email  Was a Watercourse Reached?  If YES, Volume Impacting the Watercourse.  Describe Cause of Problem and Remedial Action Taken.*  BOPCO EHS was notified of a release that occurred when the gasket failed on the production heater treater. Majority of the fluid was contained within an earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.  Describe Area Affected and Cleanup Action Taken.*  Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	Was Immediate Nation Civers		7-6-16 @ 8:45am	
Was a Watercourse Reached?  Yes No  If YES, Volume Impacting the Watercourse.  If YES, Volume Impacting the Watercourse.  Describe Cause of Problem and Remedial Action Taken.*  BOPCO EHS was notified of a release that occurred when the gasket failed on the production heater treater. Majority of the fluid was contained within an earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.  Describe Area Affected and Cleanup Action Taken.*  Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger				
If a Watercourse was Impacted, Describe Fully.*  Describe Cause of Problem and Remedial Action Taken.*  BOPCO EHS was notified of a release that occurred when the gasket failed on the production heater treater. Majority of the fluid was contained within an earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.  Describe Area Affected and Cleanup Action Taken.*  Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger				
Describe Cause of Problem and Remedial Action Taken.*  BOPCO EHS was notified of a release that occurred when the gasket failed on the production heater treater. Majority of the fluid was contained within an earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.  Describe Area Affected and Cleanup Action Taken.*  Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger		If YES, Volume Impacting the Wa	dercourse.	
Describe Cause of Problem and Remedial Action Taken.*  BOPCO EHS was notified of a release that occurred when the gasket failed on the production heater treater. Majority of the fluid was contained within an earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.  Describe Area Affected and Cleanup Action Taken.*  Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	If a Watercourse was Impacted Describe Fully *			
BOPCO EHS was notified of a release that occurred when the gasket failed on the production heater treater. Majority of the fluid was contained within an earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.  Describe Area Affected and Cleanup Action Taken.*  Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	The state of the s		<u>,</u>	
BOPCO EHS was notified of a release that occurred when the gasket failed on the production heater treater. Majority of the fluid was contained within an earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.  Describe Area Affected and Cleanup Action Taken.*  Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger				
BOPCO EHS was notified of a release that occurred when the gasket failed on the production heater treater. Majority of the fluid was contained within an earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.  Describe Area Affected and Cleanup Action Taken.*  Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger				
earth berm with the exception of a light spray to the location. A vacuum truck was called to the location to recover the standing fluid. A response crew was sent to the location to conduct an initial scrape of the well pad.  Describe Area Affected and Cleanup Action Taken.*  Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger				
Describe Area Affected and Cleanup Action Taken.*  Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	BOPCO EHS was notified of a release that occurred when the gasket fail	led on the production heater treater. Me	ajority of the fluid was contained within an	
Describe Area Affected and Cleanup Action Taken.*  Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	sent to the location to conduct an initial scrape of the well pad.	nuck was called to the location to reco	over the standing fluid. A response crew was	
Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	•			
Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger				
Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	Describe Area Affected and Cleanup Action Taken.*			
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	Majority of the affected area was within the earth berm that surrounds the production equipment; the standing fluid was recovered by a vacuum truck. A			
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	Light spray to the location was observed; an initial response crew conducted a scrape of the well pad.			
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger				
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	I hereby certify that the information given above in true and consolidate to the heat of my land and a land a land at the land			
regulations and operations are required to report allows. The certain foldase notifications and perform corrective actions for releases which may endanger				
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability	public health or the environment. The acceptance of a C-141 report by the	he NMOCD marked as "Final Report"	does not relieve the operator of liability	
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health				
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.				
OIL CONSERVATION DIVISION		OIL CONSER'	VATION DIVISION	
	Signature: 3 18 30 ·		0/1/	
Signature: Signed By Mily Denomina Approved by Environmental Specialist:	Signature. Charley Bloom	Signed By	Mile Demuce	
Printed Name: Bradley Blevins Approved by Environmental Specialist:	Printed Name: Bradley Blevins	Approved by Environmental Speciali	SI:	
Title: Assistant Remediation Foreman Approval Date: 7810 Expiration Date: NIA	Title: Assistant Remediation Foreman	Approval Date: 1810	Expiration Date: NIA	
E-mail Address: bblevins@basspet.com  Conditions of Approval  Conditions of Conditions				
Agriculation per O.C.D. Rules & Guipamaneo	P / /	SUBMIT REMEDIATION P	ROPOSAL NO	
Date: 7-7-76 Phone: 432-214-3704 SUBMIT REMEDIATION ROPUSALING  LATER THAN:				

## Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>

**Sent:** Thursday, July 07, 2016 10:23 AM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Tucker, Shelly (stucker@blm.gov)

Cc:Blevins, BradleySubject:PLU 320H Battery

Attachments: Initial C-141 PLU 320 7-6-16 HT Gasket.pdf

All,

Please find the attached initial C-141 for the release that occurred at the PLU 320 Battery. If you have any questions please let me know. Thanks

Brad Blevins BOPCO, LP 522 W. Mermod, Suite 704 Carlsbad, NM 88220 Office-575-887-7329 Cell-1-432-214-3704 bblevins@basspet.com

## Bratcher, Mike, EMNRD

From:

Blevins, Bradley <BBlevins@BassPet.Com>

Sent:

Wednesday, July 06, 2016 11:13 AM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Shelly Tucker

Cc:

Blevins, Bradley

Subject:

PLU 320 Heater Treater Release

All,

Bopco EHS was notified this morning at 8am of a release that occurred when the gasket on production heater failed. Oil and PW was released into the earthen berm and a light mist sprayed the location. Vacuum truck is on location recovering the fluid and a cleanup crew will conduct an initial scrape of the well pad. I will follow up with more detail and C-141 ASAP. Thanks

Sent from my iPhone

## Bratcher, Mike, EMNRD

From:

Tucker, Shelly <stucker@blm.gov>

Sent:

Wednesday, July 06, 2016 11:20 AM

To:

Blevins, Bradley

Cc:

Bratcher, Mike, EMNRD: Patterson, Heather, EMNRD

Subject:

Re: PLU 320 Heater Treater Release

Thank you for the notification.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J'Tucker

Environmental Protection Specialist Bureau of Land Management

620 E. Greene St Carlsbad, NM 88220

575.234.5905 - Direct 575.361.0084 - *C*ellular

stucker@blm.gov



The <u>BLM acceptance/approval does not</u> relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

<u>Confidentiality Warning:</u> This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Wed, Jul 6, 2016 at 11:13 AM, Blevins, Bradley < BBlevins@basspet.com > wrote:

All,

Bopco EHS was notified this morning at 8am of a release that occurred when the gasket on production heater failed. Oil and PW was released into the earthen berm and a light mist sprayed the location. Vacuum truck is