District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 RECEIVE Propies to appropriate District Office in accordance with Rule 116 on back side of form

## Release Notification and Corrective Action

						<b>OPERAT</b>	OR		Initia	al Report		Final Report
Name of Company Southern Union Gas Services					46	Contact Curt Stanley						
						Telephone No. 575-390-7595						
Facility Name California B (4-10)						Facility Type Natural Gas Pipeline						
Surface Owner Jay Anthony Mineral Owner						Lease No. 30-025-38822						
				LOCAT	CIO	N OF REI	EASE					
Unit Letter	Section	Township	Range			/South Line	Feet from the	East/V	Vest Line	County		15 5 7 7 1 3
"M"	5	26S	36E							Lea		
Latitude N 32 degrees 03.897' Longitude W 103 degrees 17.359' NATURE OF RELEASE												
Type of Release Crude Oil, Produced Water and Natural Gas							Volume of Release 154 BBLS Volume Recovered 147 BBLS					
Source of Release 16-Inch Steel Pipeline							Date and Hour of Occurrence Date and Hour of Discovery					
						April 14, 2011, approx. 0100 hrs   April 14, 2010, approximately 0200 hrs						
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Geoffrey Leking, NMOCD Hobbs District Office						
By Whom? Curt Stanley						Date and Hour April 14, 2011, 1113 hrs						
Was a Watercourse Reached?							lume Impacting t			7.18		172
☐ Yes ☒ No												
Describe Cause of Problem and Remedial Action Taken.*  The release occurred during pipeline pigging activities. On discovery of the release, the pipeline was partially blown down to stop the further advancement of the pig. A vacuum truck was used to recover liquids previously released to the ground. The vacuum truck was also used to recover liquids as they were released from the pipeline. When the volume of liquids released from the pipeline subsided, the pipeline was fitted with a temporary clamp to mitigate the release. The cause of the release was attributed to external corrosion. The volume of natural gas released, is to be determined.  Describe Area Affected and Cleanup Action Taken.*												
	ected by the	release meas	ures appro	eximately 3,440 sq f	t, the	largest area be	eing a pipeline ro	ad. Follo	owing repa	ir of the pipe	eline, t	ne release
regulations al public health should their o	Il operators or the envi operations h nment. In a	are required to ronment. The lave failed to addition, NMC	o report and acceptant acc	e is true and comple nd/or file certain rele ce of a C-141 report investigate and rer otance of a C-141 re	by th	notifications ar ne NMOCD ma te contaminati	nd perform correct arked as "Final R on that pose a thr	ctive acti eport" d reat to gr	ons for rele oes not reli	eases which ieve the ope r, surface wa	may en rator of ater, hu	ndanger f liability man health
Signature: Cut D. Janly						OIL CONSERVATION DIVISION  ENV ENCHIVEER:						
Printed Name: Curt D. Stanley						Approved by-	District Supervis	Thorstony Liking				
Title: EHS Compliance Specialist						Approval Dat	e: 04/15 /11	5     Expiration Date: 66 14 1				
						Conditions of Approval: SUBMIT FINAL  Attached   187-04-01-26				2698		
		ets If Necess		-370-1373						IMA		

PGRL 1313432380











