ARTESIA DISTRICT District I 1625 N. French Dr., Hobbs, NM 88240 State of New Mexico NUV 2 9 2017 Energy Minerals and Natural Resources District II Revised April 3, 2017 811 S. First St., Artesia, NM 88210 District III **Oil Conservation Division** 1000 Rio Brazos Road, Aztec, NM 87410 1220 South St. Francis Dr. District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505

## Form C-141

Superceptop appropriate District Office in accordance with 19.15.29 NMAC.

## **Amended Report Release Notification and Corrective Action**

Name of Company Agua Sucia LLC (AS) #2105779	OPERATOR	Initial Report Final Report
Name of Company Agua Sucia LLC (AS) #2105774	Contact Wayne Price-Price LLC	wayneprice77@earthlink.net
Address 10026-A S. Mingo RD #290 Tulsa, OK 74133	Telephone No. 505-715-2809	
Facility Name ESU #58	Facility Type Injection Well for	Water Flood

Surface Owner BLM

Mineral Owner BLM

| API No. 30-015-27951

## LOCATION OF RELEASE

Unit Letter K	Section 35	Township 18s	Range 31e	Feet from the 1575	North/South Line FSL	Feet from the 2200	East/West Line FWL	County Eddy

Latitude\_32.701083 Longitude\_-103.841542\_NAD83

NATURE OF RELEASE							
Type of Release: Water flood Injection "Recycled" water with trace of oil and minor solids.	Volume of Release: Approximately 20 bbls Estimated using orifice calculator	Volume Recovered: Approximately 15 bbls liquid contained in saturated soils- calculated.					
Source of Release: Inlet Injection Line on Wellhead	Date and Hour of Occurrence: Early Morning Hours of Nov 6, 2017	Date and Hour of Discovery: Anonymous Call-in from Hunter- @ Approximately 6:40 am- Agua Sucia on site at 7:20 AM					
Was Immediate Notice Given? XX Yes* No Not Required *By default OCD and Agua Sucia were notified.	If YES, To Whom? C Weaver-OCD and Louis Edgett-Agua Sucia- BLM on site same day.						
By Whom? Anonymous Call-in from Hunter- would not give name	Date and Hour: As noted above						
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse. NA						
If a Watercourse was Impacted, Describe Fully.* No Shallow Groundwater in Area. Lease sets on dune sand mantle under laid by several hundred feet of impermeable Triassic Red Beds. No beneficial groundwater is found in this area.							
groundwater is found in this area.							

Describe Cause of Problem and Remedial Action Taken.\* Nipple cracked on injection well inlet line. (See Attached Photo)- Agua Sucia personnel stopped the release early on the Morning of Nov 6, 2017. AS is in the process of redesigning the piping on the wellheads to prevent future occurrence.

2RP-4505

## NM OIL CONSERVATION