State of New Mexico NM OIL CONSERVATION

ARTESIA DISTRICT FEB 09 2018

Form C-141 Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

			Rela	ease Notific	ation	and Co	rrective A	ction				
nAzia		100 K	KUK		anoi	OPERAT				1.5		15
								\boxtimes	Initia	l Report		nal Report
Address 6488 Seven Rivers Hwy Artesia, NM 88210						Contact Wesley Ryan Telephone No. 575-390-5436						
Facility Name Aquila 22 Federal Com 1H						Facility Type Oil						
Surface Owner Federal Mineral Owner												
Surface Ow	nei reuera	<u>.</u>	API No. 50-013-40027									
						NOF RE	LEASE					
Unit Letter A	Section 22	Township 19S	Range 31E	Feet from the	North/	South Line	Feet from the	East/Wes	t Line	County	Eddy	
Latitude_32.650686, 32.650963 & 32.650631 Longitude_103.849117, 103.848818 & 103.847616_ NAD83												
				NAT	URE	OF REL	the second se					
Type of Rele		Votor Vroal-a		k Production Tank		Volume of Release 5.8 BBLS Volume Recovered 1.2 BBLS Data and Hour of Occurrence Data and Hour of Discourse						
Source of Re.	lease Free	water Knocko	ut, Flare d	e Production Tank	5	Date and Hour of OccurrenceDate and Hour of DiscoveryJanuary 28, 2018 12:30 PM MSTJanuary 28, 2018 12:30 PM MST					Г	
Was Immediate Notice Given?						If YES, To Whom?						
By Whom? Mike Shoemaker						Date and Hour January 29, 2018 11:11 AM MST						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse. N/A						
If a Watercou N/A	Irse was Im	pacted, Descr	be Fully.'	k		1					<u>, , , , , , , , , , , , , , , , , , , </u>	
Describe Cause of Problem and Remedial Action Taken.* When the lease operator arrived on site the battery was releasing fluid from the water knockout. The lease operator identified a malfunctioning valve which had caused the vessel to build pressure and relieve causing the release at multiple points. The valve was closed and a vac truck was dispatched to gather any standing fluids.												
Describe Area Affected and Cleanup Action Taken.* Approximately 5.8 bbls was released (1.2 bbls in containment, 4.5 bbls on pad, and 0.1 bbls misted off site). Approximately 1.2 bbls were recovered from the lined containment. Once fluids were removed the liner it was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left containment. For the remaining impacted areas a remediation contractor will be contacted to assist with delineation and remediation efforts.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
						OIL CONSERVATION DIVISION						
Signature: Jennifer Reyna						Approved by Environmental Specialist / Erroration						
Printed Name: Jennifer Reyna												
Title: Field	Admin Sup	port				Approval Da	te: 2/19/18	Exp	oiration	Date: NIF	1	
E-mail Address: Jennifer.Reyna@dvn.com				í	Conditions of Approval: See attacked Attached 3RP- 44224				10210			
Date: Attach Addi 2/19/18/		ets If Necess		hone: 575.746.55	00						/6	~ # 1~7

Operator/Responsible Party,

The OCD has received the form C-141 you provided on 2/9/2018 regarding an unauthorized release. The information contained on that form has been entered into our incident database and remediation case number 24/9/2018 has been assigned. Please refer to this case number in all future correspondence.

It is the Division's obligation under both the Oil & Gas Act and Water Quality Act to provide for the protection of public health and the environment. Our regulations (19.15.29.11 NMAC) state the following,

The responsible person shall complete <u>division-approved corrective action</u> for releases that endanger public health or the environment. The responsible person shall address releases in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with 19.15.30 NMAC. [emphasis added]

Release characterization is the first phase of corrective action unless the release is ongoing or is of limited volume and all impacts can be immediately addressed. Proper and cost-effective remediation typically cannot occur without adequate characterization of the impacts of any release. Furthermore, the Division has the ability to impose reasonable conditions upon the efforts it oversees. As such, the Division is requiring a workplan for the characterization of impacts associated with this release be submitted to the OCD District 2 office in <u>ARTESIA</u> on or before 3/9/2018. If and when the release characterization workplan is approved, there will be an associated deadline for submittal of the resultant investigation report. Modest extensions of time to these deadlines may be granted, but only with acceptable justification.

The goals of a characterization effort are: 1) determination of the lateral and vertical extents along with the magnitude of soil contamination. 2) determine if groundwater or surface waters have been impacted. 3) If groundwater or surface waters have been impacted, what are the extents and magnitude of that impact. 4) The characterization of any other adverse impacts that may have occurred (examples: impacts on vegetation, impacts on wildlife, air quality, loss of use of property, etc.). To meet these goals as quickly as possible, the following items must, at a minimum, be addressed in the release characterization workplan and subsequent reporting:

• Horizontal delineation of soil impacts in each of the four cardinal compass directions. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. This is not an exclusive list of potential contaminants. Analyzed parameters should be modified based on the nature of the released substance(s). Soil sampling must be both within the impacted area and beyond.

• Vertical delineation of soil impacts. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. As above, this is not an exclusive list of potential contaminants and can be modified. Vertical characterization samples should be taken at depth intervals no greater than five feet apart. Lithologic description of encountered soils must also be provided. At least ten vertical feet of soils with contaminant concentrations at or below these values must be demonstrated as existing above the water table.

• Nominal detection limits for field and laboratory analyses must be provided.

• Composite sampling is not generally allowed.

• Field screening and assessment techniques are acceptable (headspace, titration, EC [include algorithm for validation purposes], EM, etc.), but the sampling and assay procedures must be clearly defined. Copies of field notes are highly desirable. A statistically significant set of split samples must be submitted for confirmatory laboratory analysis, including the laterally farthest and vertically deepest sets of soil samples. Make sure there are at least two soil samples submitted

for laboratory analysis from each borehole or test pit (highest observed contamination and deepest depth investigated).

Copies of the actual laboratory results must be provided including chain of custody documentation.

•Probable depth to shallowest protectable groundwater and lateral distance to nearest surface water. If there is an estimate of groundwater depth, the information used to arrive at that estimate must be provided. If there is a reasonable assumption that the depth to protectable water is 50 feet or less, the responsible party should anticipate the need for at least one groundwater monitoring well to be installed in the area of likely maximum contamination.

• If groundwater contamination is encountered, an additional investigation workplan may be required to determine the extents of that contamination. Groundwater and/or surface water samples, if any, must be analyzed by a competent laboratory for volatile organic hydrocarbons (typically Method 8260 full list), total dissolved solids, pH, major anions and cations including chloride and sulfate, dissolved iron, and dissolved manganese. The investigation workplan must provide the groundwater sampling method(s) and sample handling protocols. To the fullest extent possible, aqueous analyses must be undertaken using nominal method detection limits. As with the soil analyses, copies of the actual laboratory results must be provided including chain of custody documentation.

• Accurately scaled and well-drafted site maps must be provided providing the location of borings, test pits, monitoring wells, potentially impacted areas, and significant surface features including roads and site infrastructure that might limit either the release characterization or remedial efforts. Field sketches may be included in subsequent reporting, but should not be considered stand-alone documentation of the site's layout. Digital photographic documentation of the location and fieldwork is recommended, especially if unusual circumstances are encountered.

Nothing herein should be interpreted to preclude emergency response actions or to imply immediate remediation by removal cannot proceed as warranted. Nonetheless, characterization of impacts and confirmation of the effectiveness of remedial efforts must still be provided to the OCD before any release incident will be closed.

Jim Griswold OCD Environmental Bureau Chief 1220 South St. Francis Drive Santa Fe, New Mexico 87505 505-476-3465 jim.griswold@state.nm.us

Bratcher, Mike, EMNRD

From:	Reyna, Jennifer <jennifer.reyna@dvn.com></jennifer.reyna@dvn.com>
Sent:	Friday, February 9, 2018 1:27 PM
То:	Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; 'Shelly Tucker (stucker@blm.gov)'
Cc:	Fulks, Brett; Shoemaker, Mike
Subject:	Aquila 22 Fed Com 1H_5.8 BBLS Oil_1.28.18
Attachments:	Aquila 22 Fed Com 1H_5.8 BBLS Oil_1.28.18 GIS Image.pdf; Aquila 22 Fed Com 1H_5.8
	BBLS Oil_1.28.18 Inital C-141.doc

Good Afternoon,

Attached please find the Initial C-141 and GIS Image for the 5.8 bbls of oil release at the Aquila 22 Fed Com 1H on 1.28.18. If you have any questions please feel free to contact me.


Thank you,

Jennífer Reyna

Field Admin Support Production B-Schedule

Devon Energy Corporation P.O. Box 250 Artesia, NM 88211 575 746 5588

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.



Bratcher, Mike, EMNRD

From:	Shoemaker, Mike <mike.shoemaker@dvn.com></mike.shoemaker@dvn.com>
Sent:	Monday, January 29, 2018 11:11 AM
То:	Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Shelly Tucker (stucker@blm.gov)
Cc:	Fulks, Brett
Subject:	Aquila 22 Federal Com 1H (API #30-015-40627)

Good Morning,

Devon had the following release occur at 12:30 PM MST on 01/28/18. The incident is described below.

- 1. Aquila 22 Federal Com 1H (API #30-015-40627)
 - a. When the lease operator arrived on site the battery was releasing fluid from the water knockout. The lease operator identified a malfunctioning valve which had caused the vessel to build pressure and relieve causing the release. Approximately 5.8 bbls was released (1.2 bbls in containment, 4.5 bbls on pad, and 0.1 bbls misted off site). Approximately 1.2 bbls were recovered from the lined containment.

A C-141 will be prepared and submitted with GPS coordinates of the area affected.

Thanks,

Mike Shoemaker EHS Representative

Devon Energy Corporation

6488 Seven Rivers Highway Artesia, New Mexico 88210 575-746-5566 Office 575-513-5035 Mobile



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.