




AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pCS1523130486

3RF - 3

LOGOS OPERATING, LLC



2010 Afton Place
Farmington, NM 87401
Phone: (505) 278-8720
Fax: (505) 326-6112

May 16, 2018

Charlie Perrin
New Mexico Oil Conservation Division
1000 Rio Brazos Road
Aztec, New Mexico 87410

NMOC
MAY 18 2018
DISTRICT III

RE: Condition of Approval for Extension
Section 30 Recycling Containment and Facility #3RF-3
April 10 – May 6

Dear Mr. Perrin,

Pursuant to Order R-14314, WPX submitted a C-103 for a 6-month extension request for cessation of operations on August 23, 2017, for the Section 30 Recycling Containment and Facility (#3RF-3) located in Section 30, Township 31N, Range 5W, Rio Arriba County, New Mexico. Approval of the 6-month extension was granted by Director David Catanach on August 25, 2017. Conditions of Approval (COA) of the C-103 are listed below. This report is being submitted to satisfy the monthly report requirement.

1.0 Conditions of Approval

Approval of the extension was granted with the following COA:

- 1) Take necessary actions to keep fresh water accumulation within the containment to a minimum and prevent damage from freezing.
- 2) Inspect and take photographs of the Facility weekly.
- 3) In the event of leaks or damage to the Facility, the operator must do the following.
 - a. Notify OCD District III within 72 hours of knowledge of leaks or damage.
 - b. Submit a Corrective Action Plan (CAP) to repair leaks or damage within seven days of notification above.
 - c. Upon OCD's approval of the CAP, complete repairs per the OCD-approved schedule.
- 4) By the 15th of the month, submit monthly reports to OCD District III of inspection results with photographs and progress on CAP's if any.
- 5) Verify liner integrity before returning the containment to service.

2.0 Weekly Inspections

LOGOS continues to monitor the condition of the Section 30 Recycling Containment. Attached is a summary of weekly inspections conducted at the containment from April 10 – May 6. Also attached is a photograph log documenting site conditions during April 10 – May 6.

3.0 Recent Event Summary

- A small volume of water remains in containment due to rain.
- Minimal amount of rain water and snowmelt was pumped from the leak detection over the past month.
- O.R.E. identified 14 holes and repairs were conducted by O.R.E. on 4/17/18. Repairs were vacuum tested and verified as good.
- 04/18/18 3200bbls fresh water was pumped into the leak detection and 2 leaks were identified. 4/20 to 5/3/18 the water was pumped back out to the storage tanks. 5/4/18 Stormwater inside the containment was pumped out.

Waiting on pond to dry out, then have the 2 leaks repaired.

- LOGOS personnel continue to search and inspect the liner for any potential areas of concern along the base of the containment.

**Section 30 Recycling Containment and Facility
May 2018 Monthly Report**

The next report will be submitted to the Aztec office by June 15, 2018. For additional information or questions regarding current site conditions, please contact me at 505-324-4145.

Sincerely,



Tamra Sessions
Regulatory Specialist

Attachments
Weekly Inspection Log Summary
Photograph Log

Section 30 Recycling Facility and Containment Inspection Summary

WEEKLY INSPECTION:

DATE:

4/10/18--4/15/18

4/16/18--4/22/18

4/23/18--4/29/18

4/30/18--5/6/18

1. ARE FREEBOARD LEVELS AT 3' OR GREATER?

YES	NO
YES	

YES	NO
YES	

YES	NO
YES	

YES	NO
YES	

2. IS THERE ANY OIL ACCUMULATION ON THE CONTAINMENT?

YES	NO
	no

YES	NO
	NO

YES	NO
	NO

YES	NO
	NO

3. ARE THERE VISIBLE TEARS IN LINER?

YES	NO
	no

YES	NO
	NO

YES	NO
	NO

YES	NO
	NO

4. DOES THE NET NEED MAINTENANCE?

YES	NO
	no

YES	NO
	NO

YES	NO
	NO

YES	NO
	NO

5. IS THE FENCING IN GOOD CONDITION?

YES	NO
YES	

YES	NO
YES	

YES	NO
YES	

YES	NO
YES	

6. HOUSEKEEPING ISSUES?

YES	NO
	NO

YES	NO
	NO

YES	NO
	NO

YES	NO
	NO

7. POND MEASUREMENT (HEIGHT)

0

0

0

0

8. IS THERE WATER PRESENT IN THE LEAK DETECTION TUBE?

YES	NO
	NO

YES	NO
	NO

YES	NO
	NO

YES	NO
	NO

9. DEAD WILDLIFE/BIRDS INSIDE CONTAINMENT?

YES	NO
	NO

YES	NO
	NO

YES	NO
	NO

YES	NO
	NO

COMMENTS: (include water quality, odor, color, etc.)

All water has been pumped out and pond is dry

pond is dry--

pond is dry--

all water has been pumped in to frack tanks .Nowwaiting to finish repairing liner

ADDITIONAL OBSERVATIONS:

The rain water has been pumped out into frack tanks to use for later testing
--

pumped water under the liner to check for futher leaks--Now pumping water back into the frack tanks

Pumping water out from under the liner into frack tanks--that was used to test for liner leaks.

weather, Rain and snow came case in this week; Pumping water to the SWD 1

LOGOS Operating, LLC
Section 30 Recycling Containment and Facility
May 2018 Monthly Report

April 11, 2018
Picture #1



April 11, 2018
Picture #2



LOGOS Operating, LLC
Section 30 Recycling Containment and Facility
May 2018 Monthly Report

April 16, 2018
Picture #3



April 16, 2018
Picture #4



LOGOS Operating, LLC
Section 30 Recycling Containment and Facility
May 2018 Monthly Report

April 26, 2018
Picture #5



April 27, 2018
Picture #6



LOGOS Operating, LLC
Section 30 Recycling Containment and Facility
May 2018 Monthly Report

April 27, 2018
Picture #7



April 30, 2018
Picture #8



LOGOS Operating, LLC
Section 30 Recycling Containment and Facility
May 2018 Monthly Report

May 2, 2018
Picture #9

