



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number:** pVF1824052511

**3RP - 1067**

**Hilcorp San Juan, LP**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Hilcorp Energy Company	Contact Jennifer Deal
Address 382 Road 3100 Aztec, NM 87410	Telephone No. (505) 324-5128
Facility Name Navajo Tribal H 13 WTS	Facility Type Gas Well

Surface	Mineral Owner	API No.
---------	---------------	---------

#### LOCATION OF RELEASE

Unit Letter	Section 13	Township 29N	Range 14W	Feet from the 1830	North/South Line South	Feet from the 1830	East/West Line West	County San Juan County
-------------	------------	--------------	-----------	--------------------	------------------------	--------------------	---------------------	------------------------

Latitude 36.7241647 Longitude -108.263221 NAD27

#### NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 8bbls	Volume Recovered 5bbls
Source of Release Produced Water Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 8/7/2018 @ 11:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Operator discovered water leaking from tank valve. He immediately isolated the tank and called to have water tank drained and replaced valve. Leak in tank valve was due to corrosion.

Describe Area Affected and Cleanup Action Taken.\*

Hilcorp Energy Company used a vac truck to recover 5bbls of produced water. The berm area is lined but contained gravel on the top. Hilcorp hydrovaced the gravel off of the liner and found three holes. The liner will be opened up where the holes are to assess the soil. Once the soil is assessed Hilcorp will determine a path forward and will provide OCD 48 hour notice prior to sampling.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jennifer Deal	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: <u>9/24/18</u>	Expiration Date:
E-mail Address: <a href="mailto:jdeal@hilcorp.com">jdeal@hilcorp.com</a>	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 8/28/2018	Phone: (505) 324-5128	

\* Attach Additional Sheets If Necessary

# NCS 1826738059  
Incident

NMOCD

SEP 04 2018

DISTRICT III

①