, 010 what			- AG 17			
District I	State of	f New Mexico	314151617 es	18 18 Jo	、	Form C-1
1625 N. French Dr., Hobbs, NM`88240 District II		and Natural Resource	ès 🚴	, F	R C	evised October 10, 20
1301 W. Grand Avenue, Artesia, NM 88210 District III	Oil Conse	rvation Division	e e	i B	isubmit 2	Copies to appropri
1000 Rio Brazos Road, Aztec, NM 87410 District IV		h St. Francis Dr.	1.1.1	NOUN	B District	Submit 2 Copies to appropriate District Office in accordance with Rule 116 on bac
1220 S. St. Francis Dr., Santa Fe, NM 87505		Fe, NM 87505	S. P.			side of for
Rele	ease Notificatio	n and Correctiv	e Action		»)	
		OPERATOR		X Initi	al Report	🔲 Final Re
Name of Company Chevron USA, Inc.		Contact Wayne Minch		1		
Address HCR 60 Box 432 Lovington, NM Facility Name Central Vacuum Unit	88260	Telephone No.505-39 Facility Type Satellite			<u> </u>	<u>1.1.</u>
Surface Owner State	Mineral Owner	· · · · · · · · · · · · · · · · ·		Lease f	<u>NO.</u>	
Unit Letter Section Township Range		N OF RELEASE	the Fact/	West Line	County	
31 17S 35E	Peet nom the Nort		Lasu	west Line	County	
D		l			1	
La	titude	Longitude				
Type of Release Produced Water	NATURI	COF RELEASE	0 bbl	Volume	Recovered	425bbl
Source of Release 6" fiberglass injection trunk l	ine	Date and Hour of Occ		Date and	Hour of Di	
Was Immediate Notice Given?		11:00 Pm 4/8/06 If YES, To Whom?		11:30 Pm	n 4/08/06	
	No 🗌 Not Required	Guy Wink				
By Whom? Wayne Minchew		Date and Hour 11:00 am 4/09/06				
By Whom? Wayne Minchew		Date and Hour 11:00	am 4/09/06			
By Whom? Wayne Minchew Was a Watercourse Reached? If a Watercourse was Impacted, Describe Fully.		Date and Hour 11:00 If YES, Volume Impa		tercourse.		
Was a Watercourse Reached?	*			tercourse.		
Was a Watercourse Reached?	* n Taken.* joing under Hwy 238. T	If YES, Volume Impa	cting the Wat		on both sid	les of roadway into
Was a Watercourse Reached? Yes X If a Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Actio Hole came in 6" fiberglass injection trunk line g	* oing under Hwy 238. The veek spot in the fiberglas ken.* Iwy and 30" x 390", 396	If YES, Volume Impa	cting the Wat	as released		-
Was a Watercourse Reached? Yes X If a Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Actio Hole came in 6" fiberglass injection trunk line g the pastures. Possible cause could have been a v Describe Area Affected and Cleanup Action Tal An Area of 30' x 300' on the West side of the H	* on Taken.* yoing under Hwy 238. The veek spot in the fiberglas ken.* Iwy and 30" x 390", 396 soil. e is true and complete to nd/or file certain release ce of a C-141 report by to y investigate and remedi	If YES, Volume Impa nis line is inside of condui ss. " x 190" on the East side the best of my knowledge notifications and perform the NMOCD marked as "F ate contamination that pos	t and water	as released Vill clean up and that pur tions for rel does not rel ground wate	p Iron Sulfi suant to NN leases whic lieve the op er, surface v	de and let land dry MOCD rules and h may endanger verator of liability vater, human health
Was a Watercourse Reached? Yes X If a Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Actio Hole came in 6" fiberglass injection trunk line g the pastures. Possible cause could have been a v Describe Area Affected and Cleanup Action Tal An Area of 30' x 300' on the West side of the H up. Remove top soil and replace with good top s I hereby certify that the information given above regulations all operators are required to report an public health or the environment. The acceptant should their operations have failed to adequately or the environment. In addition, NMOCD acceptant	* on Taken.* yoing under Hwy 238. The veek spot in the fiberglas ken.* Iwy and 30" x 390", 396 soil. e is true and complete to nd/or file certain release ce of a C-141 report by to y investigate and remedi	If YES, Volume Impa nis line is inside of condui ss. " x 190" on the East side the best of my knowledge notifications and perform he NMOCD marked as "F ate contamination that pos does not relieve the opera	t and water	as released Vill clean u und that pur tions for rel does not rel ground wate sibility for c	p Iron Sulfi suant to NN leases whic lieve the op er, surface v compliance	de and let land dry MOCD rules and h may endanger erator of liability vater, human health with any other
Was a Watercourse Reached? Yes X If a Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Action Hole came in 6" fiberglass injection trunk line g the pastures. Possible cause could have been a v Describe Area Affected and Cleanup Action Tal An Area of 30' x 300' on the West side of the H up. Remove top soil and replace with good top s I hereby certify that the information given above regulations all operators are required to report at public health or the environment. The acceptant should their operations have failed to adequately or the environment. In addition, NMOCD accepted federal, state, or local laws and/or regulations.	* on Taken.* yoing under Hwy 238. The veek spot in the fiberglas ken.* Iwy and 30" x 390", 396 soil. e is true and complete to nd/or file certain release ce of a C-141 report by to y investigate and remedi	If YES, Volume Impa nis line is inside of condui ss. " x 190" on the East side the best of my knowledge notifications and perform he NMOCD marked as "F ate contamination that pos does not relieve the opera	cting the Wat t and water wa of the Hwy. W e and understa corrective act inal Report" of e a threat to g tor of respons CONSERV	as released Vill clean u und that pur tions for rel does not rel ground wate sibility for c	p Iron Sulfi suant to NN leases whic lieve the op er, surface v compliance	de and let land dry MOCD rules and h may endanger erator of liability vater, human health with any other
Was a Watercourse Reached? Yes X If a Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Action Hole came in 6" fiberglass injection trunk line g the pastures. Possible cause could have been a v Describe Area Affected and Cleanup Action Tal An Area of 30' x 300' on the West side of the H up. Remove top soil and replace with good top s I hereby certify that the information given above regulations all operators are required to report at public health or the environment. The acceptant should their operations have failed to adequately or the environment. In addition, NMOCD accepted federal, state, or local laws and/or regulations. Signature:	* on Taken.* yoing under Hwy 238. The veek spot in the fiberglas ken.* Iwy and 30" x 390", 396 soil. e is true and complete to nd/or file certain release ce of a C-141 report by to y investigate and remedi	If YES, Volume Impa nis line is inside of condui ss. " x 190" on the East side the best of my knowledge notifications and perform he NMOCD marked as "F ate contamination that pos does not relieve the opera	cting the Wat t and water wa of the Hwy. W e and understa corrective act inal Report" of e a threat to g tor of respons <u>CONSERV</u> pervisor:	as released Vill clean u und that pur tions for rel does not rel ground wate sibility for c	p Iron Sulfi rsuant to NN leases whic lieve the op er, surface v compliance	de and let land dry MOCD rules and h may endanger erator of liability vater, human health with any other
Was a Watercourse Reached? Yes X If a Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Actio Hole came in 6" fiberglass injection trunk line g the pastures. Possible cause could have been a v Describe Area Affected and Cleanup Action Tal An Area of 30' x 300' on the West side of the H up. Remove top soil and replace with good top s I hereby certify that the information given above regulations all operators are required to report at public health or the environment. The acceptant should their operations have failed to adequately or the environment. In addition, NMOCD accepted federal, state, or local laws and/or regulations. Signature: Printed Name: Larry Williams	* on Taken.* yoing under Hwy 238. The veek spot in the fiberglas ken.* Iwy and 30" x 390", 396 soil. e is true and complete to nd/or file certain release ce of a C-141 report by to y investigate and remedi	If YES, Volume Impa nis line is inside of condui ss. " x 190" on the East side the best of my knowledge notifications and perform he NMOCD marked as "F ate contamination that pos does not relieve the opera <u>OIL (</u> Approved by District Su	cting the Wat t and water wa of the Hwy. W e and understa corrective act inal Report" of e a threat to g tor of respons <u>CONSERV</u> pervisor:	as released Vill clean u und that pur tions for rel does not rel ground wate sibility for c	p Iron Sulfi rsuant to NM leases whic lieve the op er, surface v compliance	de and let land dry MOCD rules and h may endanger erator of liability vater, human health with any other ON
Was a Watercourse Reached? Yes X If a Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Actio Hole came in 6" fiberglass injection trunk line g the pastures. Possible cause could have been a v Describe Area Affected and Cleanup Action Tal An Area of 30' x 300' on the West side of the H up. Remove top soil and replace with good top s I hereby certify that the information given above regulations all operators are required to report at public health or the environment. The acceptant should their operations have failed to adequately or the environment. In addition, NMOCD accepted federal, state, or local laws and/or regulations. Signature: Printed Name: Larry Williams Title: HES Champion E-mail Address: lcwl@chevron.com	* on Taken.* yoing under Hwy 238. The veek spot in the fiberglas ken.* Iwy and 30" x 390", 396 soil. e is true and complete to nd/or file certain release ce of a C-141 report by to y investigate and remedi	If YES, Volume Impa nis line is inside of condui ss. " x 190" on the East side the best of my knowledge notifications and perform he NMOCD marked as "F ate contamination that pos does not relieve the opera <u>OIL (</u> Approved by District Su Approval Date:	cting the Wat t and water wa of the Hwy. W e and understa corrective act inal Report" of e a threat to g tor of respons <u>CONSERV</u> pervisor:	as released Vill clean u und that pur tions for rel does not rel ground wate sibility for c	p Iron Sulfi rsuant to NN leases whic lieve the op er, surface v compliance	de and let land dry MOCD rules and h may endanger erator of liability vater, human health with any other ON