District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Final Report

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Name of Co			g Compa	ny		Contact:					
Address: 122 West Taylor						Telephone No.: 505-393-9174					
Facility Name: BD F							Facility Type: Salt Water Gathering System				
Surface Own	ner: Tom	Kennan	Mineral O	wner	: Lease No.:						
Dui lace OWI											
LOCATION OF RELEASE											
Unit Letter Section Township Range 30 21S 37E Feet from the N				North/South Line		Feet from the	East/West Line		County Lea		
Latitude: 32*27.176N Longitude: 103*12.974W											
NATURE OF RELEASE											
Type of Relea	se: Produc	ed water with			Volume of Release: 520 barrels Volume Recovered: 360 barrels						
Source of Release: pipeline						Date and Hour of Occurrence: Date and Hour of Discovery:					
Was Immediate Notice Given?						N/A 5/25/06 11:30 am					
was immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Pat Caperton					
By Whom? J					Date and Hour: 5/26/05 7:50 am						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse:					
If a Watercourse was Impacted, Describe Fully.*											
ii a watercou	rse was an	pacted, Descri	ibe Fully.					ti.	<i>'ह\</i>		
								ann	<i>E</i> /		
The State of Problem and Remedial Action Taken.* 6" PVC cracked. Describe Area Affected and Cleanup Action Taken. Replaced with new 6" PVC and a new Station. Vaccourse was described to the problem. Taken. Replaced with new 6" PVC and a new Station. Vaccourse was described to the problem. Taken. Replaced with new 6" PVC and a new Station. Vaccourse was described to the problem.											
Describe Cau	se of Proble	em and Reme	dial Action	Taken.* 6" PVC	cracke	d.	S HOCK	bbs	81 /		
							10	CD	<i>&</i>		
Describe Area	Affected a	and Cleanup A	Action Tak	en * Replaced wi	th new	6" PVC and	a new Compling V	Jacinim	APPOK Was I	used to reomove produced	
water from si	te.	aid Citaliap i	ionon rai	ion. Replaced Wi	ui iiew	o i ve una	in the state of th	15056	Back was t	isca to realitave produced	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
1						OIL CONSERVATION DIVISION					
Signature:	Vann.	de Al	(A)								
<u>-</u>	A VIV	12001			Approved by	District Superviso	·r·				
Printed Name	:Vennifer J	lohnson				Disarct Supervise	, ———	***			
Title: Environmental and Field Technician						Approval Dat	e:	I	Expiration I	Date:	
E-mail Address: jjohnson@riceswd.com						Conditions of Approval:				Attached	
Date: 6/15/06 Phone: 505-393-9174											
Attach Addit	ional Shee acht madi pplic	its If Necessary - ff A int - nt ation- SP #	Ary COGIG PACOG PACOG	735311 16735414 06167355	548						

June 15, 2006

Mr. Paul Sheeley New Mexico Energy, Minerals, & Natural Resources Oil Conservation Division 1625 N. French Drive Hobbs, New Mexico

> RE: INVESTIGATION & CHARACTERIZATION PLAN BD G-30 ACCIDENTAL DISCHARGE SITE UL/G SEC 30 T21S R37E

Mr. Sheeley:

Rice Operating Company (ROC) discovered an accidental discharge on the above mentioned site on May 25, 2006. A 6 inch PVC pipeline cracked thus releasing 520 barrels of which 360 barrels were recovered. The 6 inch PVC pipeline was replaced with 20 feet of new PVC as a permanent repair. Regional groundwater information indicates the depth to groundwater is approximately 117 ft bgs. The surface area affected by this release was approximately 7,419 sq ft.

For all environmental projects, ROC will choose a path forward that:

- protects public health,
- provides the greatest net environmental benefit,
- complies with NMOCD Rules, and
- is supported by good science.

Each site shall have three submissions or a combination of:

- 1. This <u>Investigation and Characterization Plan</u> (ICP) is a proposal for data gathering and site characterization and assessment. Highly impacted topsoil will be removed from the surface at this time and disposed of at a permitted facility.
- 2. Upon evaluating the data and results from the ICP, a recommended remedy will be submitted in a <u>Corrective Action Plan</u> (CAP). ROC will request concurrence or conditions from NMOCD with this submission.
- 3. Finally, after implementing the remedy, a <u>closure report</u> with final documentation will be submitted. This will include the C-141 (final) form. ROC will request concurrence or conditions from NMOCD with this submission.

ROC herein submits the enclosed ICP to address potential environmental concerns at the above-referenced site. ROC is the service provider (operator) for the BD SWD System and has no ownership of any portion of the pipeline, well, or facility. The System is owned by a consortium of oil producers, System Partners, who provide all operating capital on a percentage ownership/usage basis.

NMOCD will be notified 48 hours in advance of any significant work. Thank you for your consideration concerning this matter.

Rice Operating Company

Jennifer Johnson Environmental Technician

Cc: KFP, file

Enclosed: ICP, site map, driving directions, Initial C-141

INVESTIGATION AND CHARACTERIZATION PLAN BD G-30 ACCIDENTAL DISCHARGE UL/G SEC 30 T21S R37E

Background and Previous Work

Rice Operating Company (ROC) discovered an accidental discharge on the above mentioned site on May 25, 2006. A 6 inch PVC pipeline cracked thus releasing 520 barrels of which 360 barrels were recovered. The 6 inch PVC pipeline was replaced with new 20 feet of new PVC as a permanent repair. Regional groundwater information indicates the depth to groundwater is approximately 117 ft bgs. The surface area affected by this release was approximately 7,419 sq ft.

Work Elements

- Impacted topsoil not to exceed 4 inches of depth over entire 7419 sq ft will be removed and disposed of at an approved facility.
- A water well inventory will be performed to encompass a half mile radius around the release site. The inventory will include a review of water well records on the New Mexico Office of the State Engineer W.A.T.E.R.S. database and United States Geologic Survey (USGS) website. Any water wells denoted on the USGS 7.5 minute topographic quadrangle map within the search radius will be inspected. If viable wells are located, they will be evaluated for the possible water level measurements and groundwater monitoring.
- Produced water samples were collected from the pipeline where the release occured.
- Perimeter and area of the affected surface will be defined using stakes and flagging.

 Perimeter samples will be taken to define the lateral extent of impact. Vertical delineation will also be conducted. These delineation activities may be performed with the following equipment but not limited to a hand auger, backhoe, and soil boring.
- ROC will employ chloride field tests and PID screenings to monitor constituents of concern on the soil samples that will be collected at regular intervals.
- Appropriate and strategic samples will be submitted for laboratory analysis as confirmation of field tests.
- NMOCD will be notified of any significant activities 48 hours in advance.
- Delineation results from this release site will be used to form an appropriate site specific remedy and will be submitted in a Corrective Action Plan (CAP).

Following completion of the ICP, a CAP that details the site results of this ICP and includes the remedy recommendation will be submitted for NMOCD approval. ROC generally selects the remedy that offers the greatest environmental benefit while causing the least environmental impairment. When evaluating any proposed remedy or investigative work, ROC will confirm that there is a reasonable relationship between the benefits created by the proposed remedy or assessment and the economic and social costs.

BD G-30 DRIVING DIRECTIONS

GPS 32*27.194N 103*11.954W

FROM HWY 8 AND LEGION ROAD IN EUNICE GO WEST ON HWY 8 1 MILE TURN NORTH THROUGH CATTLE GUARD GO .6 TENTHS ROAD Y'S AT PUMP JACK LOCATION GO NORTH WEST TOWARDS CHEVRON BATTERY. ROAD Y'S GO NORTH .1 TENTH ROAD T'S GO WEST .2 TENTHS TURN SOUTH ON RIGHT OF WAY LOCATION 800 FT.

CAUSE OF LEAK						
Discribe cause of problem & how it was	repaired. 6' PVC cracked, replaced					
	#8					
	6 Lease Road					
	B 55×33=3624 B 55×33=1815 C 233×60=1980					
	Total 7,419 ft					
	7 (33)					
, , , , , , , , , , , , , , , , , , ,	20 1 Cm ² 2					
	3					
Lease Road						