

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company CHEVRON	Contact Larry Williams
Address P.O. Box 1949 Eunice NM. 88231	Telephone No. 505-394-1247 (office), 505-390-7165 (cell)
Facility Name- CDU Injection System	Facility Type - Injection Trunk line

Surface Owner- Chevron	Mineral Owner - State of New Mexico	Lease No.
------------------------	-------------------------------------	-----------

LOCATION OF RELEASE

Unit Letter B	Section 21	Township 21S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea

Latitude 32.44231_ Longitude 103.18017_

NATURE OF RELEASE

WTR 55' to 75' deep

Type of Release- Produced Water	Volume of Release 115 BW	Volume Recovered- 111 BW
Source of Release- 4" Fiberglass line	Date and Hour of Occurrence- 07/10/07 9:30 am	Date and Hour of Discovery 07/10/07 9:33 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Billy Anderson	Date and Hour 7/10/07 @ 10:36 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

B&H Construction was doing a road boring for us under Highway 176 when it struck our 4" fiberglass truck line. The water was contained inside of the ditch that they had dug out for the boring tools. It was in clay, so it contained the majority of the water without it going into the ground. Called out vacuum truck and picked up standing water.

Describe Area Affected and Cleanup Action Taken.* The majority of the fluid was contained within the ditch for the road boring. Water was picked up from the ditch with a vacuum truck and taken to Sundance for disposal. We will not do any remediation due to the small amount that was absorbed in the ditch and the depth of the ditch. We will have a good 5 foot of coverage with good top soil.

Chlorides are 21,000. Depth to ground water. Between 85' to 90'

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Larry Williams		Approved by District Supervisor: 	
Title: Production Rep	Approval Date: 7-18-07	Expiration Date: _____	
E-mail Address: lcwl@chevron.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 07/12/07	Phone: 505-394-1247		

* Attach Additional Sheets If Necessary

RPT 1491