

NM1 - 3

MONITORING REPORTS


YEAR(S):

1988 - 1989

MAP

DIKES		ELEV. OF TOP	PIT		ELEV. OF FLUID LEVELS
CONSTRUCTED	A	3451	1		3447
	B	3451	2		3458
	C	3461	3		3458
	D	3439	4		3435
	E	3439	5		3446
	F	3461	6		3447
	G	3450	7		3447
	H	3450			
	I	3450			

MONITOR HOLES		
HOLE NO.	ELEV. TOP OF PERFS.	ELEV. BASE OF PERFS.
1-21	3451	3427
23-32	3461	3436
33-40	3462	3436
41-51	3440	3390
52-63	3442+	3415
64-76	3449 OR BELOW	3410 OR BELOW
77-87	3440	3410



- LEGEND
- TEST HOLE; ● TRIASSIC ENCOUNTERED
 - MONITOR HOLE
 - MONITOR HOLE, ABANDONED
 - △ PIT FLOOR; ▲ TRIASSIC ENCOUNTERED
 - + PIT RIM
 - INSTRUMENT STATION
 - CORE HOLE
 - GRAVEL EXPLORATION HOLE
 - DIKE/CORE TRENCH
 - PROPOSED PIPELINE

FIGURE-1

LEA COUNTY, NEW MEXICO
PARABO, INC.

TOP OF TRIASSIC

REV. 2/81
REV. 11/81
REV. 6/16/82
REV. 10/19/83
REV. 4/1/85
REV. 10/30/85

ED L. REED & ASSOCIATES, INC.
CONSULTING HYDROLOGISTS
MIDLAND-CORPUS CHRISTI, TEXAS

copy 1/2 file copy