District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003 bruit 2 Copies to appropriate

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

						OPERA	ГOR	X Init	X Initial Report Final Report			
Name of Company ConocoPhillips Company						Contact Jess	se A. Sosa					
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5												
Facility Name North Skaggs WF Injection Station						Facility Type Injection Gathering Site						
S. S. S. Overson DIM						BLM Lease No. NM 0557686						
Surface Owner BLM Mineral Owner						Lease No. NW 0337080						
				LOCA	TIO	N OF REI	LEASE					
Unit Letter	Section	Township	Range			/South Line	Feet from the	East/West Line	County			
N	13	20S	37E						Lea			
Latitude 32 34.060 Longitude 103 12.435												
NATURE OF RELEASE												
Type of Release Produced Water						Volume of Release 37 Volume Recovered 30						
Source of Re						Date and Hour of Occurrence 11/29/07at 2at0 Hour of Discovery 11/29/07						
Was Immedia	ite Notice () T V [la Darin		If YES, To Whom?						
		<u>IA</u>	Yes [No Not Req	uired	NMOCD (P. Richards) & BLM (T. BadBear)						
By Whom? Jesse Sosa						Date and Hour 11/29/2007 3:33 pm						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
		L	Yes 🔼	No		If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*												
The Mar was the second of the												
								12	NOA S	ued	9	
								27	Recei	hs	0	
Describe Cause of Problem and Remedial Action Taken.*												
Tank overflowed due to level controller failure. Controller was renaired to shut in flow to tank. Headswitches to be gone through and												
repaired.												
•									261 81 TI	917		
Describe Cause of Problem and Remedial Action Taken.* Tank overflowed due to level controller failure. Controller was repaired to shut in flow to tank. Headswitches to be gone through and repaired.												
Describe Area Affected and Cleanup Action Taken.*												
Affected area was 40' X 200' on caliche pad and location. Will remediate in place according to NMOCD and BLM recommendations.												
REGULATIONS												
				is true and complet								
				d/or file certain rele e of a C-141 report								
				investigate and rem								
				ance of a C-141 rep								
federal, state,	or local lav	vs and/or regu	lations.									
/	}	Λ λ _			1		OIL CONS	SERVATION	DIVISIO	N		
1 X 1 X 1												
Signature: Xun W O m								CM	30.Am		ļ	
Printed Name: Jesse A. Sosa						Approved by 1	District Superviso	ÖNMENTAL I	NGMEE	à	ł	
								J.WILLIAM I	:1 A (311 A1 1 1 1	L		
Title: HSER	Lead					Approval Date	:11.4.07	Expiration	Date: 1.Z.	<u>5 ·08</u>	<u>}</u>	
	T .		1 2114			<i>#4</i>			1			
E-mail Addres	ss: Jesse.A.	.Sosa(a)cono	cophillips	.com		Conditions of	Approval:		Attached	П		
Date: 11/30/2	2007		Phone:	(505)391-3126	3							
Attach Additi		ts If Necess			SUBMIT DELL DEATION &							
riacii Mudii	onai piiçe	m 11 14000386	ш.у	- (`s.	.*	Closus	ce Plan B	4	[]	壯	11 m	
									[_/d	ITT	$\mathcal{O}(\mathcal{O})$	
AP 1010												
									ı v			