

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Chevron Mid-Continent LP	Contact	Kim Klahsen
Address	HCR 60 Box 423 Lovington, NM 88260	Telephone No.	505-396-4414 X 128 432-894-3298 (Cell)
Facility Name	Vacuum Grayburg SanAndreas Unit. Central Tank Battery.	Facility Type	Tank Battery and Injection Station

Surface Owner	State of NM	Mineral Owner	State of NM	Lease No.
---------------	-------------	---------------	-------------	-----------

LOCATION OF RELEASE

Unit Letter	Section 2	Township 18S	Range 34E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	45 bbl	Volume Recovered	40 bbl
Source of Release	Valve leak	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	OCD-		
By Whom?	Kim Klahsen	Date and Hour	12-29-07		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RECEIVED

JAN 14 2008

HOBBS OCD

If a Watercourse was Impacted, Describe Fully.*
No Impact to watercourse.

Describe Cause of Problem and Remedial Action Taken.*
A valve leaked below ground. Water pooled on the surface in an area about 60 feet long by 20 feet wide. A vacuum truck was immediately dispatched to recover the pooled water. A work order was completed to remove several inches of contaminated soil. The spill occurred adjacent to a tank battery.

Describe Area Affected and Cleanup Action Taken.*
The Vacuum truck recovered 40 bbls of produced water. Surface soil will be removed with a backhoe. *Must be sampled for CI contamination levels. Ca*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kim Klahsen</i>		OIL CONSERVATION DIVISION	
Printed Name: Kim Klahsen		Approved by District Supervisor: <i>Chris Williams</i>	
Title: HES Specialist		Approval Date: <i>1/16/08</i>	Expiration Date: <i>4/16/08</i>
E-mail Address: KDKL@chevron.com		Conditions of Approval:	
Date: 1-10-08		Attached <input type="checkbox"/>	
Phone: 505-396-4414			

* Attach Additional Sheets If Necessary

RP# 1730