1R-426-152

REPORTS




4-1-08

BD N-31 Vent

ci.

۰

1R426-152




RICE OPERATING COMPANY JUNCTION BOX FINAL REPORT

				BOX LOCA	TION					
SWD SYSTEM	JUNCTION	UNIT	SECTION	TOWNSHIP	RANGE	COUNTY	NEW BOX		ONS - FEET	
Blinebry-	N-31 vent	N	31	215	37E	Lea	Length	Width	Depth	
Drinkard (BD)			<u> </u>				no box	; junction elim	inated	
LAND TYPE: BL	VISTA	TE	FEE LAND	OWNER	Patrick S	Sims	OTHER			
Depth to Ground	water	211	feet	NMOCE	SITE ASS	ESSMENT I	RANKING S		0	
Date Started	7/13/20	07	Date Co	mpleted	7/24/2007		D Witness		no	
Soil Excavated	0	cubic ya	rds Exc	cavation Lei	ngthn/a	Width	n/a	Depth	n/a	feet
Soil Disposed	0	cubic ya	rds Of	fsite Facility	<u></u> n/	′a	Location		n/a	
FINAL ANALYT 5-point composite sidewalls. TPH and	sample of bott	om and 4-p	oint compos	site sample o				pth		
laboratory a	ind testing pro	cedures pu	suant to N	NOCD guide	lines.		OCATION	DEPTH (ft		
Sample	<u>PID</u> (field	GF	20	DRO	Chloride	V(P.7. 5 882)			· · · · · · · · · · · · · · · · · · ·	om
Location	ppm	mg		mg/kg	mg/kg	No. No. No.	A Constant of Parks			
4-WALL COMP.		(5) (5) (1)							Providencia Registration Registration	194 DE 194
BOTTOM COMP.										
BACKFILL										
General Description pipeline. This junction wa impacts to the soil or vega by the box and to contour return to productive capad	as eliminated as etations were ob the surrounding	This part of the pi served at anc surface. On	peline replace around the s	ement/upgrade ite. 12 cubic y	e program. Up yards of clean,	oon removal of imported soil	this box in 20 was used to l	backfill the hole	e impacts e left	
	city at a norman					······································		en	closures: p	photos
) HEREB)	Y CERTIFY TH	HAT THE IN		DN ABOVE I /LEDGE AN		ID COMPLE	те то тне	BEST OF N	ſΥ	
	L. Bruce Baker	SIGI		my Bruce	Baker /	2, COMP	ANY RICI	E Operating Co	mpany	

REPORT ASSEMBLED BY	Kristin Farris Pope	SIGNATURE	Kantin Janin Rose	
DATE	12/3/2007	TITLE	Project Scientist	

BD N-31 vent

Unit N, Section 31, T21S, R37E



inactive, watertight, fiberglass-lined junction box





site inspection after old box was removed



7/24/2007

seeding backfilled surface

7/24/2007