Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	June 19, 2008
1625 N. French Dr., Hobbs, NM 88240 District II		30-025-03687
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION 5.	Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Allo	· · · · · · · · · · · · · · · · · · ·
District IV		State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		L-214
		Pease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)	<u> </u>	State GA
,	Well Other 8.	Well Number 6
2. Name of Operator Pecos Opera	eting Company, LLC 9.	OGRID Number 246798
3. Address of Operator 400 W Illin	nois Suite 1210	Pool name or Wildcat
Midland, TX	· · · · · · · · · · · · · · · · · · ·	Caudill Devonian
4. Well Location		
Unit Letter D: 66		
Section		IPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
张·丁香油等等。1925年4月2日 1921年2月2日 1921年2月		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTEN	ITION TO: SUBSEC	QUENT REPORT OF:
	UG AND ABANDON   REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON 🔲 CHA	ANGE PLANS 🔲 COMMENCE DRILLIN	G OPNS.□ P AND A □
	ILTIPLE COMPL   CASING/CEMENT JO	3 🗆
DOWNHOLE COMMINGLE		
	l l	
OTHER:	OTHER: Re Er	try
	operations. (Clearly state all pertinent details, and giv	e pertinent dates, including estimated date
13. Describe proposed or completed of starting any proposed work).	U   OTHER.	e pertinent dates, including estimated date
13. Describe proposed or completed of starting any proposed work). So or recompletion.	operations. (Clearly state all pertinent details, and giv	e pertinent dates, including estimated date
of starting any proposed work). Some or recompletion. 5-10-08 Clear location, 5-13-08 Drill out surface	operations. (Clearly state all pertinent details, and gives SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. See plug, cleanout to 4500', Test 8-5/	e pertinent dates, including estimated date wellbore diagram of proposed completion
13. Describe proposed or completed of starting any proposed work). So or recompletion. 5-10-08 Clear location, 5-13-08 Drill out surface Drill out cement	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. See plug, cleanout to 4500', Test 8-5/2 plugs to csg stub @9013'.	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - 0K.
13. Describe proposed or completed of starting any proposed work). So or recompletion. 5-10-08 Clear location, 5-13-08 Drill out surface Drill out cement 5-19-08 Ran 65' of 7-3/8	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. See plug, cleanout to 4500', Test 8-5/2 plugs to csg stub @9013'.  By bowlover and 209 jts 5-1/2", 17#,	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx
13. Describe proposed or completed of starting any proposed work). So or recompletion. 5-10-08 Clear location, 5-13-08 Drill out surfact Drill out cement 5-19-08 Ran 65' of 7-3/8 65:35 poz:C w/ 6	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. The plug, cleanout to 4500', Test 8-5/2 plugs to csg stub @9013'.  By bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc 1	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx
13. Describe proposed or completed of starting any proposed work). So or recompletion. 5-10-08 Clear location, 5-13-08 Drill out surface Drill out cement 5-19-08 Ran 65' of 7-3/8 65:35 poz:C w/ 6 Release Drlg Rig	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. See plug, cleanout to 4500', Test 8-5/5; plugs to csg stub @9013'.  By bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc Tog & MIRU completion Unit.	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx OC - 4000'.
13. Describe proposed or completed of starting any proposed work). So or recompletion. 5-10-08 Clear location, 5-13-08 Drill out surface Drill out cement 5-19-08 Ran 65' of 7-3/8 65:35 poz:C w/ 6 Release Drlg Rig 5-28-08 Drill out cmt in	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. The plug, cleanout to 4500', Test 8-5/2 plugs to csg stub @9013'.  By bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc 1	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - 0K.  J-55 csg. Cmtd w/ 550 sx  OC - 4000'.  1000 psi - 0K. Drill cmt
13. Describe proposed or completed of starting any proposed work). So or recompletion. 5-10-08 Clear location, 5-13-08 Drill out surface Drill out cement 5-19-08 Ran 65' of 7-3/8 65:35 poz:C w/ 6 Release Drlg Rig 5-28-08 Drill out cmt in plugs and clean on-off tool @ 12	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. See plug, cleanout to 4500', Test 8-5/5; plugs to csg stub @9013'.  B" bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc Transport	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx  OC - 4000'.  1000 psi - OK. Drill cmt ng to 13,320' w/ pkr &
13. Describe proposed or completed of starting any proposed work). So or recompletion.  5-10-08 Clear location,  5-13-08 Drill out surface Drill out cement  5-19-08 Ran 65' of 7-3/8  65:35 poz:C w/ 6  Release Drlg Rig  5-28-08 Drill out cmt in plugs and clean on-off tool @ 12  6-10-08 Perf Devonian 13	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. The plugs to csg stub @9013'.  B' bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc Transport Calc Tr	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx  OC - 4000'.  1000 psi - OK. Drill cmt  ng to 13,320' w/ pkr &  15% HC1.
13. Describe proposed or completed of starting any proposed work). So or recompletion. 5-10-08 Clear location, 5-13-08 Drill out surface Drill out cement Drill out cement 5-19-08 Ran 65' of 7-3/8 65:35 poz:C w/ 6 Release Drlg Rig 5-28-08 Drill out cmt in plugs and clean on-off tool @ 12 6-10-08 Perf Devonian 13 7-01-08 Pull tubing and	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. See plug, cleanout to 4500', Test 8-5/5; plugs to csg stub @9013'.  B" bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc Transport	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx  OC - 4000'.  1000 psi - OK. Drill cmt  ng to 13,320' w/ pkr &  15% HC1.
of starting any proposed work). So or recompletion. 5-10-08 Clear location, 5-13-08 Drill out surface Drill out cement 5-19-08 Ran 65' of 7-3/8 65:35 poz:C w/ 6 Release Drlg Rig 5-28-08 Drill out cmt in plugs and clean on-off tool @ 12 6-10-08 Perf Devonian 13 7-01-08 Pull tubing and and pump.	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. The plugs to csg stub @9013'.  B' bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc Transport Calc Tr	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx OC - 4000'.  1000 psi - OK. Drill cmt ng to 13,320' w/ pkr &  15% HCl. back onto packer. Run rods
of starting any proposed work). So or recompletion. 5-10-08 Clear location, 5-13-08 Drill out surface Drill out cement 5-19-08 Ran 65' of 7-3/8 65:35 poz:C w/ 6 Release Drlg Rig 5-28-08 Drill out cmt in plugs and clean on-off tool @ 12 6-10-08 Perf Devonian 13 7-01-08 Pull tubing and and pump.	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. The plugs to csg stub @9013'.  By bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc The Second Completion Unit.  The 5-1/2" csg to 9118'. Test patch to out to 13,433' PBTD. Ran 2-7/8" tubit 2,822'.  By 366 - 13,412'. Acidize w/ 1500 gal install SN at 8000'. Rerun and latch	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx OC - 4000'.  1000 psi - OK. Drill cmt ng to 13,320' w/ pkr &  15% HCl. back onto packer. Run rods
13. Describe proposed or completed of starting any proposed work). So or recompletion. 5-10-08 Clear location, 5-13-08 Drill out surface Drill out cement Drill out cement S-19-08 Ran 65' of 7-3/8 65:35 poz:C w/ 60 Release Drlg Rig S-28-08 Drill out cmt in plugs and clean on-off tool @ 12 6-10-08 Perf Devonian 13 7-01-08 Pull tubing and and pump. 7-21-08 Start well pumpi	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. The plugs to csg stub @9013'.  By bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc The Second Completion Unit. The second Completion Unit. The second Cout to 13,433' PBTD. Ran 2-7/8" tubit 2,822'.  By 366 - 13,412'. Acidize w/ 1500 gal install SN at 8000'. Rerun and latch Ling 8 x 144" SPM. 7-23-08 Test: 47 Install SN at 8000'.	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx OC - 4000'.  1000 psi - OK. Drill cmt ng to 13,320' w/ pkr &  15% HCl. back onto packer. Run rods
13. Describe proposed or completed of starting any proposed work). So or recompletion.  5-10-08 Clear location,  5-13-08 Drill out surface Drill out cement  5-19-08 Ran 65' of 7-3/8  65:35 poz:C w/ 6  Release Drlg Rig  5-28-08 Drill out cmt in plugs and clean on-off tool @ 12  6-10-08 Perf Devonian 13  7-01-08 Pull tubing and and pump.  7-21-08 Start well pumpi  Spud Date: 5-13-08	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. The plugs to csg stub @9013'.  B' bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc Transport Calc Tr	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx OC - 4000'.  1000 psi - OK. Drill cmt ng to 13,320' w/ pkr &  15% HC1. back onto packer. Run rods  60, 343 BW, Gas - TSTM.
13. Describe proposed or completed of starting any proposed work). So or recompletion.  5-10-08 Clear location,  5-13-08 Drill out surface Drill out cement  5-19-08 Ran 65' of 7-3/8  65:35 poz:C w/ 6  Release Drlg Rig  5-28-08 Drill out cmt in plugs and clean on-off tool @ 12  6-10-08 Perf Devonian 13  7-01-08 Pull tubing and and pump.  7-21-08 Start well pumpi  Spud Date: 5-13-08	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. The plugs to csg stub @9013'.  By bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc The Second Completion Unit. The second Completion Unit. The second Cout to 13,433' PBTD. Ran 2-7/8" tubit 2,822'.  By 366 - 13,412'. Acidize w/ 1500 gal install SN at 8000'. Rerun and latch Ling 8 x 144" SPM. 7-23-08 Test: 47 Install SN at 8000'.	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx OC - 4000'.  1000 psi - OK. Drill cmt ng to 13,320' w/ pkr &  15% HC1. back onto packer. Run rods  60, 343 BW, Gas - TSTM.
13. Describe proposed or completed of starting any proposed work). So or recompletion.  5-10-08 Clear location,  5-13-08 Drill out surface Drill out cement  5-19-08 Ran 65' of 7-3/8  65:35 poz:C w/ 6  Release Drlg Rig  5-28-08 Drill out cmt in plugs and clean on-off tool @ 12  6-10-08 Perf Devonian 13  7-01-08 Pull tubing and and pump.  7-21-08 Start well pumpi  Spud Date: 5-13-08	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. The plugs to csg stub @9013'.  B' bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc Transport Calc Tr	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx OC - 4000'.  1000 psi - OK. Drill cmt ng to 13,320' w/ pkr &  15% HC1. back onto packer. Run rods  60, 343 BW, Gas - TSTM.
13. Describe proposed or completed of starting any proposed work). So or recompletion.  5-10-08 Clear location,  5-13-08 Drill out surface Drill out cement  5-19-08 Ran 65' of 7-3/8  65:35 poz:C w/ 6  Release Drlg Rig  5-28-08 Drill out cmt in plugs and clean on-off tool @ 12  6-10-08 Perf Devonian 13  7-01-08 Pull tubing and and pump.  7-21-08 Start well pumpi  Spud Date: 5-13-08	operations. (Clearly state all pertinent details, and give SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. The plugs to csg stub @9013'.  B' bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc Transport Calc Tr	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx OC - 4000'.  1000 psi - OK. Drill cmt ng to 13,320' w/ pkr &  15% HC1. back onto packer. Run rods  60, 343 BW, Gas - TSTM.
13. Describe proposed or completed of starting any proposed work). So or recompletion.  5-10-08 Clear location,  5-13-08 Drill out surface Drill out cement of the starting and clean on the starting an	operations. (Clearly state all pertinent details, and gives SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. See plug, cleanout to 4500', Test 8-5/5 plugs to csg stub @9013'.  B" bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc Test & MIRU completion Unit.  In 5-1/2" csg to 9118'. Test patch to out to 13,433' PBTD. Ran 2-7/8" tubic 2,822'.  B,366 - 13,412'. Acidize w/ 1500 gal install SN at 8000'. Rerun and latch ling 8 x 144" SPM. 7-23-08 Test: 47 If Rig Release Date: 7-03-08	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx OC - 4000'.  1000 psi - OK. Drill cmt ng to 13,320' w/ pkr &  15% HCl. back onto packer. Run rods  60, 343 BW, Gas - TSTM.
13. Describe proposed or completed of starting any proposed work). So or recompletion.  5-10-08 Clear location,  5-13-08 Drill out surface Drill out cement of the starting and clean on the start well pumping and pump.  Type or print name William R. Hu	operations. (Clearly state all pertinent details, and gives SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. See plug, cleanout to 4500', Test 8-5/5 plugs to csg stub @9013'.  B" bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc Test & MIRU completion Unit.  In 5-1/2" csg to 9118'. Test patch to out to 13,433' PBTD. Ran 2-7/8" tubic 2,822'.  B,366 - 13,412'. Acidize w/ 1500 gal install SN at 8000'. Rerun and latch ling 8 x 144" SPM. 7-23-08 Test: 47 If Rig Release Date: 7-03-08	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx OC - 4000'.  1000 psi - OK. Drill cmt ng to 13,320' w/ pkr &  15% HCl. back onto packer. Run rods 60, 343 BW, Gas - TSTM.  DATE 7-30-08  companie Sprione: 432-620-8480
13. Describe proposed or completed of starting any proposed work). So or recompletion.  5-10-08 Clear location,  5-13-08 Drill out surface Drill out cement of the starting and clean on the starting an	operations. (Clearly state all pertinent details, and gives SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. See plug, cleanout to 4500', Test 8-5/5 plugs to csg stub @9013'.  B" bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc Test & MIRU completion Unit.  In 5-1/2" csg to 9118'. Test patch to out to 13,433' PBTD. Ran 2-7/8" tubic 2,822'.  B,366 - 13,412'. Acidize w/ 1500 gal install SN at 8000'. Rerun and latch ling 8 x 144" SPM. 7-23-08 Test: 47 If Rig Release Date: 7-03-08	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx OC - 4000'.  1000 psi - OK. Drill cmt ng to 13,320' w/ pkr &  15% HCl. back onto packer. Run rods 60, 343 BW, Gas - TSTM.  DATE 7-30-08  companie Sprione: 432-620-8480
13. Describe proposed or completed of starting any proposed work). So or recompletion.  5-10-08 Clear location,  5-13-08 Drill out surface Drill out cement of the starting and clean on the start well pumping and pump.  Type or print name William R. Hu	operations. (Clearly state all pertinent details, and gives SEE RULE 1103. For Multiple Completions: Attach Dig out and Re-Install Wellhead. See plug, cleanout to 4500', Test 8-5/5 plugs to csg stub @9013'.  B" bowlover and 209 jts 5-1/2", 17#, 5% gel and 250 sx Cl H w/ FLA. Calc Test & MIRU completion Unit.  In 5-1/2" csg to 9118'. Test patch to out to 13,433' PBTD. Ran 2-7/8" tubic 2,822'.  B,366 - 13,412'. Acidize w/ 1500 gal install SN at 8000'. Rerun and latch ling 8 x 144" SPM. 7-23-08 Test: 47 If Rig Release Date: 7-03-08	e pertinent dates, including estimated date wellbore diagram of proposed completion  8" casing to 500 psi - OK.  J-55 csg. Cmtd w/ 550 sx OC - 4000'.  1000 psi - OK. Drill cmt ng to 13,320' w/ pkr &  15% HCl. back onto packer. Run rods  60, 343 BW, Gas - TSTM.  DATE 7-30-08  companie sprione: 432-620-8480  AUG 0 5 2008