| • | | | | | | | | | | - | |
|--|--------------|------------------------------|-------------|---|--|--|---------------------------------------|-----------------|--|-----------------|-----------------|
| District I | Dr. Hobbe | NM 88240 | | St | tate o | f New Mex | tico | | | | Form C-141 |
| District II Energy Miner | | | ineral | Is and Natural Resources | | | | Revis | sed October 10, 2003 | | |
| 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 District III Oil Con | | | Conse | ervation Division | | | Sub | mit 2 Cop | pies to appropriate fice in accordance | | |
| District IV 1220 So | | | | uth St. Francis Dr. | | | D | with | Rule 116 on back side of form | | |
| | | | | | Fe, NM 87505 | | | | | | |
| | | | Rel | ease Notifi | catio | on and Co | orrective A | ction | | | |
| | | | | | | OPER A | | | Initial R | leport | X Final Repor |
| | | Americo Ene lipe, Ste 200 | | urces, LLC 1, TX 77063 | | Contact Osc Telephone 1 | car Nosrati No. 713-984-97 | 00 | | <u> </u> | |
| | | | | 30015050 | 287 | · · · · · · · · · · · · · · · · · · · | e Injection Wel | | | <u> </u> | |
| Surface Ow | mer BLM | | | Mineral (| Owner | BLM | Leas | Lease No. | | | |
| | | | | LOC | ATIO | N OF REI | LEASE | | | | |
| Unit Letter | Section | Township | Range | Feet from the | Nort | h/South Line | Feet from the | East/West Lir | | | |
| F | 34 | 18S | 31E | 2,310 | Nort | h | 2,310 | West | Edd | y | |
| L | 1 | I | La | titude | L | Longitud | ـــــــــــــــــــــــــــــــــــــ | L | - | | |
| | | | La | | | 0 | | | | | |
| Type of Rele | ase Produc | ed water and | oil | | UKH | COF RELI | Release 150 bbls | s Volum | e Recove | ered 130 | bbls |
| | | n relief valve | <u> </u> | | | Date and H | lour of Occurrenc | e Date a | nd Hour | of Disco | |
| Was Immedi | ate Notice (| Given? | | | | 6/24/2007 6/24/07 If YES, To Whom? | | | | | |
| | | X | Yes 🗌 | No 🗌 Not Req | uired | | | | | | |
| By Whom? Was a Water | | ched? | | | | Date and Hour 6/25/07 1:20 pm If YES, Volume Impacting the Watercourse. | | | | | |
| in as a mater | | | Yes X | No | | | nume impueting t | | | | |
| If a Watercou | irse was Im | pacted, Descri | ibe Fully.* | k | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| Describe Cau | se of Probl | em and Remed | dial Action | n Taken.* | | | | | | | |
| Injection wel | l supply lin | e ruptured, Re | placed lin | e. | | | | | | | |
| | | •••••••••••••• | | • | | | | | | | |
| | | | | | | | | | | | |
| Describe Are | a Affected : | and Cleanup A | Action Tak | en.* | | | | | | | |
| All work has | been perfor | med accordin | g to the ap | proved Workplar | n dated | February 8, 20 | 008 | | | | |
| | | | | | | | | | | | |
| | | | | is true and comp | | | | | | | |
| public health | or the envir | ronment. The | acceptanc | d/or file certain ro e of a C-141 repo | ort by th | ne NMOCD ma | arked as "Final Re | eport" does not | elieve th | e operato | or of liability |
| | | | | investigate and re tance of a C-141 | | | | | | | |
| | | vs and/or regu | | | | | | | | | |
| | | | | | | | OIL CONS | SERVATIO | <u>N DIV</u> | ISION | |
| Signature: | | | | | | | | | | | |
| Printed Name: Jerri Lee | | | | | Approved by District Supervisor: TGumby SB | | | | | | |
| Title: Consult | ant | | | | | Approval Date | 288 | Expiratio | 1 | NA | |
| | | | <u>_</u> | | | | | | | , | |
| E-mail Addre | ss: office@ | sesi-nm.com | | | | Conditions of Approval: \sim \sim \sim \sim \sim \sim \sim \sim \sim \sim | | | IN/A | | |
| | 22, 2008 | - ICNI- | | ne: 575-397-0510 | | | <u>۲</u> | V. | | <u>/) · · ·</u> | ι |
| Attach Addit | ional Shee | ets II Necessa | ary | | | r | | | -2K | V-14 | Q |
| | | | | | | | | | | 1 | |

1

Americo Energy Resources East Shugart Unit #15 Closure Report Unit F, Section 34, Township 18S, Range 31E Eddy County, New Mexico

July 31, 2008



Prepared for:

Americo Energy Resources 7575 San Felipe, Ste 200 Houston, TX 77063

By:

Safety & Environmental Solutions, Inc. 703 E. Clinton Hobbs, New Mexico 88240 (575) 397-0510

TABLE OF CONTENTS

•

| I. | COMPANY CONTACTS | | 1 |
|---------------|---|-----------|------------------|
| 11. | BACKGROUND | | 1 |
| 111. | SURFACE AND GROUND WATER | | 1 |
| IV. | WORK PERFORMED | | 1 |
| V. | CLOSURE PLAN | | 1 |
| VI. F F | FIGURES & APPENDICES Figure 1 - Vicinity Map Figure 2 - Site Plan Appendix A - Site Photos | | 1 2 3 4 |
| | | | |

I. Company Contacts

| NAME | Company | Telephone | E-mail |
|---------------|----------------|--------------|---------------------------------|
| Oscar Nasrati | Americo Energy | 713-984-9700 | Oscar.nosrati@americoenergy.com |
| Brian Cuellar | SESI | 505-390-7066 | bcuellar@sesi-nm.com |

II. Background

Safety and Environmental Solutions, Inc. (SESI) was engaged by Americo Energy Resources to perform cleanup services at the East Shugart Unit #15 spill site. This is an injection well site, in which the supply line ruptured, releasing 150 barrels of primarily produced water. A vacuum truck was utilized to remove the standing fluids.

III. Surface and Ground Water

The closest groundwater of record is in the same Section, Range and Township. The depth of water in this well was 261' in March of 1994.

IV. Work Performed

On April 30, 2008 SESI began remediation of the contaminated areas according to the approved workplan dated February 8, 2008. The entire spill area was excavated to a depth of 4'. Approximately 3,400 cubic yards of soil were transported to Lea Land, an NMOCD approved facility, for disposal. The bottom of the excavation was then lined with a 20-mil impervious liner to prevent and further migration of contamination left in place. The entire area was then backfilled using like soils and contoured to grade. Windrows were also installed to help with re-vegetation and the area was reseeded.

V. Closure Plan

It is requested that the spill report will be closed with no further remediation required.

VI. Figures & Appendices

Figure 1 – Vicinity Map Figure 2 – Site Plan Appendix A – Analytical Results Appendix B – Site Photos

Figure 1 Vicinity Map








Figure 2 Site Plan





Appendix A Site Photos


























William States and Sta ÈÈÉ (de la compañía de la compañía d CARAGE !! dhi.)