RECEIVED

District I 1625 N. French Dr., Hobbstoff 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road District IV 1220 S St. Francis Dr , Santa Fe, NM 87505

•

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action												
OPERATOR Initial Report Final Report												
Name of Co				ven M. Bishop								
			, N.M. 88240		Telephone No. (575) 397-8251							
Facility Nar	ne South	Hobbs Unit	System		Facility Type Production							
Surface Ow		· 1 D	Mineral C		т:	Deutuenalein		Lease No. (SHU #152 Inj Well)				
Occidental I	Permian Li	imited Partn	Occidenta	ll Permi	nian Limited Partnership			API No. 30-025-28355				
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the	North/	h/South Line Feet from the East/West Line County			County			
'A'	9	19 - S	38-E							LEA		
Latitude North 32°40'52.20" Longitude West 103°06'51.50"												
NATURE OF RELEA'SE												
Type of Rele	ase	·····			UTLL	Volume of Release Volume R				lecovered		
Injection War	ter					Estimated 100 BW			0 Bbls			
Source of Re		jection trunk	lina			Date and Hour of Occurrence 12/05/2008 05:00 PM			Date and Hour of Discovery 12/05/2008 05.00 PM			
Was Immedia						If YES, To		Whitaker	2/03/200	Jo 05.00 FM		
			Yes 🗌	No 🗌 Not R	equired	,						
By Whom?	Steven M. E	Bishop		······		Date and Hour 12/05/2008 05:23 PM						
Was a Water	course Read			•	If YES, Volume Impacting the Watercourse. N/A							
\Box Yes \boxtimes No												
If a Watercourse was Impacted, Describe Fully * N/A												
Describe Cau	se of Proble	em and Reme	dial Action	n Taken.* A 10"	cement	lined steel in	ection trunk line	from South	Hobbs	Unit Central T/B to South		
Hobbs Unit I	njection Bu	ilding #1 spli	t causing s	pill. Isolated the						Init #152 is the closest injector		
		this well was			ad is one	movimately 0	$0' \times 150'$ to the p	orth and sou	th of lo	ak site in the pasture. An		
estimated 100 bbls of produced water was spilled and 0 bbls were recovered. Piping was excavated and repaired, samples will be taken in affected area to insure area is in compliance with NMOCD guidelines for spills.												
I haraby garti	fy that the	nformation a	won about	is true and some	loto to ti	a host of my	knowledge and u	ndorstand th	hat nura	uant to NMOCD rules and		
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
								OIL CONSERVATION DIVISION				
Signature:	$\sum_{i=1}^{n}$	oron	SISH4	\mathcal{O}	Dohuson							
Bignature.			ð									
Printed Name	: Steven M	. Bishop			Approved by District ENEW ROUNMENTAL ENGINEER							
Title: HES S	pecialist					Approval Date: (2.(8.08 Expiration Date			Date: Z.18.09			
E-mail Addre	ss: Steven	B1shop@oxy	.com			Conditions of Approval:						
Date: 12/08/	2008		P	hone [.] (575) 397-8	251	SABMIT FINAL C. 141 W/Docs 112P # 2035						
have		Shoote If Ne					• • • • •		<u> </u>			


Attach Additional Sheets If Necessary

FGRL0835836222

SPILL MAP

PLEASE DRAW SKETCH OF SPILL AND INDICATE WHERE SPILL ORIGINATED.

12/05/2008 5:00pm 10" Comment lined Steel INJECTION TELLINE NOD# PSZ LIL'A', SEC. 9, T-1.9-S, R-38-E, N 320 40' 52.20", W103006'51.50" N O X 100 BW - ØBBL Recovered. MARK WHITAKOR 5:23PM DXY PERMIAN LAND DUINER



MITCHELL ANALYTICAL LABORATORY

2638 Faudree Odessa, Texas 79765-8538 561-5579

•

L

Company:	Nalco	Comp	any								
Well Number: Lease: Location:	South Ho OXY	obbs Inj	jection			Sample Temp Date Sampled Sampled by:	d: 8/28/	70 8/28/2008 Chase Alexander			
Date Run:	8/28/200					Employee #:					
Lab Réf #:	t: 08-aug-n42251					Analyzed by:	DOM				
				Dissolved (Tagos						
				Dissolveu	Juses	Mg/L	Eq. Wt.	MEq/L			
Hydrogen Sulf						346.00	16.00	21.63			
Carbon Dioxid	•	CO2)		NOT ANA				v			
Dissolved Oxy	gen (02)		NOT ANALYZED							
				Cations							
Calcium	•	Ca++)				549.78	20.10	27.35			
Magnesium	,	Mg++)				144.74	12.20	11.86			
Sodium		Na+)				2,676.14	23.00	116.35			
Barium	•	Ba++)		NOT ANAL	YZED		07 50	00			
Manganese	l	Mn+)				.03	27.50	.00			
				Anions							
Hydroxyl	•	OH-)				.00	17.00	.00			
Carbonate	•	CO3=)				.00	30.00	.00			
BiCarbonate	•	(HCO3-)				1,784.12	61.10	29.20			
Sulfate	•	SO4=)				525.00	48.80	10.76			
Chloride	(Cl-)				4,104.51	35.50	115.62			
Total Iron	(Fe)				0.13	18.60	.01			
Total Dissolve				10,130.45							
Total Hardnes				1,967.88							
Conductivity M	1ICROMH	DS/CM				15,460					
рН	6.720				Specifi	ic Gravity 60/	'60 F.	1.007			
CaSO4 Solubili		13.	36MEq/L,	CaSO4	scale is unlike	ely					
CaCO3 Scale Index											
70.0	.53	34	100.0	.884	130.	0 1.3	394				
80.0	.66	64	110.0	1.124	140.	0 1.3	394				
90.0	.88	34	120.0	1.124	150.	0 1.0	624				

Nalco Company



December 08, 2008

RECEIVED

DEC 1 0 2008

New Mexico Oil Conservation Division District I 1625 N. French Drive Hobbs, New Mexico 88240

HOBBSOCD

Attn: Environmental Engineering

RE: Remediation Plan South Hobbs Unit 10" Injection Trunk line from Central T/B to Injection Building #1 SHU #152 Closest Injector API No 30-025-28355 UL 'A', Sec. 9, T-19-S, R-38-E

Leak occurred on 12/05/2008, at approximately 05:00 PM. A 10" cement lined steel trunk line used to transfer injection water from South Hobbs Unit Central T/B to South Hobbs Unit Injection Building #1 split causing spill. Valves on both ends of the trunk line were shut to isolate leak. The line operates at approximately 1100 pounds with an unknown bbls per day rate, due to several lines delivering approximately 90,000 bbls to the South Hobbs Unit Injection System. The area affected by this spill is an area measuring approximately 90' X 150' to the north and south of the leak site in the pasture. An estimated 100 barrels of injection water was spilled with none recovered. Occidental Permian Limited Partnership is the surface owner and utilizes the area for oil and gas production exclusively. Depth to ground water according to State Engineers Office is an average of 53', for all wells in the area, giving this spill site a ranking of 10. Remediation of the spill site will be as follows:

- 1. Piping has been excavated and repaired.
- 2. Affected area will be excavated and affected soil will be disposed of at Sundance Services, Parabo facility near Eunice, NM.
- 3. Soil samples will be gathered from affected area.
- 3. NMOCD guidelines will be used to insure entire site is in compliance with guidelines.
- 4. Soils removed will be replaced with clean fresh soils, where needed.
- 5. Soil analysis data will be submitted with final closure letter.

December 8, 2008 Page 2

If you have any questions, or if I can be of further assistance, please contact me at (505) 397-8251.

STORON M. SISKO

Steven M. Bishop HES Specialist/Central Operating Area Steven_Bishop@oxy.com (575) 397-8251

Attachments: Initial C-141 Hand drawn map of spill site Analytical data of South Hobbs Unit Injection Water dated 8/28/2008

1

ζ