

Rec 13 4/9/09

Form C-141 Revised October 10, 2003

side of form

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back

District I 1625 N French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District III 1000 Rio Brazos Road, Aztec, NM 87410 State of New Mexico Energy Minerals and Natural Resources Oil Conservation Division

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

- 1						
	30-0	15-	21	103	1	

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Release Notification and Corrective Action

MCB 0910	448390		•		OPERATOR Initial Report Final Report							
Name of Company SOUTHWEST ROYALTIES, INC.						Contact DAWN M. HOWARD						
Address 6 DESTA DRIVE, STE 2100, MIDLAND, TX 79705						Telephone No. 432/688-3267						
Facility Name WILDERSPIN FEDERAL						Facility Type BATTERY – closest to well #1						
Surface Owner BLM –grazing permit allottee Mineral Owner Winston Ballard #77020)wner	·BLM/SWR Lease				No. NMNM1478B/16282		
LOCATION OF RELEASE												
Unit Letter F	Section 11	Township 21S	Range 27E	Feet from the 1980	North N	/South Line	Feet from the 1980	East/V W	t/West Line County EDDY			
	LatitudeLongitude											
NATURE OF RELEASE												
Type of Rele		OIL					Release ~115				57	
Source of Re	lease	HOLE IN	N TANK			Date and Hour of Occurrence 4/1/09 midnight			Date and Hour of Discovery 4/2/09 10:30 a.m.			
Was Immedia	ate Notice (If YES, To Whom?						
			Yes 📙	No Not Re	equired	NMOCD -	Mike Bratcher; I	3LM – J	im Amos			
By Whom?						Date and Hour 4/2/09 11:30 a.m.						
Was a Water	Was a Watercourse Reached? ☐ Yes ☑ No If YES, Volume Impacting the Watercourse.											
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.* A hole in the side of oil stock tank at the battery was discovered when the pumper gauged. The tank will be repaired.												
Describe Area Affected and Cleanup Action Taken.* All oil was contained within the firewall. Vacuumed and recovered 57 Bbls of oil. A backhoe was used to scrape and dust location due to cattle in the area. An environmental contractor's services have been obtained to analyze and aid in the efforts to remediate this location.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
				OIL CONSERVATION DIVISION								
Signature:	Jain	m. T		Approved by District Supplies & Lances								
Timed (dane. DAW) W. Howards												
Title:	OPERA	TIONS ASSIS	STANT			Approval Date	PR 1 7 200)9 _E	xpiration I	Date:		
E-mail Addres	ss: <u>DHOW</u>	ARD@CLAY	<u>TONWILI</u>	JAMS COM		Conditions of	Approval: Beme	diatun	per		_	
Date: 4/3/09	Phone: 43	32/688-3267		Conditions of Approval: Fremediation per Och Pules & Guide lines Attached								
A 1 A 11'4'	anal Chan	- ICNI								1		

* Attach Additional Sheets If Necessary

2RP-300

4/17/09

NOTE: Excauster of improbal material has commend & vem-diation is ongoing.

New Mexico Office of the State Engineer **POD Reports and Downloads**

Township: 21S Range: 27E Sections:

NAD27 X:

Y:

Zone:

Search Radius:

County:

Basin:

Number:

Suffix:

Owner Name: (First)

(Last)

ONon-Domestic ODomestic All

POD / Surface Data Report

Avg Depth to Water Report

Water Column Report

Clear Form

iWATERS Menu

Help

AVERAGE DEPTH OF WATER REPORT 04/13/2009

								(nebtu	water in	reet)
Bsn	Tws	Rng	Sec	Zone	x	Y	Wells	Min	Max	Avg
С	21S	27E	01				1	186	186	186
С	21S	27E	05				1	350	350	350
С	21S	27E	06				1	175	175	175
С	21S	27E	09				2	80	120	100
C	215	27E	19	***********			29	20	137	44
С	21S	27E	21				1	75	75	75
С	21S	27E	24	1			2	17	21	19
С	21S	27E	25				6	5	178	67
С	21S	27E	26				4	5	70	38
С	21S	27E	28				4	16	46	36
С	21S	27E	29				37	8	256	35
С	21S	27E	30				68	10	217	26
С	21S	27E	31				16	5	40	19
С	21S	27E	32				10	11	32	18
С	21S	27E	35				1	30	30	30

Record Count: 183

TREND MAP = 25-50'





Bratcher, Mike, EMNRD

From: Mark Staley [mark@sportenvironmental.com]

Sent: Thursday, April 16, 2009 12:25 PM

To: Bratcher, Mike, EMNRD

Cc: Debi Moore

Subject: Southwest Royalties - Wilderspin Federal Battery

Attachments: SWR Wilderspin.pdf

Mike,

Attached is a diagram of the battery with hot spots. The client is going to remove the tanks from the battery so we can further delineate the spill. As soon as we get to that point and receive our analysis back we will send in a C-141. I just wanted to keep you updated on the status of the battery.

Thank you and have a great day,



MARK E. STALEY

Environmental Coordinator

Sport Environmental Services, PLLC 502 North Big Spring Street Midland, Texas 79701 mark@sportenvironmental.com Business: 432.683.1100

Fax: 888.500.0622 Cell: 432.631.1401

This inbound email has been scanned by the MessageLabs Email Security System.

