GW - 301

INSPECTION

(Drain-lines, Sump, BGT, Site, etc.)

Lowe, Leonard, EMNRD

From:

Fernald, Donald [dfernald@epco.com]

Sent:

Friday, August 14, 2009 11:59 AM

To:

Lowe, Leonard, EMNRD; Hebert, Beth; Powell, Brandon, EMNRD

Cc:

Seale, Runell; Lee, Stephen

Subject:

RE: GW-301, Inspection Report Response (Manzanares CS)

Hi Leonard.

T411 & T412 are no longer in service.

Thanks,

Don Fernald EHS&T 614 Reilly Avenue Farmington, NM 87401 O: 505-599-2141

C: 505-486-6668 F: 505-599-2119 dfernald@epco.com

From: Lowe, Leonard, EMNRD [mailto:Leonard.Lowe@state.nm.us]

Sent: Friday, August 14, 2009 11:43 AM **To:** Hebert, Beth; Powell, Brandon, EMNRD

Cc: Fernald, Donald; Seale, Runell

Subject: GW-301, Inspection Report Response (Manzanares CS)

Ms. Hebert,

The OCD appreciates Enterprises efforts in resolving the inspection results.

Below-grade tanks: please submit a work plan for the removal of T411 and T412. Any particular reason for the BGT removals?

Submit the evaluation and proposed work on the AST's when completed. Provide OCD a status on September 25, 2009 if the evaluation has not been resolved.

Two items are still considered open from the inspection results.

Thank you for your attention.

llowe

Leonard Lowe

Environmental Engineer Oil Conservation Division/EMNRD 1220 S. St. Francis Drive Santa Fe, N.M. 87505 Office: 505-476-3492

Lowe, Leonard, EMNRD

From:

Lowe, Leonard, EMNRD

Sent:

Friday, August 14, 2009 11:43 AM

To:

'bhebert@eprod.com'; Powell, Brandon, EMNRD

Cc:

'Fernald, Donald'; Seale, Runell

Subject:

GW-301, Inspection Report Response (Manzanares CS)

Ms. Hebert,

The OCD appreciates Enterprises efforts in resolving the inspection results.

Below-grade tanks: please submit a work plan for the removal of T411 and T412. Any particular reason for the BGT removals?

Submit the evaluation and proposed work on the AST's when completed. Provide OCD a status on September 25, 2009 if the evaluation has not been resolved.

Two items are still considered open from the inspection results.

Thank you for your attention.

llowe


Leonard Lowe

Environmental Engineer Oil Conservation Division/EMNRD 1220 S. St. Francis Drive Santa Fe, N.M. 87505 Office: 505-476-3492

Fax: 505-476-3462

E-mail: leonard.lowe@state.nm.us

Website: http://www.emnrd.state.nm.us/ocd/



August 7, 2009

ENTERPRISE PRODUCTS PARTNERS LP ENTERPRISE PRODUCTS OPERATING LLC

ENTERPRISE PRODUCTS GP, LLC, GENERAL PARTNER ENTERPRISE PRODUCTS OLPGP, INC., SOLE MANAGER

Certified Mail 7008 3230 0002 4472 9461

Mr. Glenn von Gonten, Acting Environmental Bureau Chief New Mexico Energy, Minerals and Natural Resources Department New Mexico Oil Conservation Division 1220 St. Frances Drive Santa Fe. NM 87505

Re: Enterprise Field Services, LLC

Manzanares Compressor Station -GW-301 SW/4, NW/4, Section 33, Township 30 North, Range 7 West, NMPM San Juan County, NM

Dear Mr. von Gonten:

Enterprise Field Services, LLC is submitting this letter in response to the site inspeciton conducted at the Manzanares Compressor Station on June 10, 2009, and items listed in Number 16 of the Discharge Permit approval conditions.

- 1. Liquids will be removed from sumps within 72 hours. During the NMOCD inspection, the facility had experienced precipitation the prior 48 hours.
- 2. On July 23, 2009 attempts to collect a sample of the liquids within the secondary wall of BGT T411 were unsuccessful using a pump and tube. It appears that less than ½" of liquid is located within the secondary wall of BGT T411. BGT T411 and T412 will be scheduled for removal in late 2009. Below Grade Tanks (BGTs) are currently being inspected on a monthly basis. A copy of the most recent inspection is included as Attachment "A".
- 3. Enterprise is currently evaluating the liquid handling process at Manzanares Compressor Station. Once this evaluation is completed, the condensate storage tanks from the location will either be removed or kept in place. If storage tanks remain in service, an impervious secondary containment will be installed on the applicable tanks in 2010. Please note that Tanks T406, T407, T408 and T409 do have a liner in place. Signage and labels are currently being upgraded in accordance with our discharge permit.

If you have questions or require additional information, please contact Don Fernald, Environmental Scientist at (505) 599-2141 or me directly at (713) 381-6518.

Yours truly,

Mary E Hebert

Director, Environmental Compliance

/sjn

#tackuriys4 HOUSTON, TX 77210-4324 713.381.6500

1100 LOUISIANA STREET HOUSTON, TX 77002-5227 www.epplp.com

Attachment A

Monthly SPCC Inspection Form / NMOCD Discharge Plan Inspection Form

MONTHLY SPCC INSPECTION FORM / NMOCD DISCHARGE PLAN INSPECTION FORM

y 3 m b

Manzanares Canyon Compressor Station

Page 1 of 2				Tank Fland	ID Alternation			
if Ves and insert Work Request number.	T-401 500 Gas	T-632 500 Gail	T-403 500 Ctal	Tanûk Field	T-426 75 B2/ 69T	T-406 1000 (\$5.8	T-487 1900 Day	T-600 1:000 E21
A yes answer indicates that there is a deficiency and correction(s) are required.	Lube 04	Late Oil	Lube Of	Lube Off	Comp Sidd flump	Condensate Storage	Condensus \$1309	Condensate Storage
				I SITIK ASSSI	Number			
Leakage is detected at seam connections, comosion or gaskets.								
Leakage is detected at ancelary equipment, gauges and instrumentation.								
Leakage is detected from pumps, piping and fittings.								
Secondary containment is in substandard condition, cracks, breaches, leaks or damage is apparent or likely.								
Leakage is accumulating in area drains or disches.								
Subgrade tank portal inspection indicates leaks.								
Leakage is accumulating in clike, of applicable.								
Any leatage/stained soil noted on site (if so, state in notes/comments)								
Any other issues noted? Please list in comments.				<u>.</u>				
Enter Work Request Number for Corrective Actions								
Enter Work Order Number for Corrective Actions								
NOTES:	Sems on large taris	s (1,000 BBL) has	an opening on Sem	nfor Load line!				
Check III appropriate boxes as indicated. If leakage is noted, please with in the early order number in the appropriate box.	•							
COMMENTS:								
Sand completed fortion to Environmental Representative to be retained for the	as lear						-	
Inspector And And					Deces	July-29-09		
Screwing					Deze			
Page 2 of 2								
G if Ves and invert Work Request number		1419 120 81/ BOT	Tatt 188 En boll		ID Number	T		I.
② if Yes and insert Work Request number. A yes answer indicates that there is a deficiency and	T-408 1990 SSS Condensate Statege	T-429 120 Stor Bust Produced Water Sump	E-411 188 Est boll Theoreal Oxidinat Sures	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege	T-414 506 Bzs Gonderwste Szorege	T-413 S0 (0.5) (0.01) Fig Receiver Stattp	F-itis 200 Gai TEG Stockge
		Panduced Water	Commel Childhan	T-412 156 Ebi Olycol Storage	\$-413 210 Etd		T-415 SD 813' BOST Pig Receiver SEETD	
A yes answer indicates that there is a deficiency and		Panduced Water	Commel Childhan	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-415 50 800 800 BOT PRO RECEIVED	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrosion or gaskets. Leakage is detected at anothery equipment, gauges and		Panduced Water	Commel Childhan	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-15 SD Rui BOI Fig Receiver Stamp	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrosion or gaskets.		Panduced Water	Commel Childhan	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-115 SO BUI DOT Plig Receiver Sump	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrosion or gaskets. Leakage is detected at anothery equipment, gauges and instrumentation.		Panduced Water	Commel Childhan	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-13 SO RJ: DOTO: Rig Reserver Sutto	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrosion or gaskets. Leakage is detected at anothery equipment, gauges and instrumentation. Leakage is detected from pumps, opting and fittings. Secondary containment is in substandard condition, cracks,		Panduced Water	Thermal Duddmar	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-415 SO BUI SO(I) Mg Receiver Surro	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrosion or gaskets. Leakage is detected at anothery equipment, gauges and instrumentation. Leakage is detected from pumps, opting and fittings. Secondary containment is in substandard condition, cracks, breaches, tests or damage is apparent or skety.		Panduced Water	Thermal Duddmar	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-13 SO RJI DOTO Rig Reserver SETTP	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrosion or gaskets. Leakage is detected at anothery equipment, gauges and instrumentation. Leakage is detected from pumps, opting and fittings. Secondary containment is in substandard condition, cracks, breaches, teaks or damage is apparent or likely. Leakage is accumulating in area drains or disches.		Panduced Water	Thermal Duddmar	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-13 SO BJ 601 Pig Reserver Sutto	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrosion or gaskets. Leakage is detected at anothery equipment, gauges and instrumentation. Leakage is detected from pumps, opting and fittings. Secondary containment is in substandard condition, cracks, breaches, texts or damage is apparent or likely. Leakage is occumulating in area drains or disches. Subgrade tank portal inspection indicates leaks.		Panduced Water	Thermal Duddmar	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-13 SO RJI DOZIN	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrosion or gaskets. Leakage is detected at anothery equipment, gauges and instrumentation. Leakage is detected from pomps, opting and titings. Secondary containment is in substandard condition, cracks, treaches, texts or damage is apparent or likely. Leakage is accumulating in area drains or disches. Subgrade tank portal inspection indicates leaks. Leakage is accumulating in diet, of applicable. Any testage/stained soil noted on site (if so, state in		Panduced Water	Thermal Duddmar	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-13 SO BJ DJ DJ Pg Racehve Suttp	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrosion or gaskets. Leakage is detected at anothery equipment, gauges and instrumentation. Leakage is detected from pumps, opting and fittings. Secondary containment is in substandard condition, cracks, breaches, leaks or damage is apparent or likely. Leakage is accumulating in area drains or disches. Subgrade talls portal inspection indicates leaks. Leakage is accumulating in dike, if applicable. Any leakage/stained soll noted on site (if so, state in notes/comments)		Panduced Water	Thermal Duddmar	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-13 SO RJI DOZI Rig Reserver Sutto	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, contotion or gaskets. Leakage is detected at anothery equipment, gauges and instrumentation. Leakage is detected from pumps, oping and fittings. Secondary containment is in substandard condition, cracks, treaches, tests or damage is apparent or likely. Leakage is accumulating in area drains or disches. Subgrade tank portal inspection indicates (eaks.) Leakage is accumulating in dike, diapplicable. Any leakage/stained soll noted on site (if so, state in notes/comments).		Panduced Water	Thermal Duddmar	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-13 SO BJ DJ PJ Racehve Sutto	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrosion or gaskets. Leakage is detected at anothery equipment, gauges and instrumentation. Leakage is detected from pomps, opting and titings. Secondary containment is in substandard condition, cracks, breaches, tests or damage is apparent or likely. Leakage is accumulating in area drains or disches. Subgrade tank portal inspection indicates leaks. Leakage is accumulating in dite, if applicable. Any leakage/stained soil noted on site (if so, state in notes/comments) Any other issues noted? Please list in comments. Enter Work Request Number for Corrective Actions		Panduced Water	Thermal Duddmar	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-13 SO BJ DJ PJ Racehve Sutto	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrosion or gaskets. Leakage is detected at anothery equipment, gauges and instrumentation. Leakage is detected from pumps, opting and fittings. Secondary containment is in substandard condition, cracks, breaches, jeaks or damage is apparent or likely. Leakage is accumulating in area drains or disches. Subgrade tank portal inspection indicates leaks. Leakage is accumulating in dite, if applicable. Any leakage/stained soil noted on site (if so, state in notes/comments) Any other issues noted? Please list in comments. Enter Work Request Number for Corrective Actions Enter Work Order Number for Corrective Actions	Condensate States 20	Panduced Water	Thermal Duddmar	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-13 SO RJI DOTO Rig Reserver Sutto	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrosion or gaskets. Leakage is detected at anothery equipment, gauges and instrumentation. Leakage is detected from pumps, opting and fittings. Secondary containment is in substandard condition, cracks, treaches, jetits or diamage is apparent or likely. Leakage is accumulating in area drains or disches. Subgrade tank portal inspection indicates leaks. Leakage is accumulating in dite, if applicable. Any leakage/stained soll noted on site (if so, state in notes/comments) Any other issues noted? Please list in comments. Enter Work Request Number for Corrective Actions Enter Work Order Number for Corrective Actions Enter Work Order Number for Corrective Actions Creek & appropriate boxes as indicated, if leakage is noted, plasms write in the	Condensate States 20	Panduced Water	Thermal Duddmar	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege		T-13 SO RJI DOT Rig Reserver Sutto	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrotion or gaskets. Leakage is detected at anothery equipment, gauges and instrumentation. Leakage is detected from pumps, opting and fittings. Secondary containment is in substandard condition, cracks, treaches, jeaks or damage is apparent or likely. Leakage is accumulating in area drains or disches. Subgrade tank portal inspection indicates leaks. Leakage is accumulating in die, if applicable. Any leakage/stained soil noted on site (if so, state in notes/comments) Any other issues noted? Please list in comments. Enter Work Request Number for Corrective Actions Enter Work Order Number for Corrective Actions Enter Work Order Number for Corrective Actions Contains in the appropriate tone as indicated. If leakage is noted, plants write in the appropriate con. (CORMENTS)	Condensate States po	Panduced Water	Thermal Duddmar	T-412 156 Ebi Olycol Storage	T-813 210 EM Condensite Statege	Dondernata Bronga	T-13 SO RJI DOT Rig Reserver Setto	
A yes answer indicates that there is a deficiency and correction(s) are required. Leakage is detected at seam connections, corrosion or gaskets. Leakage is detected at anothery equipment, gauges and instrumentation. Leakage is detected from pumps, opting and titings. Secondary containment is in substandard condition, cracks, treaches, leaks or damage is apparent or allely. Leakage is accumulating in area drains or disches. Subgrade tank portal inspection indicates leaks. Leakage is accumulating in dite, of applicable. Any leakage/stalined soft noted on site (if so, state in notes/comments) Any other issues noted? Please list in comments. Enter Work Request Number for Corrective Actions Enter Work Order Number for Corrective Actions Series Work Order Number for Corrective Actions Series that appropriate tones as indicated, if leakage is noted, please write in the appropriate con. SWANDENTS: Supplied-11 to be removed.	Condensate States po	Panduced Water	Thermal Duddmar	T-412 156 Ebi Olycol Storage	F-413 210 Etal Condonata Strange III Di Number		T-13 SO BJ DJ DJ Pg Racehve Sutto	

GW-301, Manzanares CS

Inspection noted on last permit renewal.
Response was submitted within prescribe time.
See "PERMITS" for photographs attached to the latest permit.

- **16. OCD Inspections:** The OCD performed an inspection of this facility on June 10, 2009. Mr. Clay Roesler and Runell Seale witnessed the inspection. All photographs referenced below are located in the attachment of this permit. As a result of this, OCD inspection concluded the following:
 - 1. Photo 1 & 2: Owner/operator shall verify that sumps are maintained per Condition 11 of this permit.
 - 2. Photo 3 5: The facility has 4 below grade tanks. They are all designed with a secondary containment (tank within a tank design) with a leak detection system. A proper cap shall be placed on the leak detection view port. All leak detection systems were all found to be dry, except for T411. There appeared to be a vicious fluid substance within the annular walls of the BGT. Owner/Operator shall investigate the reason for fluids in the leak detection system and if need be verify tank integrity. During the inspection, the leak detection system for all BGT ports were not easily accessible indicating that the leak detection system are not frequently inspected. The owner/operator shall monitor and keep record of these leak detection systems on a monthly basis. See Condition 11 for details.
 - 3. Photo 6 & 7: All above ground storage tanks (AST) must be properly lined. There appears to have been some overflow of contents in one tank. The owner/operator shall submit to the OCD a work plan to line all above ground storage tanks. See Condition 9 for details. This was also noted in the 2003 permit, Condition 7. At the time of inspection tanks were still not lined. Enterprise is currently in violation of their discharge permit.

Enterprise shall resolve items 2 and submit a work plan for item 3 by August 10, 2009.