District I 1625 N. French Dr , Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410

State of New Mexico

Energy Minerals and Natural Resources

NOV U 9 years, Oil Conservation Division 1220 South St. Francis Dr. HOBBSUGD

WATER 966

Form C-141 Revised October 10, 2003

District IV 1220 S. St Francis Dr , Santa Fe, NM 87505 Submit 2 Copies to appropriate
District Office in accordance with Rule 116 on back side of form

	,	, t		2:	anta 1	e, NM 8/3	05				
			Relo	ease Notific	catio	on and Co	rrective A	ction			
						OPERA	ΓOR	🛭 Initi	al Report		Final Report
Name of Co	mpany A	merico Ener	gy Resou	rces, LLC		Contact Ehsan Bayat					
Address 7575 San Felipe Ste 200 Houston, TX 77063						Telephone No. 713-984-9700					
Facility Name BC Dickinson D Battery						Facility Type Battery					
Surface Owner Mineral Owner LOCATIO						NOF RELEASE NEARRY WELL API # 30-025-0517			178-00-00		
Unit Letter	Section	Township	Range	Feet from the	Nort	h/South Line	Feet from the	East/West Line	County		
	35	14S	37E						LEA		
			La	titude		Longitud	le				
NATURE OF BUILDING											

NATURE OF RELEASE Type of Release Oil and Produced Water Volume Recovered 0 Volume of Release 55 bbls Source of Release Heater treater Date and Hour of Occurrence Date and Hour of Discovery 11/4/09 2:30 11/4/09 2:31 Was Immediate Notice Given? If YES, To Whom? Maxey Brown By Whom? Bruce Madden Date and Hour 11/4/09 2:34 Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ⊠ No If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The heater at the BC Dickinson D battery blew a 2" welded collar and bull plug out of the bottom of it, (below water leg). The heater treater released 15 bbls of oil and 40bbls of produced water.

- 1. NMOCD was immediately notified.
- 2. Vacuum was called to the site to clean site
- 3. Back hoe and called to site for remediation.

Describe Area Affected and Cleanup Action Taken.*

Release breached firewall and went to west side of battery. Most of the fluid stayed on lease road, except for an area of 15X30 ft.

Vacuum truck and back hoes were immediately contacted to clean spill and perform remediation work on the site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other

federal, state, or local laws and/or regulations.								
-0 0 m A	OIL CONSERVATION DIVISION							
Signature:								
Duinted News a Chean Dayet	Approved by District Supervisor. Therefore Johnson							
Printed Name: Ehsan Bayat	Theifflow delling							
Title: Regulatory Analyst	Approval Date: 12120109 Expiration Date: 0212740							
E-mail Address: Ehsan.bayat@americoenergy.com	Conditions of Approval: DELINEATE TO Attached							
Date: 11/4/09 Phone: 713-984-9700	Conditions of Approval: DELINEATE TO CLEAN +1. SUBMIT FINAL C-141 BY 02/22/10. Attached IRP-09.11.2339							

^{*} Attach Additional Sheets If Necessary