District I 1625 N French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

Form C-141 SEP 17 2010 Revised March 17, 1999

HOBBS Submit 2 Copies to appropriate of the cordance with Rule 116 on back side of form

Release Notification and Corrective Action OPERATOR Initial Report Final Report Name of Company BTA Oil Producers LLC Contact Skip Baca or Pam Inskeep 104 S. Pecos, Midland, TX 79701 (432) 682-3753 Address Telephone No. Facility Name Hartley, 8609 JV-P Facility Type Well Mineral Owner Lowe et al Surface Owner Loretta Lowe Lease No. LOCATION OF RELEASE API #30.025.29800.00.00 Township Feet from the North/South Line Unit Letter Section Range Feet from the East/West Line County 37E 26 13S 1650 South 330 East Lea I NATURE OF RELEASE

Produced Water Volume of Release 120 bbls Type of Release Volume Recovered 10 bbls Source of Release Lightning Strike Date and Hour of Occurrence Date and Hour of Discovery evening CDT, 09/15/2010 8 am CDT, 9/16/2010 Was Immediate Notice Given? If YES, To Whom? Geoffrey Leking, Hobbs ☐ Yes ☐ No ☐ Not Required Clay Tipton, Field Supervisor Date and Hour By Whom? 8:30 am CDT 9/16/2010 If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* A field employee of another company passed by our location and saw damage to the water tank. He immediately called our contract pumper, Refugio Porras, who was making his rounds but had not arrived at this location yet. Our pumper immediately called his Field Supervisor, Clay Tipton, and headed for the location. Clay called BTA's office and the OCD, Hobbs, Geoffrey Leking, NMOCD Investigator, and also headed for the location. Upon arriving at the location, the pumper found that lightning had stuck the 500 bbl metal water tank and blown the top and sides off of the tank base. The top of the tank was approximately 100 ft from the tank pad. The contents of the tank had released onto the location. All product remained on the location site. A vacuum truck was dispatched to recover all produced water possible. BTA's Environmental Coordinator will assess the site and determine any further remediation activities. The destroyed tank will be removed from the site and replaced with another. Describe Area Affected and Cleanup Action Taken.* See above explanation I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by District Supervisor. Printed Name: Pam Inskeep Approval Date: 09/20/10 Expiration Date: W2210 Title: Regulatory Administrator

Attached | 09/16/2010 Conditions of Approval: DETINEATE TO Phone: (432) 682-3753 Date:

CLEAN +1. SUBMIT FINAL C-141

IRP-10-9-2611