



<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210				New Mexico and Natural Resources			Form C-141 Revised October 10, 2003				
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505		1220	) Sou	ervation Div th St. Franc Fe, NM 875	is Dr.		Submit 2 Copics to appropria District Office in accordanc with Rule 116 on bac side of form				
30-015-31891	Rele				orrective A	ctión				<u> </u>	
nKmu 110764000	KCIC		Latit	OPERA		• • • • • • •	🛛 Initia	Doport		Final Report	
Name of Company COG OPERAT	ING LL	C 22913	1		anicia Carrillo			al Report	ليا	r mai repoi	
Address 550 W. Texas, Suite 100 Midland, TX 79701					Telephone No. 432-685-4332						
Facility Name – Holder CB 6&7				Facility Type- Battery							
Surface Owner Federal		Mineral (		Lease No. NMLC056551A							
SW1/4-NW1/4	LOCATION OF RELE					SE					
	Range 30E	Feet from the	Nort	th/South Line	Feet from the	e East/West Line County Eddy					
Driving directions to battery: From	Loco Hi			217 .9 m – tu le Longita		turn N	orth .3 m	ı – turn E:	ast .1 i	n to locatio	
		NAT	<b>FURI</b>	E OF REL	EASE						
Type of Release- Oil				Volume of	Release-80 bbls lour of Occurrenc			Recovered-			
Source of Release- Circulating Pump	Source of Release- Circulating Pump					e-	Date and Hour of Discovery 12/22/09				
Was Immediate Notice Given?	12/22/09 If YES, To	Whom?		12/22/09							
🛛 Y	res 🔲	No 🗌 Not Re	equired								
By Whom? Pat Ellis		Date and Hour 12/23/09 4:44pm									
Was a Watercourse Reached?				If YES, Ve	If YES, Volume Impacting the Watercourse.						
Describe Cause of Problem and Remedi	al Action	Takan *									
Circulating pump discharge piping failed											
Describe Area Affected and Cleanup Ac Scraped battery pad(minimal contaminat environmental land fill. Tetra Tech will sample the spill site area NMOCD for your approval prior to any	tion)-Top	dressed pad w/	e conta				_				
I hereby certify that the information give regulations all operators are required to public health or the environment. The a should their operations have failed to ad or the environment. In addition, NMOC federal, state, or local laws and/or regula	report and cceptance equately CD accept	d/or file certain i e of a C-141 rep investigate and i	release ort by remedi	notifications a the NMOCD m ate contaminat	nd perform correc arked as "Final R on that pose a thre e the operator of i	tive acti eport" de eat to gro responsi	ons for rel oes not rel ound wate bility for c	eases which ieve the ope r, surface w ompliance v	rator o ater, hu with an	ndanger f liability ıman health	
k = -				OIL CONSERVATION DIVISION							
Signature:				Approved by District Supervisor.							
Printed Name: Kanicia Carrillo Title: Regulatory Analyst				Approval Date: 3/17/11 Expiration Date:							
E-mail Address: kcarrillo@conchoresou	urces.com	1		Conditions o	f Approval:						
Date: 1/06/10 Ph	none: 432	2-685-4332		-	DIATION per (	OCD R	ules and	ttachec	_		
* Attach Additional Sheets If Necessar	ŗy				es. <u>SUBMIT RI</u>			6	<i>ar</i>	P-64	



### Bratcher, Mike, EMNRD

From: Sent: To: Subject: Pat Ellis [PEllis@conchoresources.com] Wednesday, December 23, 2009 3:44 PM Bratcher, Mike, EMNRD; 'terry\_gregston@nm.blm.gov' Fw: Spill Report

Mike,

I wanted to give you notification of a spill. We will send Tetra Tech next week to access the spill. Have a good holiday. Thanks, Pat.

----- Original Message -----From: Ronnie Tice To: Pat Ellis; Kanicia Castillo Cc: Kent Greenway Sent: Wed Dec 23 14:04:51 2009 Subject: Spill Report

Spill report for Holder CB 6-7 battery:

Date of occurrence: Tue22Dec09

Location of occurrence: Holder CB Fed 6-7 Battery

Legal Description of battery: SW1/4-NW1/4-Sec17-T17S-R30E

Driving directions to battery: From Loco Hills go North on CR217 .9 m - turn West .6 m - turn North .3 m - turn East .1 m to location

Cause of occurrence: Circulating pump discharge piping failed

Estimated release volume: 80 bbls

Composition of released product: 100% crude oil

Immediate action taken: Vac trucked up est. 30 BO – Scraped battery pad(minimal contamination)-Top dressed pad w/clean material-picked up top 6" of contaminated top soil on edge of pad and hauled to environmental land fill

Remedial action: Will wait for orders to cover edge of pad area in the event that soil sampling may be ordered

This inbound email has been scanned for malicious software and transmitted safely to you using Webroot Email Security.



## Bratcher, Mike, EMNRD

From:	Kanicia Castillo [KCarrillo@conchoresources.com]
Sent:	Wednesday, January 06, 2010 3:37 PM
To:	Bratcher, Mike, EMNRD; terry_gregston@nm.blm.gov
Cc:	Pat Ellis
Subject:	Skelly Unit 989 C141 & Holder CB Federal 6&7 C141
Attachments:	Skelly Unit 989 battery C141 122609.pdf; Holder CB Federal 6&7 C141 122209.pdf

Hi,

Please, let me know if you need anything else.

Thank you,

# Kanicia Castillo

Regulatory Analyst COG OPERATING LLC 550 W. Texas Avenue, Suite 100 Midland, Texas 79701 p.432.685.4332 f.432.685.4396

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

This inbound email has been scanned for malicious software and transmitted safely to you using Webroot Email Security.