

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
2040 South Pacheco  
Santa Fe, NM 87505

**HOBBS OCD**

**JUN 09 2011**

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**RECEIVED**

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name: Range Resources	Contact: Brian Kindred
Address:	Telephone No. 575-602-1788
Facility Name: Grizzle B Battery	Facility Type: Battery

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

**LOCATION OF RELEASE** *NEARBY WELL GRIZZLE B #004*  
*30-025-26713-00-00*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	8	22S	37E					Lea. NM

**NATURE OF RELEASE**



Type of Release: Crude Oil	Volume of Release: 65 BBLS	Volume Recovered: 60 BBLS
Source of Release: Overflow	Date and Hour of Occurrence: 5/28/11 10 am	Date and Hour of Discovery: 5/28/11 1:30 PM
Was immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoff Lcking NMOCD	
By Whom? Isaac Kincaid, SESI	Date and Hour: 5/28/11 4:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: N/A	

If a Watercourse was Impacted, Describe Fully.\*  
No water was impact

Describe Cause of Problem and Remedial Action Taken.\*  
High alarm was no active and caused tank to over flow. Vacuum truck was onsite to remove standing fluid inside berm area. The berm has a 20-mil liner throughout the entire battery location.

Describe Area Affected and Cleanup Action Taken.\*  
Area inside lined berm was affected. SESI was onsite to assess site and once removal of all fluids. SESI recommends to remove gravel and take to disposal then add new gravel for backfill.

Describe General Conditions Prevailing (Temperature, Precipitation, etc.)\*

I hereby certify that the information given above is true and complete to the best of my knowledge and belief.	<b>OIL CONSERVATION DIVISION</b>		
	Signature: 	Approved by: ENV ENCLINDESR. District Supervisor: 	
Printed Name: <b>STEVE A MAGAN</b>	Approval Date: <b>06/09/11</b>	Expiration Date: <b>-</b>	
Title: <b>PS II</b>	Conditions of Approval: <b>IRP-06-11-2716</b>		
Date: <b>5-31-11</b> Phone: <b>575-631-026</b>	Attached <input type="checkbox"/>		

\* Attach Additional Sheets If Necessary

Ran-11-006 site photos 6-9-11




Well sign




Battery location facing east




Battery location facing southwest




Battery location facing south




Battery location facing south




Battery location facing southwest



Battery location backfilled with gravel



Battery location backfilled with gravel



Battery location backfilled with gravel facing southeast