


NW

POKER LAKE UNIT 347H STRUCTURAL CROSS SECTION

SE





Well began flowing while drilling @ 10,170'; salt water flow. Shut well in, recorded 250 psi on drill pipe, 125 psi on casing.

POKER LAKE UNIT 401H - INJECTION AREA LOCATION MAP

Structure Map - Top Delaware Lower Brushy Canyon

Poker Lake Unit, Eddy Co., New Mexico



OCD CASE NOS.
15219 AND 15231

BOPCO
Exhibit # 11