

14-Mar-08

Well Inspection History

API Number: **30-015-02589-00-00** Well Name & No.: **DAUGHERTY STATE**
 Operator: **SANDLOTT ENERGY (JACKIE BREWER D** District: **ARTESIA** County Name: **EDDY**
 Field: **DAUGHERTY STATE** Legal: **S: 4 T: 18S R: 28E**
 Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
7/20/2007	Routine/Periodic	Normal Routine Activity	IMLB07201506		211		
	Contamination at well head area. Well is pumping. Unit came on during inspection. Some contamination at tank battery situated North of well site.						
10/20/2005	Compliance Verification	Normal Routine Activity	iCLB05293417		212		
	Took samples along north side of tanks. Sample 1: 32.78334N 104.18598W 3-6 inches Sample 2: 32.78328N 104.18597W 3-6 inches Sample 3: 32.78339N 104.18586W 3-6 inches						
	Tanks: 1: 32.78329N 104.18590W 2: 32.78330N 104.18595W 3: 32.78339N 104.17595W						
8/30/2005	Routine/Periodic	Normal Routine Activity	IMLB05242353		211		
	Well is pumping. Stuffing box leaking. Heavy contamination at well head area extending out onto location. Some contamination at tank battery for this well.						
8/19/2004	Routine/Periodic	Normal Routine Activity	iGEG0423247		209		
	Wellhead leaking. Well is pumping.						
2/4/2004	Compliance Verification	Normal Routine Activity	iGEG0403546		209		
	Leak stopped. Needs work around well head.						
1/26/2004	Routine/Periodic	Normal Routine Activity	iGEG0402639		209	Y	
	Stuffing box leak.						
11/22/2002	Routine/Periodic	Normal Routine Activity	IMLB02326477		211		
	Equipment and Location needs minor attention. PJ---B/T						
1/31/2001	Routine/Periodic	Normal Routine Activity	iPCH0103136		210		
	Equipment and Location needs minor attention. B/T						
10/19/1999	Routine/Periodic	Status Check	iELG0002836		207		
	A-OK. All Equipment and Location in Good Shape. B/T						

Total Inspections Performed: 9

Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 4