

27-Mar-08

Well Inspection History

API Number: **30-015-22660-00-00** Well Name & No.: **GOURLEY FEDERAL**
 Operator: **KIMLAR OIL COMPANY, BECKY HILL** District: **ARTESIA** County Name: **EDDY**
 Field: **GOURLEY FEDERAL** Legal: **S: 31 T: 22S R: 28E**
 Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
3/18/2008	Compliance Verification	Normal Routine Activity	iSEB08078392		217		
	Witnessed sample event						
3/14/2008	Compliance Verification	Normal Routine Activity	iSEB08074459		217		
	3/14/08 seb: Site visit for purpose to review remediation work performed. Excavation of cellar area including excavation to north and west of pump jack. Photos available.						
1/29/2008	File and Compliance Review	Normal Routine Activity	iSEB08030484		217		
	Met with Larry Hill of Kimlar Oil and Mike Felkins of Roadrunner Environmental for purpose of obtaining samples. Mr Felkins not prepared to obtain samples. Preliminary work completed: KOGO Construction excavated/scraped stained soils. Hauled to Texas. Brought in backfill soils from Texas. Gave Mr Hill direction that he is not supposed to transfer soils from out of state. Explained that site is located on BLM land and possibility of invasive/noxious plants could be introduced. Discussed cellar contamination. Mr Hill stated he plans to make repairs to stop leaking, dig out cellar contamination, and re-route flow line. Roadrunner Enviro to submit work plan for approval. Mr. Hill stated he plans to keep well shut in until work is approved and completed. Sample Event to be rescheduled.						
1/18/2008	Final Restoration	Normal Routine Activity	iGEG0801840		209		
	Spill appears to have been covered. No indication of sampling.						
1/16/2008	Routine/Periodic	Normal Routine Activity	iREH0801639		214		
	On location to witness sampling event. No other personnel present. Historical contamination around PJ bas and wellhead. Cellar full of fluids. Staining throughout location. Photos taken.						
1/11/2008	Routine/Periodic	Normal Routine Activity	iMLB08011471		211		109
	C-141 rec'd 1/9/08 reporting releases of produced fluids that have occurred at this site over an unknown period of time. Remediation work plan due 2/10/08. Well is included in ACO-174.						
12/19/2007	Routine/Periodic	Normal Routine Activity	iREI07353457		213		
	Fluids in cellar, but looks like water. PJ operating.						
11/16/2007	Routine/Periodic	Normal Routine Activity	iREI07320480		213		
	Still fluids in cellar. Looks like soil has been scrapped off on north side of pump jack.						
6/12/2007	Compliance Verification	Normal Routine Activity	iGEG0716341		209		Y
	Well has highly contaminated soils around pumpjack. Belts are off motor. Cellar is full of fluid which has an oil emulsion on top. Violation of Rule 116. Photo #1 thru #4						
2/15/2007	Routine/Periodic	Normal Routine Activity	iMLB07046442		211		
	Well is pumping at time of this inspection. Open cellar has oil and water standing. There is what appears to be a large hydrocarbon type staining surrounding pumping unit and running South from wellhead towards power pole.						
2/5/2007	Routine/Periodic	Normal Routine Activity	iCPO0703651				

Total Inspections Performed: 11

Kimlar Oil Company

**Case 14054
OCD Exhibit No. 4**