

Submit 3 Copies To Appropriate District Office
 District I
 25 N. French Dr., Hobbs, NM 87240
 District II
 1 South First, Artesia, NM 87210
 District III
 200 Rio Brazos Rd., Aztec, NM 87410
 District IV
 40 South Pacheco, Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 2040 South Pacheco
 Santa Fe, NM 87505

WELL API NO. 30-025-03734
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E9335-S
7. Lease Name or Unit Agreement Name: STATE "T"
8. Well No. 1
9. Pool name or Wildcat Townsend Permo Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS
 DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:
 Oil Well Gas Well Other

Name of Operator
 Pronghorn Management Corporation

Address of Operator
 P. O. Box 1772 Hobbs, NM 88241

Well Location
 Unit Letter M : 2970 feet from the South line and 330 feet from the West line
 Section 6 Township 16-S Range 36-E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
 3965' RKB

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK PLUG AND ABANDON
- TEMPORARILY ABANDON CHANGE PLANS
- WELL OR ALTER CASING MULTIPLE COMPLETION
- OTHER:

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ALTERING CASING
- COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
- CASING TEST AND CEMENT JOB
- OTHER:

2. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set CIBP @ ± 10,100', Cap with 35' cement
2. Circulate hole with mud laden fluid.
3. Nipple up to 5 1/2" casing. Stretch, cut and pull ± 7000' csg.
4. Spot cement plug 50' in and out of stub. WOC and tag.
5. Spot 100' cement plug 4680' - 4780'. (Int. csg. shoe) WOC and Tag.
6. Spot 100' cement plug 1939' - 2039'. (Top of salt) WOC and Tag.
7. Spot 10 sx. surface plug.
8. Erect dry hole marker. Clean location.

255X OR 100' WHICHEVER IS GREATER
 F/ 350' to 250' - TAG (13 3/8 SHOE)

BEFORE EXAMINER
 OIL CONSERVATION DIVISION
 OCD EXHIBIT NO. 18
 CASE NO. 12771-A

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF DRUGGING OPERATIONS FOR THE CASE TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE G. A. Baber TITLE Partner DATE 4/7/00

Type or print name G. A. BABER Telephone No 505-393-9176

This space for State use)

APPROVED BY _____ ORIGINAL SIGNATURE TITLE _____ DATE 4/7/00

Conditions of approval, if any:

✍