




- Down-to-North Fault
- Down-to-South Fault
- Active Dakota Producing Well
- BHL
- Surface

Examiner _____
 Case No. 12098
 EXHIBIT NO. 3

Cross Timbers Oil Company	
UTE DOME FIELD San Juan County, New Mexico	
STRUCTURE: Top of Dakota	
November, 1998	GKB/MSV

U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION

EXHIBIT **3**

Q. OF NO. _____