


R 14 W



T
3
1
N



- Down-to-North Fault
- Down-to-South Fault

OIL CONSERVATION DIVISION

CASE NUMBER _____

EXHIBIT 4

Cross Timbers Oil Company	
UTE DOME FIELD San Juan County, New Mexico	
STRUCTURE: TOP OF DAKOTA UTE INDIANS A-32	
November, 2000	MSV