

N-11-12N-32E: From above to well (Silverstein #1 Umer) which was subject of forced plugging Case #279, heard 8/7/51. No order written. Correspondence in file indicates well not properly plugged and Form C-103 reporting same not approved by OCC. Inspection found 4 3/4" pipe filled with cement at location; no identification. A water well with windmill and stock tank is on location, the two bore holes being approximately 25' apart. Drilling contractor (Mr. Crews) in Tucumcari verified that he did plugging and also drilled twin well for water supply. File will be closed. cu - 5/26/75