C 111

DISTRICT

P.O. Box 1980, Hobbs, NM 88240

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

DISTRICTI P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.

Santa Fe, NM 87505 WELL API NO. 30-059-20063

5. Indicate Type of Lease

STATE FEE X 6. State Oil & Gas Lease No.

ALTERING CASING

PLUG AND ABANDONMENT

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name		
MEIT [	WELL [	отнех СО2		BDCDGU-	1934	
2. Name of Operator				8. Well No.		
Amoco Production Company				091		
3. Address of Operator				9. Pool name or Wildcat		
PO Box 606, Clayton, NM 88415				Tubb		
4. Well Location				<u> </u>		_
Unit Letter K	: 1650 Feet From The _	South	Line and1994	Feet From The	West L	ine
Section 9	Township 191	Kange		NMPM Union	County	,
	10. Elevat	tion (Show whether DF, 4870' GR	RKB, RT, GR, etc.)			
I	Check Appropriate Box	x to Indicate Nat	ure of Notice, Re	eport, or Other Da	ta	4.1

PULL OR ALTER CASING CASING TEST AND CEMENT JOB Install Casing Liner OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLUG AND ABANDON

CHANGE PLANS

RUN & SET 1.625 BLK PLG IN PROFILE NIP

NOTICE OF INTENTION TO:

BLEED DOWN TBG NIPPLE UP BOP REL ON/OFF TOOL SWAB & BLOW WELL DRY

LAY DOWN FG TBG & ON/OFF TOOL OS RUN POLYBORE GAUGE RING TO PKR

CHANGE RAMS IN BOP RUN ON/OFF TOOLOS W/SW LATCH ON TO PKR W/WS

RIG UP RIG ASSISTED SNUBBING UNIT

REL PKR

MIRUSU

SNUB TBG, PKR, TAILPIPE OUT OF WELL

SHUT IN WELL W/BLIND RAMS RIG DOWN SNUBBING UNIT

INSTALL SS WELLHEAD BONNET ON TOP OF BOP

SNUB AND POLYBORE PROCEDURE NSTALL PRODUCTION EQUIPMENT

REMEDIAL WORK

COMMENCE DRILLING OPNS.

RWTP UP 5.5 STEEL CSG PRODUCE FOR 12 TO 20 DAYS MOVE IN RIG UP SERVICE UNIT

SHUT IN BOP-BLINDS

RUN BAKER WIRE LINE ,SET INFLATTABLE BP

SUBSEQUENT REPORT OF:

SET IBP ABOVE TOP PERF BLEED CSG TO 0 PSI **RUN 9-31/8" DRILL COLLARS** 

RIG UP RRU

RUN POLYLINER TO INFLATTABLE BP

RUN 23/8" WORK STRING & PULL DRILL COLLARS

FUSE ON WELLHEAD FLANGE

INSTALL SS ADAPTER

RETRIEVE IBP WITH WIRELINE

RWTP **RDMOSU** 

I hereby certify that the information above is true and complete

SIGNATURE

Field Foreman

5/29/97

TYPE OR PRINT NAME

<u>Billy E Prichard</u>

тејенноме ко, 374 – 3053

(This space for State Use)

DISTRICT SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY