Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals, and Natural Resources Department

Form C-103 Revised 1-1-89

District Office

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

- 31	Ո-Ր	159.	-20	በጸጸ

S. Indicate Type of Lease							
STA	ATE		FEE				

6. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A

DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

L. Type of Well

CO<sub>2</sub>

7. Lease Name or Unit Agreement Name

BRAVO DOME CO2 GAS UNIT

Name of Operator 8. Well No.

AMOCO PRODUCTION COMPANY

Address of Operator P.O. Box 303, AMISTAD, NEW MEXICO 9. Pool name or Wildcat

BRAVO DOME CO2 GAS UNIT

1935-111G

Well Location Unit Letter

**EMPORARILY ABANDON** 

ULL OR ALTER CASING

THER

G

Feet From The Township

Line and

NMPM

Feet From The

SUBSEQUENT REPORT OF:

Line County

10. Elevation (Show whether DF, RKB, RT, GR. etc.)

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

'ERFORM REMEDIAL WORK PLUG AND ABANDON

CHANGE PLANS

REMEDIAL WORK

COMMENCE DRILLING OPNS

ALTERING CASING PLUG AND ABANDONMENT

CASING TEST AND CEMENT JOB

**OTHER** 

2. Describe Proposed or Completed Operations SEE RULE 1103

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

MIRUSU, kill well as necessary, NUBOP, release packer, lay down production tubing and packer, run workstring to 2,193 feet, spot 69 sacks of class C cement, pull workstring, WOC, run workstring, tag cement, cement should be above 2,108 feet, pressure test casing to 500 psi, displace casing with corrosion inhibited fluid, pull workstring to 1,616 feet, spot 11 sacks of cement, pull workstring to 30 feet and fill casing with cement, NDBOP, RDMOSU, cut off wellhead, install PXA marker, cut off well anchors and clean location.

nereby certify that the information above is true and complete to the best of my knowledge and belief

GNATURE

Field Foreman

TELEPHONE NO

(505) 374-3010

/PE OR PRINT NAME

his space for State Use) PROVED BY

ONDITIONS OF APPROVAL, IF ANY